

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

MSC TECHNICAL NEWS

No. M7700-17-9202

7700 Series Remarks on Interrupts

In certain cases, caution is required when **writing** to the 7700 Series interrupt control registers.

1. Relevant types

This applies to the following groups, regardless of the memory type, memory capacity, speed, or operating voltage etc.

M37700, M37701, M37702, M37703, M37704, M37705, M37708, M37720,
M37730, M37732

2. The problem

The problem occurs when special programs are executed, that use instructions such as LDM to write all bits to the interrupt control register of interrupts for which the interrupt request is asynchronously generated. Accordingly, there is no problem at all when these interrupt control registers are being accessed by the normal programming method using the CLB and SEB instructions.

2.1 The present condition

If the interrupt control registers for two interrupt sources are at an even address and the following (even address+1) odd address, and a **write instruction W** (refer to 2.3 for details) is being used to write to one of the registers only, if an interrupt request occurs for the other register, the interrupt request bit for the latter is not set to "1".

The case in which the instruction is one that changes the data length using the data length flag (m) is described below. The case in which the instruction is one that changes the data length using the index register length flag (x) is the same.

For example, when the data length flag (m) is "1" (8-bit), and an interrupt control register at an even address is being written to, there is a possibility that the interrupt request bit of the following odd address will be effected, and when an interrupt control register at an odd address is being written to, there is a possibility that the interrupt request bit of the previous even address will be effected.

Also, when the data length flag (m) is "0" (16-bit), and a write is performed from an interrupt control register at an odd address, the write operation is actually performed in two cycles. Therefore, in the same way as for the case when the data length flag (m) is "1", there is a possibility that the interrupt request bit of the previous even address will be effected when an interrupt control register at an odd address is being written to, and when an interrupt control register at an even address is being written to, there is a possibility that the interrupt request bit of the following odd address will be effected.

When the data length flag (m) is "0" (16-bit), and a write instruction is executed from an even address, the write operation is performed in one cycle and neither of the interrupt request bits are effected.

2.2 Relevant registers

The relationship between the registers that produce an effect because of the write operation described above, and the registers that are effected and have their interrupt request bits cleared to "0", is given in the table below.

Note, however, with the $\overline{\text{INT}}_0$ and $\overline{\text{INT}}_1$ interrupt requests, as there is no influence from write operations to the timer B2 and $\overline{\text{INT}}_2$ interrupt control registers, the interrupt request bit is not cleared to "0". Also, watchdog timer interrupt and $\overline{\text{DBC}}$ interrupt, which do not have interrupt control registers, are not effected.

Interrupt control registers that produce an effect because of the write operation.		Interrupt control registers that have their interrupt request bits cleared to "0".		Remarks
Interrupt source	address	Interrupt source	address	
DMA0	6C ₁₆	DMA1	6D ₁₆	Only applies to M37720
DMA1	6D ₁₆	DMA0	6C ₁₆	
DMA2	6E ₁₆	DMA3	6F ₁₆	
DMA3	6F ₁₆	DMA2	6E ₁₆	
A-D conversion	70 ₁₆	UART0 transmission	71 ₁₆	Except M37730
UART0 transmission	71 ₁₆	A-D conversion	70 ₁₆	
UART0 receive	72 ₁₆	UART1 transmission	73 ₁₆	Except M37730
UART1 transmission	73 ₁₆	UART0 receive	72 ₁₆	
UART1 receive	74 ₁₆	Timer A0	75 ₁₆	
Timer A0	75 ₁₆	UART1 receive	74 ₁₆	Except M37730
Timer A1	76 ₁₆	Timer A2	77 ₁₆	
Timer A2	77 ₁₆	Timer A1	76 ₁₆	
Timer A3	78 ₁₆	Timer A4	79 ₁₆	
Timer A4	79 ₁₆	Timer A3	78 ₁₆	
Timer B0	7A ₁₆	Timer B1	7B ₁₆	Except M37730
Timer B1	7B ₁₆	Timer B0	7A ₁₆	
$\overline{\text{INT}}_0$	7D ₁₆	Timer B2	7C ₁₆	Except M37730
$\overline{\text{INT}}_1$	7E ₁₆	$\overline{\text{INT}}_2$	7F ₁₆	Except M37705

2.3 Relevant instructions

Write instructions covered by the "write instruction W" described in 2.1 above are as follows.

LDM, STA, STX, STY

In general the CLB and SEB instructions are used to write to this area, and use of these instructions will not cause any problems.

Also, although they are probably not normally executed in this area, the problem that occurs when the LDM instruction is used also occurs with the following instructions.

BRK, JSR, MVN, MVP, PEA, PEI, PER, PHA, PHB, PHD, PHG, PHP, PHT, PHX, PHY, PSH

3. Countermeasures

When writing to an interrupt control register with the data length flag (m) (or the index register length flag (x)) set to "1" (8-bit), or when word writing from an odd address with the data length flag (m) (or the index register length flag (x)) set to "0" (16-bit), **use the CLB and SEB instructions to set the necessary bits in the interrupt control register.**

Program example (with the data length flag (m) set to "1" (8-bit))

- To disable interrupts (set the interrupt priority level to "0")

CLB.B #07H, XXXX

- To set the interrupt priority level to "3"

CLB.B #07H, XXXX

SEB.B #03H, XXXX

As touched upon in 2.1 above, when the data length flag (m) (or the index register length flag (x)) is "0" (16-bit), and a word writing is executed from an even address, the write operation is performed in one cycle, and neither of the interrupt request bits are effected.