# **RENESAS** Tool News

### RENESAS TOOL NEWS on February 16, 2008: 080216/tn3

### A Note on Using E8a Emulator Software V.1.01 Release 00

## --With Debugging Target Systems Designed with MCUs of the R8C/2G or R8C/2H Group--

Please take note of the following problem in using the emulator software for the E8a on-chip debugging emulator:

• With debugging target systems designed with MCUs of the R8C/2G or R8C/2H group

#### 1. Description

In the specifications of the MCUs concerned, the bit 4 (CM04) of the system clock control register 0 is set to 1 by default after the target MCU has been reset, which enables the MCU's XCIN (P4\_3) and XCOUT (P4\_4) pins to supply the XCIN clock to the system.

In some cases, however, CM04 is cleared to 0 after MCU reset, which forces the XCIN (P4\_3) and XCOUT (P4\_4) pins to function as an I/O port. If this is the case, no target systems synchronized with the XCIN clock would be operated.

#### 2. Conditions

This problem occurs if the following conditions are all satisfied:

- (1) The R8C/Tiny E8a Emulator Debugger included in the product concerned is running.
- (2) The target system is designed with any member of the R8C/2G or R8C/2H group of MCUs.
- (3) Any of the following operations has been performed:
  - Pressing of the CPU Reset button
  - Selection of Reset CPU out of the Debug menu
  - Hardware reset of the user board

#### 3. Workaround

If your target system synchronized with the XCIN clock is debugged using the E8a emulator, keep the CM04 bit set to 1 by describing it in the user program.

### 4. Schedule of Fixing the Problem

We plan to fix this problem in the next release of the product.

#### [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.