

Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138

	P	RODUCT/PRO	CESS C	HAN(SE NOTI	ICE (P	CN)		
PCN #: N1701-01 Date: February 2, 2017 Product Affected: 8V97051NLGI 8V97051NLGI8 8V97051NLGI/W Date Effective: May 2, 2017			■ Proc □ Bac □ Date	MEANS OF DISTINGUISHING CHANGED DEVICES: ■ Product Mark Prefix character on date code line as shown on Attachment 1 □ Back Mark □ Date Code					
Contact:	TSD Clock Team		Attachm	ent:	Yes		No		
E-mail:	clocks@idt.com		Samples	: Samples	are available	now.			
□ Die Technolog □ Wafer Fabrica □ Assembly Pro □ Equipment □ Material □ Testing □ Manufacturing □ Data Sheet ■ Other - Die Ro	ation Process cess g Site evision Change	This notice is to advise of above. There is no change to the The change improves deviate marginality may on rare of environments. Pro-active have been taken. The fail devices even though none fault include: no output seconfiguration in the digit low, the above mentioned. There are no AC or DC of the current version of the current version of the control of the current version of the control of the current version ve	vice robustness occasions cause e measures to i ling power-up e has been obs witching, swit al PLL blocks d design change	s for low to the the device the device implement condition we rived so far ching at an analysis. While the will complete the will complete the the will complete the will comp	emperature ope e to power up the same resolu- vould potential r. Possible fail- incorrect freque probability of oletely elimina- ign change.	eration. On in an undes ation on thi ly be seen ure modes uency, no a this fault b	other simil sirable state is device, wat cold tem related to the color of the color of the ibility of the color of the col	ar devices, a circuit e in low temperature which uses a similar circuit, uperature as for other similar his potential low temperature e registers, and wrong fest in the current design is his fault occurring.	
There is no		ON SUMMARY: nology/process and no per peen validated through bot			n device chara	cterization	result.		
IDT records indi to grant approva it will be assume IDT reserves the	cate that you requi l or request addition ed that this change right to ship eithe	TENT OF RECEIPT: re written notification of t nal information. If IDT do is acceptable. r version manufactured aft eted. The ealier version w	er the process	acknowled	gement within	30 days of	f this notice		
Customer:			☐ App	proval for	shipments	prior to e	effective d	date.	
Name/Date:			E-Mail Addre	ess:					
Title:			Phone # /Fax	#:					
CUSTOMER C	OMMENTS:								
	LEDGMENT OF	RECEIPT:	DATE:						



PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 1 - PCN #: N1701-01

PCN Type: Die Revision Change

Data Sheet Change: No

Detail of Change: The change improves device robustness for low temperature operation. On other similar

devices, a circuit marginality may on rare occasions cause the device to power up in an undesirable state in low temperature environments. Pro-active measures to implement the same resolution on this device, which uses a similar circuit, have been taken. The failing power-up condition would potentially be seen at cold temperature as for other similar devices even though none has been observed so far. Possible failure modes related to this potential low temperature fault include: no output switching, switching at an incorrect frequency, no access to the registers, and wrong configuration in the digital PLL blocks. While the probability of this fault being manifest in the current design is low, the above mentioned design change will completely eliminate the possibility of this fault occurring.

Example of Prefix character change in datecode line

