

RENESAS TECHNICAL UPDATE

1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan
Renesas Electronics Corporation

Product Category	MPU & MCU		Document No.	TN-16C-A223A/E	Rev.	1.00
Title	Errata to R32C/116 Group User's Manual: Hardware		Information Category	Technical Notification		
Applicable Product	R32C/116 Group	Lot No.	Reference Document	R32C/116 Group User's Manual: Hardware Rev. 1.10 (REJ09B0532-0110)		

This document describes corrections to the R32C/116 Group User's Manual: Hardware, Rev. 1.10. The corrections are indicated in red in the list below.

- Page 25 of 520, register symbol "R3R0" in line 3 of 2.1.1 is corrected as follows:
"R3R1"
- Page 41 of 520, register name "Increment/Decrement Counting Select Register" in Table 4.13 is corrected as follows:
"Increment/Decrement Select Register"
- Page 61 of 520, descriptions for the VDEN bit in Figure 6.4 are modified as follows:

Bit Symbol	Bit Name	Function	RW
VDEN	Low Voltage Detector Enable Bit	0: Low voltage detector disabled 1: Low voltage detector enabled	RW

- Page 63 of 520, description of the third paragraph of 6.2.1 is modified as follows:
"When the voltage **rises to or** above Vdet(R) **again**, the VMF bit becomes 1 ($VCC \geq Vdet$) and the LVDF bit becomes 1. **At this point**, an interrupt request **is generated when** the LVDIEN bit is 1."

•Page 69 of 520, Figure 8.1 is corrected as follows:




Figure 8.1 Clock Generation Circuitry

•Page 71 of 520, bit name “XCIN-XCOUT Drive Power Select Bit” in Figure 8.3 is modified as follows:
 “XCIN-XCOUT Drive **Strength** Select Bit”

- Page 71 of 520, the following description is added to Note 8 in Figure 8.3:
 “When rewriting this bit while the watchdog timer is running, set it immediately after writing to the WDT3 register.”
- Page 72 of 520, bit name “XIN-XOUT Drive Power Select Bit” in Figure 8.4 is modified as follows:
 “XIN-XOUT Drive **Strength** Select Bit”
- Page 72 of 520, description of Note 2 in Figure 8.4 is modified as follows:
 “When the BCS bit in the CCR register is 0 (PLL clock selected as base clock source), the PLL frequency synthesizer does not stop oscillating even if the CM10 bit is set to 1.”
- Page 73 of 520, bit symbol “CM02” in Note 3 of Figure 8.5 is corrected as follows:
 “CM20”
- Page 82 of 520, description of the last paragraph of 8.1.4 is modified as follows:
 “The on-chip oscillator clock is stopped after a reset. It starts running when setting the CM31 bit in the CM3 register to 1. It is not necessary to wait for stabilization because the on-chip oscillator instantly starts oscillating.”
- Page 83 of 520, description “(Refer to Figure 8.17 “State Transition (when the sub clock is used)”)” is deleted from 8.2.
- Page 92 of 520, description of 8.7.2 is modified as follows:
 “The base clock stops in wait mode, so clocks generated by the base clock, the CPU clock and peripheral bus clock, stop running as well. Thus the CPU and watchdog timer, operated by these two clocks, also stop. Since the main clock, sub clock, PLL clock, and on-chip oscillator clock continue running, the peripherals using these clocks also continue operating.”
- Page 101 of 520, mathematical symbols in 9.3.1 are corrected as follows:
 - In memory expansion mode

$$0080000h \leq (CB23 \times 2^{18}) \leq (CB12 \times 2^{18}) \leq (CB01 \times 2^{18}) \leq 3DC0000h$$
 - In microprocessor mode

$$0080000h \leq (CB23 \times 2^{18}) \leq (CB12 \times 2^{18}) \leq (CB01 \times 2^{18}) \leq 3FC0000h$$
- Pages 104 and 105 of 520, setting ranges for registers CB01, CB12, and CB23 in Figures 9.7 to 9.9 are corrected as follows:
 CB01: “02h to F8h in memory expansion mode” and “02h to FFh in microprocessor mode”
 CB12: “02h to F8h in memory expansion mode” and “02h to FFh in microprocessor mode”
 CB23: “02h to F8h in memory expansion mode” and “02h to FFh in microprocessor mode”
- Pages 104 and 105 of 520, descriptions of Note 2 in Figures 9.7 to 9.9 are modified as follows:
 CB01: “The setting value should be equal to or greater than that of the CB12 register.”
 CB12: “The setting value should be equal to or greater than that of the CB23 register and should be equal to or less than that of the CB01 register.”
 CB23: “The setting value should be equal to or less than that of the CB12 register.”
- Page 108 of 520, bit names of bits ESUR1 and ESUR0, bits ESUW1 and ESUW0, bits EWR1 and EWR0, and EWW1 and EWW0 in Figure 9.12 are modified as follows:
 ESUR1 and ESUR0: “Address Setup **Cycles Before Read** Setting Bit”
 ESUW1 and ESUW0: “Address Setup **Cycles Before Write** Setting Bit”
 EWR1 and EWR0: “**Read** Pulse Width Setting Bit”
 EWW1 and EWW0: “**Write** Pulse Width Setting Bit”

- Page 124 of 520, description “Bits PRC0 and PRC1 do not automatically become 0. They should be set to 0 by a program.” is deleted from Note 1 of Figure 10.1.
- Page 127 of 520, description of Note 1 in Figure 11.1 is modified as follows:
“The peripheral interrupts are generated by the corresponding peripherals in the MCU.”
- Page 128 of 520, the second paragraph of (5) in 11.2 is modified as follows:
“The stack pointer (SP) used for this interrupt differs depending on the software interrupt numbers. For software interrupt numbers 0 to 127, when an interrupt request is accepted, the U flag is saved and set to 0 to select the interrupt stack pointer (ISP) during the interrupt sequence. The saved data of the U flag is restored upon returning from the interrupt handler. For software interrupt numbers 128 to 255, the stack pointer does not change during the interrupt sequence.”
- Page 130 of 520, description of 11.5 is corrected as follows:
“Each interrupt vector has a 4-byte memory space, in which the start address of the associated interrupt handler is stored. When an interrupt request is accepted, a jump to the address set in the interrupt vector takes place. Figure 11.2 shows an interrupt vector.”
- Page 131 of 520, description in the Remarks for the BRK instruction in Table 11.1 is corrected as follows:
“If address FFFFFFFE7h is FFh, a jump to the interrupt vector of software interrupt number 0 in the relocatable vector table takes place”
- Page 138 of 520, description for the IR bit below Figure 11.4 is corrected as follows:
“The IR bit becomes 1 (interrupt requested) when an interrupt request is generated; this bit setting is retained until the interrupt request is accepted. When the request is accepted and a jump to the corresponding interrupt vector takes place, the IR bit becomes 0 (no interrupt requested).
The IR bit can be set to 0 by a program. This bit should not be set to 1.”
- Page 142 of 520, description of Note 1 in Table 11.7 is corrected as follows:
“These are the values when the interrupt vectors are aligned to the addresses in multiples of 4 in the internal ROM. However, the condition does not apply to the fast interrupt.”
- Page 149 of 520, register symbol “IIOiE” in line 16 of 11.13 is corrected as follows:
“IIOiE”
- Page 153 of 520, description in lines 4 to 6 of 12. Watchdog Timer is corrected as follows:
“Select either an interrupt request or a reset with the CM06 bit in the CM0 register for when the watchdog timer underflows. Once the CM06 bit is set to 1 (reset), it cannot be changed to 0 (watchdog timer interrupt) by a program. It can be set to 0 only by a reset.”
- Page 156 of 520, expression “a value more than 00000001h” in the Specification of DMA transfer start-up in Table 13.1 is corrected as follows:
“a value other than 00000000h”
- Page 164 of 520, description of the first paragraph in 13.1 is corrected as follows:
“The transfer cycle is composed of bus cycles to read data from (source read) or to write data to (destination write) memory or an SFR.”
- Page 165 of 520, external bus address “00060000h” in Table 13.5 is corrected as follows:
“00080000h”
- Page 170 of 520, source address “FFFFFFFh” in Note 1 of Table 14.1 is corrected as follows:
“FFFFFFFh”

- Page 170 of 520, bit symbol "IIRLT" in the fifth bullet point of 14.1 is corrected as follows:
"IRLT"
- Pages 172 and 173 of 520, expression "DMA II transfer complete interrupt vector address" in lines 3 to 4 and the seventh bullet point of 14.1.2 and Figure 14.2 is corrected as follows:
"jump address for the DMA II transfer complete interrupt handler"
- Pages 172 and 175 of 520, expression "interrupt vector" in Figure 14.2 and 14.1.4 is corrected as follows:
"interrupt vector space"
- Page 173 of 520, expression "jump address" in the seventh bullet point of 14.1.2 is corrected as follows:
"start address"
- Page 174 of 520, bit names of the OPER bit and bits CNT0 to CNT2 in Figure 14.3 are modified as follows:
OPER: "Calculation Result Transfer Select Bit"
CNT0 to CNT2: "Number of Transfers Setting Bit"
- Page 184 of 520, description of the third bullet point of 16.1 is corrected as follows:
"One-shot timer mode: The timer outputs pulses after a trigger input until the counter reaches 0000h"
- Page 187 of 520, "Counting" is deleted from bit names of bits TA0UD to TA4UD "Timer A0/1/2/3/4 Increment/Decrement Counting Select Bit" and the register name "Increment/Decrement Counting Select Register" in Figure 16.7.
- Page 195 of 520, bit name of the MR2 bit in Figure 16.12 is modified as follows:
"Increment/Decrement Switching Source Select Bit"
- Page 195 of 520, bit symbols "TAiTGH and TAI^TGL" in Note 5 of Figure 16.12 are corrected as follows:
"TAjTGH and TAJ^TGL"
- Page 196 of 520, pin name "INT2" in Figures 16.13 and 16.14 is corrected as follows:
"INT2"
- Page 214 of 520, description of the first bullet point of 16.3.3.2 is corrected as follows:
"While the TBjS bit in the TABSR or TBSR register is 1 (start counter), after the MR3 bit becomes 1 (overflow) and at least one count source cycle has elapsed, a write operation to the TBjMR register sets the MR3 bit to 0 (no overflow)."
- Page 214 of 520, expression "TBj interrupt handler" in the eighth bullet point of 16.3.3.2 is changed as follows:
"timer Bj interrupt handler"
- Page 218 of 520, description of Note 1 in Figure 17.3 is modified as follows:
"Set this register after setting the PRC1 bit in the PRCR register to 1 (write enabled). Also, rewrite this register while timers A1, A2, A4, and B2 are stopped."
- Page 225 of 520, description "The sum of setting values for registers TAI and TAI1 should be identical to the setting value of the TB2 register in this mode." is deleted from lines 8 to 9 of 17.3.
- Page 229 of 520, bit symbol "INV06" in Note 3 of Figure 17.15 is corrected as follows:
"INV16"
- Page 230 of 520, register symbol "INV1" in Note 2 of Figure 17.17 is corrected as follows:
"INVC1"

- Pages 238 and 239 of 520, descriptions for the CRD bit in Figures 18.5 and 18.6 are modified as follows:

Bit Symbol	Bit Name	Function	RW
CRD	CTS Function Disable Bit	0: CTS function enabled 1: CTS function disabled	RW

- Page 240 of 520, description of function of the UiIRS bit in Figure 18.7 is modified as follows:
 “0: **Transmit buffer** is empty (TI = 1)
 1: Transmission is completed (TXEPT = 1)”
- Page 243 of 520, description of function of the SWC bit in Figure 18.11 is modified as follows:
 “0: No wait-state/wait-state cleared
 1: **Hold the SCLi pin low after the eighth bit is received**”
- Page 244 of 520, expression “UiBRG count source” in the function of bits DL0 to DL2 in Figure 18.12 is corrected as follows:
 “**baud rate generator count source**”
- Page 245 of 520, bit name of the RSTAREQ bit in Figure 18.13 is modified as follows:
 “**Repeated START** Condition Generate Bit”
- Page 245 of 520, description of function of the SWC9 bit in Figure 18.13 is modified as follows:
 “0: No wait-state/wait-state cleared
 1: **Hold the SCLi pin low after the ninth bit is received**”
- Page 253 of 520, “TXEPT flag” in Figure 18.20 is corrected as follows:
 “**TXEPT bit**”
- Page 253 of 520, bit symbol “UiRS” in the fourth dash of Figure 18.20 is corrected as follows:
 “**UiIRS**”
- Pages 261 and 262 of 520, descriptions of function of the UiIRS bit in Figures 18.25 and 18.26 are corrected as follows:
 0: “**(an interrupt request is generated when the transmit buffer is empty)**”
 1: “**(an interrupt request is generated when transmission is completed)**”
- Page 297 of 520, description of 19.1.5 is modified as follows:
 “In repeat sweep mode 1, the analog voltage applied to eight selected pins including **one to four** prioritized pins is repeatedly converted into a digital code. Table 19.6 lists specifications of repeat sweep mode 1.”
- Page 297 of 520, description in the specification of the function in Table 19.6 is modified as follows:
 “**The analog voltage applied to eight selected pins including one to four prioritized pins is repeatedly converted into a digital code. The prioritized pins are selected by setting bits SCAN1 and SCAN0 in the AD0CON1 register and bits APS1 and APS0 in the AD0CON2 register**”
- Page 305 of 520, “AD0i register” in the ninth bullet point of 19.3.2 is modified as follows:
 “**AD00 register**”

- Page 308 of 520, Figure 21.1 is corrected as follows:




Figure 21.1 CRC Calculator Block Diagram

- Page 321 of 520, descriptions for bits UD0 and UD1 in Figure 23.6 are modified as follows:

Bit Symbol	Bit Name	Function	RW
UD0	Increment/Decrement Control Bit	b6 b5 0 0 : Increment mode	RW
UD1		0 1 : Increment/decrement mode 1 0 : Two-phase pulse signal processing mode ⁽⁶⁾ 1 1 : Do not use this combination	RW

- Page 324 of 520, Note 3 “The GOC bit becomes 0 after gating is cleared.” is deleted from Figure 23.9.
- Page 330 of 520, description in the second bullet point of the reset conditions in Table 23.2 is modified as follows:
“An input of low signal into the external interrupt pin (**INT0** or **INT1**) as follows:”
- Page 331 of 520, description of the first bullet point of the selectable functions in Table 23.2 is corrected as follows:
“The base timer starts counting when the BTS or BTIS bit is set to 1. **When the base timer reaches FFFFh, it starts decrementing.** When the RST1 bit in the GiBCR1 register is 1 (**the base timer is reset by matching with the GiPO0 register**), the timer counter starts **decrementing two counts after the base timer value matches the GiPO0 register setting.** When the timer counter **reaches 0000h**, it starts **incrementing** again (refer to Figure 23.20).”
- Pages 342, 344, and 347 of 520, expression “Input to the IIOi_j pin” in Figures 23.25 to 23.27 is corrected as follows:
“**IIOi_j** pin”
- Pages 349 and 351 of 520, expression “Input to the OUTC2_j pin” in Figures 23.28 and 23.30 is corrected as follows:
“**OUTC2_j** pin”

•Page 351 of 520, description “Bits RST2 to RST0 in the G2BCR1 register are set to 000b (base timer is not reset)” in the second dash is deleted from Case 1 in Figure 23.30.

•Page 363 of 520, Figure 24.1 is corrected as follows:




Figure 24.1 Multi-master I²C-bus Interface Block Diagram

•Page 378 of 520, description of the second bullet point of the case that the IRF bit becomes 1 in 24.1.8.5 is modified as follows:

“When data is written to the I2CCCR register (the RIE bit is 1, internal WAIT flag is 1)”

•Page 381 of 520, bit symbol “STR” in line 8 of 24.2 is corrected as follows:

“TRS”

- Page 393 of 520, description of the first and second paragraphs in 25. I/O Pins is corrected as follows (refer to TN-16C-A200A/E):

“Each pin of the MCU functions as a programmable I/O port, an I/O pin for **integrated peripherals**, or a bus control pin. These functions can be switched by the function select registers or the processor mode registers. This chapter particularly addresses the function select registers. For the use as a bus control pin, refer to 7. “Processor Mode” and 9. “Bus”.

The pull-up resistors are enabled for every group of four pins. However, a pull-up resistor is separated from other **peripherals** even if it is enabled, when a pin functions as an output pin.” (“or an analog I/O pin” is deleted)

- Page 393 of 520, Figure 25.1 is corrected as follows (refer to TN-16C-A200A/E):




Figure 25.1 Typical I/O Pin Block Diagram (i = 0 to 15; j = 0 to 7)

- Page 393 of 520, description in the last paragraph of 25. I/O Pins is corrected as follows:
“The input-only port P8_5 shares a pin with **NMI** and has no function select register or bit 5 in the PD8 register. Port P14_1 (or P9_1 in the 100-pin package) also functions as an input-only port. **The function select register and bit 1 in the PD14 register are reserved.** Port P9 is protected from unexpected write accesses by the PRC2 bit in the PRCR register (refer to 10. “Protection”).”
- Page 394 of 520, pin symbols “WR/WR0”, “BC1/WR1”, “BC2/WR2”, and “BC3/WR3” in line 4 of 25.1 are corrected as follows:
“**WR/WR0**”, “**BC1/WR1**”, “**BC2/WR2**”, “**BC3/WR3**”
- Pages 397, 408, and 412 of 520, expressions “IIO0 output” and “IIO1 output” in Figures 25.4, 25.15, and 25.19 are changed as follows:
“**IIO0_i output**” and “**IIO1_i output**”
- Page 399 of 520, “PD3_i register” in line 3 of the paragraph below Figure 25.6 is corrected as follows:
“**PD3_i bit**”

- Page 438 of 520, setting ranges for registers CB01, CB12, and CB23 in Table 26.8 are corrected as follows:
 CB01: “02h to F8h”
 CB12: “02h to F8h”
 CB23: “02h to F8h”
- Page 464 of 520, “Programming and erasure endurance of flash memory” in Table 27.8 is changed as follows:
 “Program/erase cycles”
- Page 464 of 520, unit “times” for “Programming and erasure endurance of flash memory” in Table 27.8 is corrected as follows:
 “Cycles”
- Pages 469 and 482 of 520, the following pins are added to the hysteresis for V_{T+} - V_{T-} in Tables 27.16 and 27.42:
 “MSCL” and “MSDA”
- Pages 470 and 483 of 520, expression “Driver power” in Tables 27.17 and 27.43 is modified as follows:
 “Drive strength”
- Page 500 of 520, “counting” is deleted from the UDF register name “Increment/decrement counting select register” in Table 28.1.
- Page 508 of 520, description of the first bullet point of 28.7.3.2 is corrected as follows:
 “While the TBjS bit in the TABSR or TBSR register is 1 (start counter), after the MR3 bit becomes 1 (overflow) and at least one count source cycle has elapsed, a write operation to the TBjMR register sets the MR3 bit to 0 (no overflow).”
- Page 508 of 520, expression “TBj interrupt handler” in the eighth bullet point of 28.7.3.2 is changed as follows:
 “timer Bj interrupt handler”
- Page 513 of 520, “AD0i register” in the ninth bullet point of 28.10.2 is modified as follows:
 “AD00 register”