

# RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan  
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-SH7-A920A/E	Rev.	1.00
Title	Notes about SSCG		Information Category	Technical Notification		
Applicable Product	See following	Lot No.	Reference Document	See following		
		All				

In the products listed in bellow, a bug about SSCG function is found. There is a possibility that SSCG function can not modulate clock frequency properly.

The details is shown in below.

## Applicable products and relevant documents

Applicable products		Relevant documents	Rev.	Document number
series	Group			
SH7260	SH7268, SH7269	SH7268 Group, SH7269 Group User's Manual: Hardware	Rev 3.00	R01UH0048EJ0300

### [1] Condition


When SSCG is used and fulfill more than one of following conditions.

- The power is supplied in the power on sequence as following order
  - 1) Supply 3.3 volt power and MD\_CLK0 pin is changed to high level (SSCG ON)
  - 2) Supply 1.2 volt power

Detail condition is described in "[4] Detail Condition".

### [2] Phenomenon

There is a possibility that clock modulation function does not work and the frequency is fixed to the lower limit frequency.



[3] Workaround

Please apply the following software workarounds or hardware workarounds.


● Software workarounds

After power on, be sure to execute transition to Deep standby mode and cancelling, then execute user program.

Details are described in the “[5] Software workarounds details”.

● Hardware workarounds


- Please make more than one microsecond between Vcc power on and change timing of MD\_CLK0 pin to high level. (below figure)




From Electrical Characteristics (DC) in  
 - SH7268 Group, SH7269 Group  
 User's Manual: Hardware  
 Vcc (Min.) = 1.15V  
 VT- = 0.5V

- PVcc power on timing should be at the same time as MD\_CLK0 pin or faster than MD\_CLK0 pin. (below figure)


if PVcc power on timing is later than change timing of MD\_CLK0 pin to high level, it becomes absolute maximum rating violation.




[4] Detail Condition




1. In case of order of PVcc, Vcc, MD\_CLK0




2. In case of order of PVcc = Vcc, MD\_CLK0



3. In case of order of Vcc, PVcc, MD\_CLK0




4. In case of order of Vcc, PVcc = MD\_CLK0



From Electrical Characteristics (DC) in  
 - SH7268 Group, SH7269 Group  
 User's Manual: Hardware  
 Vcc (Min.) = 1.15V  
 VT- = 0.5V

[5] Software workarounds details

According to flowchart below, after power on, be sure to execute transition to Deep standby mode and cancelling, then execute user program.



\*1: Please execute depending on system

Only when selecting EXTAL as RTC operation clock, the frequency of the operation clock for performing the one-second counting operation can be set by Frequency register H / L (RFRH / L).

In this case, by setting the value of RFRH / L register according to the following formula, RTC alarm interrupt can be generated in less than 1s.

$$RFRH/L.RFC[18:0] = \text{Alarm interrupt time} \div (\text{EXTAL period} \times 64)$$

(in case of RFRH/L.SEL64 = 1)

e.g.) When EXTAL frequency is 13.33MHz, RFC[18:0]=209

End of document