Microcontroller Technical Information

	Document No.	ZBG	-CD-10-0007	1/2	
QB-78K0RIX3 (Old Name: QB-78K0RKX3L)	Date issued	Janu	ary 25, 2010		
In-Circuit Emulator for	Issued by	Development Tool Solution Group			
78K0R/KC3-L, KD3-L, KE3-L, IB3, IC3, ID3, IE3		Multipurpose Microcomputer Systems			
		Microcomputer Operations Unit			
Usage Restrictions		NEC Electronics Corporation			
Related documents	Notification		Usage restriction		
QB-78K0RIX3 User's Manual: U19228EJ1V0UM00	classification		Upgrade		
QB-78K0RIX3 (Old Name: QB-78K0RKX3L)			Document modification		
In-Circuit Emulator for 78K0R/KC3-L, KD3-L, KE3-L, IB3, IC3, ID3, IE3 Upgrade: ZBG-CD-10-0008			Other notification		

1. Affected product

Product	Outline	Control Code ^{Note}
QB-78K0RIX3	In-circuit emulator for 78K0R/KC3-L, 78K0R/KD3-L,	A, B, C, D
(Old name:	78K0R/KE3-L, 78K0R/IB3, 78K0R/IC3, 78K0R/ID3, 78K0R/IE3	
QB-78K0RKX3L)		

Note The control code is the second digit from the left in the 10-digit serial number. To see if the product has been upgraded, click the ID78K0R-QB **Help** menu, select **About**, and then check the control code. *X* in **IECUBE** **** *X* **F/W: V***.** is the control code.

2. New restriction

Restriction No. 9 has been added. See the attachment for details.

3. Workarounds

See the attachment for details.

4. Modification schedule

Products in which No. 9 is corrected are scheduled for release as follows: Upgrade for already shipped products: Available from January 25, 2010 Date when the upgrade file is posted on the Development Tools Download webpage: January 25, 2010 Newly shipped products (control code: E): Shipments as of January 29, 2010

* Note that this schedule is subject to change without notice. For the detailed release schedule of modified products, contact an NEC Electronics sales representative.

5. List of restrictions

See the attachment.

ZBG-CD-10-0007	2/2
----------------	-----

6. Document revision history

QB-78K0RIX3 (Old Name: QB-78K0RKX3L) In-Circuit Emulator for 78K0R/KC3-L, KD3-L, KE3-L, IB3,

IC3, ID3, IE3 - Usage Restrictions

Document Number Issued on		Description				
ZBG-CD-08-0041	September 18, 2008	1st edition.				
		Addition of restrictions No. 6 to No. 8				
ZBG-CD-10-0007	January 25, 2010	Addition of restriction No. 9				

Operating Precautions for QB-78K0RIX3

This document describes the restrictions applicable to this emulator. Note that some restrictions have been corrected in later control codes.

See the following documents for the restrictions related to the target device:


- User's manual of target device
- Restrictions notification document for target device

Also see the user's manual for cautions on using the emulator.

1. Product Version

The product versions of NEC Electronics in-circuit emulators are indicated by a control code. The control code is the second digit from the left in the 10-digit serial number. To see if the product has been upgraded, click the ID78K0R-QB **Help** menu, select **About**, and then check the control code. In Figure 2, **X** in **IECUBE** **** **X F/W**: **V***.** is the control code.

Figure 1. Checking the Control Code (Label on QB-78K0RIX3)





:	NEC Integrated Debugger ID78K0F In this case, the control code is Version V3.50 [19 May 2008] 78K0R IECUBE Monitor V1.01
	Flash Firmware V1.00 Control Board 0003 01.00 00.30 I/O Board 0102 02.00
	Copyright (C) NEC Electronics Corporation 1993,2008 All rights reserved by NEC Electronics Corporation

ZBG-CD-10-0007 Attachment - 2/6

2. Restrictions

2.1 List of restrictions

No.	Restrictions	Control Code						
		А	В	С	D			
1	Self-programming	×	×	0	0			
2	Interrupt function for key-return (applicable when the target device	×	0	0	0			
	is 78K0R/Kx3-L)							
3	P73/TXD0/TO10 pin (only applicable to 38-pin MC packages)	×	0	0	0			
4	Comparator interrupt function	×	×	0	0			
5	Count clock for timer array unit	×	×	×	0			
6	Restriction on trace data when an interrupt occurs (1)	×	×	×	0			
7	Program execution on RAM	×	×	×	0			
8	A break during division operation	×	×	×	0			
9	Restriction on trace data when an interrupt occurs (2)	×	×	×	×			

-: Not relevant, ×: Applicable, O: Corrected

2.2 Restriction details

No. 1 Self-programming

Description:

Self-programming is not supported.

Workaround:

There is no workaround.

Correction:

This issue has been corrected in QB-78K0RIX3 with control code C.

No. 2 Interrupt function for key-return (applicable when the target device is 78K0R/Kx3-L)

Description:

The interrupt function for key-return does not operate.

Workaround:

There is no workaround.

Correction:

This issue has been corrected in QB-78K0RIX3 with control code B.

No. 3 P73/TXD0/TO10 pin (only applicable to 38-pin MC packages)

Description:

The P73/TXD0/TO10 pin can be used for reading and writing to SFRs, but its port function and alternate function do not operate.

Workaround:

There is no workaround.

Correction:

This issue has been corrected in QB-78K0RIX3 with control code B.

ZBG-CD-10-0007 Attachment - 3/6

No. 4 Comparator interrupt function

Description:

When a comparator interrupt function is used, interrupt requests are issued continuously while an overvoltage is being detected.

In normal operation, an interrupt request is issued only once upon detection of overvoltage.

Workaround:

There is no workaround.

Correction:

This issue has been corrected in QB-78K0RIX3 with control code C.

No. 5 Count clock for timer array unit

Description:

A subsystem clock whose frequency is divided by 4 cannot be used as a count clock for a timer array unit.

Workaround:

There is no workaround.

Correction:

This issue has been corrected in QB-78K0RIX3 with control code D.

No. 6 Restriction on trace data when an interrupt occurs (1)

Description:

If a read access or write access is performed immediately before occurrence of an interrupt, this access might not be reflected to the trace result.

Workaround:


There is no workaround.

Correction:

This issue has been corrected in QB-78K0RIX3 with control code D.

An example of trace data before and after the correction of this restriction is shown below.

ZBG-CD-10-0007 Attachment - 4/6



No. 7 Program execution on RAM

Description:

When a branch instruction is executed on RAM and if the branch destination is an odd address located in

RAM, a fail-safe break due to a word misalign access occurs.

Workaround:

Clear the check box for Word Miss-align Access in the Fail-Safe Break dialog box in the ID78K0R-QB.

A break source can be checked in the status bar in the ID78K0R-QB, as shown below.

107	8KO-QB							
<u>Eile E</u> o	dit <u>V</u> iew <u>O</u> pti	on <u>R</u> un Eve <u>r</u>	<u>it B</u> rowse <u>J</u> ump	<u>W</u> indow <u>H</u> elp				
П	• • • _N •	▶ ▶ ▲			a	≥ ≪ ⊠ ! ▼ ₹ 00		
📓 As	semble							
Sea	arch <<	>>> _ \	Watch Quick	Refresh	Close			A break source is displayed
* >	0FFFF 10000		FF	?				on the status bar.
* *	10001		FF FF	2				
*	10002		FF	?				
* *	10003		FF FF	2				
*	10005		FF	?				
*	10006		FF FF	2				
*	10008		FF	?				
*	10009 1000A		FF FF	2				Wand Mine allow Assess
*	1000B		FF	ż				Word Miss-align Access
*	1000C 1000D		FF	2				
*	1000E		FF FF FF	?				1
*	1000F 10010		FF FF	?				
*	10011		FF	?				
*	10012		FF FF	?				
*	10014		FF	?		-		
*	10015		FF	?				
*	10017		FF FF FF FF	?		A ¥		
	1							
#-			OFFFF	POW OFF	5us 000ns	Word Miss-align Access	1.	

Correction:

This issue has been corrected in QB-78K0RIX3 with control code D.

No. 8 A break during division operation

Description:

If a break occurs in a program in the 16th clock cycle after a division operation is started (DIVST = 1), the operation result might be incorrect.

Workaround:

Do not set breaks for the division operation.

Correction:

This issue has been corrected in QB-78K0RIX3 with control code D.

No. 9 Restriction on trace data when an interrupt occurs (2)

Description:

If interrupt servicing is executed under a specific condition, the trace result might be incorrect.

Although the correct trace result is not displayed, the instructions are executed correctly. The following describes the detailed condition and operations:

Condition:

Execution jumps to an interrupt vector immediately after executing one of the following instructions:

- (1) MOVW SP, #word
- $(2)\,\,\text{MOVW}$ SP, AX
- (3) ADDW SP, #byte
- (4) SUBW SP, #byte

If the instruction fetches data from the ROM, the displayed trace result is incorrect if any instruction from (1) to (4) is executed.

If the instruction fetches data from the RAM, the displayed trace result is incorrect if instruction (3) or (4) is executed.

ZBG-CD-10-0007 Attachment - 6/6

Operation:

If execution jumps to an interrupt vector immediately after executing one of the above instructions, the instruction that follows the above instructions is not supposed to be executed or displayed in the trace result. However, due to this problem, the following items are displayed in the trace result:

- The instruction that follows the above instructions
- The incorrect vector address

Workaround:


There is no workaround.

Correction:

This issue will be corrected in the next revision.

An example of trace data before and after correcting this restriction is shown below.

Before correction:



After correction:

_ A	000162	0:00:00.000	046	016	13E82	1004	M1				ADDW	SP,#4H
_ A	000163	0:00:00.000	046	516				FFEA8	9601	W		
_ A	000164	0:00:00.000	046	766	00034	В1	VECT	FFEA6	3E84	W		
_ A	000165	0:00:00.000	047	766	040B1	C1	M1				PUSH	AX
_ A	000166	0:00:00.000	048	016	040B2	C7	M1	FFEA4	1000	W	PUSH	HL
			/									
	The cor	rect vector add	played.									