# **RENESAS** Tool News

#### RENESAS TOOL NEWS on October 19, 2007: 071019/tn1

## A Note on Using the Real-Time OSes for the SuperH MCU Families --With Using the ivset\_tfl Service Call--

Please take note of the following problem in using the real-time OSes for the SuperH MCU families:

• With making the ivset\_tfl service call

#### **1. Products and Versions Concerned**

- (1) All the versions of the real-time OS for the SH-4- and SH-4A-cored MCUs, HI7750/4 V1.00r1 through V.2.02 Release 02
- (2) All the versions of the real-time OS for the SH-4A- and SH4AL-DSPcored MCUs, HI7300/PX V.1.00 Release 00 through V.1.02 Release 00
- (3) All the versions of the real-time OS for the SH4AL-DSP-, SH-3-, and SH3-DSP-cored MCU, HI7700/4 V1.00r1 through V.2.03 Release 00
- (4) All the versions of the real-time OS for the SH2A-DUAL-cored MCUs, HI7200/MP V.1.00 Release 00 and V.1.00 Release 01
- (5) All the versions of the real-time OS for the SH2-DSP-, SH-1-, SH-2-, SH-2A-, and SH2A-FPU-cored MCUs, HI7000/4 V1.00r1 through V.2.02 Release 02

#### 2. Problem

If the program is running through the following steps, the ivset\_tfl service call issued in Step (4) may prevent task event flag specific to the task in Step (1) from being set by the vset\_tfl or ivset\_tfl service call in Step (2).

- (1) A task, here called A, is in WAITING state for task event flag.
- (2) A program makes the vset\_tfl or ivset\_tfl service call to set any bits that task A is waiting for.
- (3) An interrupt (including a timer interrupt) is occurred while the kernel is servicing the call in (2).
- (4) The handler (an interrupt-, cyclic-, alarm-, or overrun handler) invoked by the interrupt in (3) issues the ivset\_tfl service call to task A to set any bits that task A is waiting for.

#### 3. Workaround

Use general event flag instead of task event flag as follows:

- (1) Create an event flag as follows:
  - Attribute of event flag (T\_CFLG.flgatr): TA\_WSGL|TA\_CLR
  - Initial value of bit pattern (T\_CFLG.iflgptn): 0
- (2) Set an event flag using set\_flg or iset\_flg in place of vset\_tfl or ivset\_tfl.
- (3) Clear an event flag using clr\_flg or iclr\_flg in place of vclr\_tfl or ivclr\_tfl.
- (4) Wait for an event flag using wai\_flg, twai\_flg, or pol\_flg in place of vwai\_tfl, vtwai\_tfl, or vpol\_tfl with TWF\_ORW for parameter 'wfmode' (waiting mode).

### 4. Schedule of Fixing the Problem

We plan to fix this problem in the next release of the products.

#### [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 $\ensuremath{\textcircled{\sc c}}$  2010-2016 Renesas Electronics Corporation. All rights reserved.