

[Notes]

R20TS0757EC0100
Rev.1.00
Oct. 01, 2021

e² studio Smart Configurator Plug-in, Smart Configurator for RL78

Outline

When using Smart Configurator for RL78, note the following points.

1. Notes on creating LLVM for Renesas RL78 C/C++ Executable Project
2. Notes on using Port Input buffer function

1. Notes on creating LLVM for Renesas RL78 C/C++ Executable Project

1.1 Applicable Products

e² studio 2021-04 (Smart Configurator for RL78 Plug-in V1.0.1) or later

1.2 Applicable Devices

RL78 family: RL78/G23 group

- RL78/G23 (30-pin, 32-pin, 36-pin, 40-pin, 44-pin, 48-pin, 52-pin, 64-pin, 80-pin, 100-pin, 128-pin product)

1.3 Details

In e² studio, when creating [LLVM for Renesas RL78 C/C++ Executable Project] and selecting [C++] language, [Use Smart Configurator] (refer to Figure 1-1), the Smart Configurator generated code is not guaranteed to build successfully. The reason is that Smart Configurator generated code is not compatible with C++ language.




Figure 1-1 Creating [LLVM for Renesas RL78 C/C++ Executable Project]

1.4 Workaround

Please avoid selecting [Use Smart Configurator] when selecting C++ language (refer to Figure1-2).




Figure 1-2 Example for not use Smart Configurator

1.5 Schedule for Fixing the Problem

This problem will be fixed in the next version. (Scheduled to be released in Jan 2022.)

2. Notes on using Port Input buffer function

2.1 Applicable Products

- e2 studio 2021-04 (Smart Configurator for RL78 Plug-in V1.0.1) or later
- Smart Configurator for RL78 V1.0.1 or later version

2.2 Applicable Devices

RL78 family: RL78/G23 group

- RL78/G23 (30-pin, 32-pin, 36-pin, 40-pin, 44-pin, 48-pin, 52-pin, 64-pin, 80-pin, 100-pin, 128-pin product)

2.3 Details

When using Port component, and configure the following *Pmn*, if “Unused” is selected and “Input buffer” is unselected (refer to figure 2-1), the other alternative input function on this pin cannot work correctly.

- RL78/G23: 30-pin, 32-pin, 36-pin, 40-pin, 44-pin, 48-pin, 52-pin, 64-pin products
 - PORT0 (P00, P02, P03, P04)
 - PORT1 (P10, P11, P12, P13, P14, P15, P17)
 - PORT4 (P42)

- PORT5 (P50, P55)
- PORT7 (P71, P72, P74)
- PORT12 (P120)
- PORT13 (P137)
- RL78/G23: 80-pin, 100-pin, 128-pin products
- PORT0 (P00, P02, P03, P04)
- PORT1 (P10, P11, P12, P13, P14, P15, P17)
- PORT3 (P34)
- PORT4 (P42, P43, P44, P45)
- PORT5 (P50, P52, P53, P54, P55)
- PORT7 (P71, P72, P74)
- PORT8 (P80, P81, P82, P83)
- PORT9 (P96)
- PORT12 (P120)
- PORT13 (P137)
- PORT14 (P142, P143, P144)

Port selection PORT0

Apply to all

Unused In Out Pull-up TTL buffer Input buffer N-ch Output 1

P00

Unused In Out Pull-up Input buffer N-ch Output 1

P01

Unused In Out Pull-up TTL buffer Output 1

P02

Unused In Out Pull-up Input buffer N-ch Output 1

P03

Unused In Out Pull-up TTL buffer Input buffer N-ch Output 1

P04

Unused In Out Pull-up TTL buffer Input buffer N-ch Output 1

Figure 2-1 Pmn “Unused” and “Input buffer” setting

2.4 Workaround

Please set “Input buffer” by the following steps (refer to figure 2-2):

- 1) After open [PORT*n*] page, select “Apply to all” and “Input buffer” in the top group. By this step, all “Input buffer” functions on this page are selected.
- 2) Change each *Pmn* setting to the proper function which user want to use except “Input buffer” setting. “Input buffer” should all be kept as checked state always.




Figure 2-2 Example for “Input buffer” setting steps

2.5 Schedule for Fixing the Problem

This problem will be fixed in the next version. (Scheduled to be released in Jan 2022.)

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Oct.01.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/