

Supplemental Information

This notice describes the differences between the updated version (Version 4, dated December 4, 2006) and its previous version (Version 3, dated April 7, 2006) of the IDT82V2604 data sheet. It helps readers to identify the changes when the data sheet is upgraded.

Revision History

Revision Date	PCN Number (if applicable)	Date Code	Changed Items
December 4, 2006	-	-	11
April 7, 2006	-	-	3-10
December 8, 2003	-	-	1-2

Changed Items

December 4, 2006

Item 11: Changed the unit of the T_{in} and T_{exit} parameters in the 'ConfigDev Command' from '250 ms' to '1 s' (Page 32)

April 7, 2006

Item 10: Changed the identification code from '004B8067' to '104B8067' (Page 79)

Item 9: Changed attributes for LODS (Page 71)

Item 8: Changed GetLinkWorkingPara Command (Encoding: 1EH) description (Page 64)

Item 7: Changed ConfigGSMTimers Command (Encoding: 08H) description (Page 40)

Item 6: Changed FIFO Interrupt Reset Register (06H) description (Page 25)

Item 5: Changed the default value for FIFO Interrupt Status Register (05H) (Page 25)

Item 4: Added HW version bits to FIFO Interrupt Status Register (05H) (Page 25)

Item 3: Deleted "Supports line side clock detection" in the feature list. (Page 9)

December 8, 2003

Item 2: Changed datasheet status from "Advance" to "Final"

Item 1: Changed IMAOS version