

# RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan  
Renesas Electronics Corporation

Product Category	IIBU/ClockMatrix	Document No.		Rev.	1.00
Title	8A3xxxx Firmware Version v4.8.8 - Errata Notice		Information Category	Technical Notification	
Applicable Product	8A3xxxx, ClockMatrix	Lot No.	Reference Document		

## Devices Affected

8A3xxxx devices running firmware version 4.8.8 loaded from internal ROM, or loaded into RAM from an EEPROM or by a host processor. Consult Renesas for information about later firmware versions that may eliminate these issues.

## Issue BRMBXR-3256 Description

A DPLL configured as a GPIO\_Slave will use hitless reference switching when it is triggered by GPIO to switch from Master to Slave. This behavior can cause a phase difference between the output of the master and the slave timing devices.

## Work-Around

There are two options:

1. After a DPLL is triggered to switch from Master mode to Slave mode by a GPIO, use the DPLL\_HS\_TIE\_RESET control bit to reset the hitless switching time interval error and align the DPLL output with its input reference.
2. Change from Master mode to Slave mode using the DPLL\_REF\_MODE control register.

## Issue BRMBXR-3301 Description

PWM receivers configured for an external channel cannot receive all 128 bytes of payload if the carrier frequency is lower than 50kHz.

## Work-Around

Ensure the carrier frequency is  $\geq 50\text{kHz}$ .

## Issue BRMBXR-3302 Description

If the OTP or EEPROM configuration has OUT\_SYNC\_DISABLE bit set to "1" then the output clock might not become active for a random interval of up to 8 seconds after power on reset. This issue does not happen after a warm reset.

## Work-Around

Set the OUT\_SYNC\_DISABLE bit to "0" in OTP and EEPROM configurations.

**Issue BRMBXR-3308 Description**

DPLL\_0 will not switch from disabled mode to write phase mode using the PLL\_MODE bit field unless DPLL\_0 is reset after changing the setting of the PLL\_MODE bit field.

**Work-Around**

There is no work-around for this issue.

**Issue BRMBXR-3403 Description**

The fine phase measurement algorithm may affect the decimator value of the DPLL when the FILTER\_STATUS\_UPDATE\_EN bit is set.

**Work-Around**

There is no work-around for this issue.

**Issue BRMBXR-3416 Description**

When a channel is in Phase Measurement mode and the frequency of the channel FOD is set to zero Hz; if a new reference input is selected, valid phase measurement data will not be available for 10s.

**Work-Around**

There is no work-around for this issue.

**Issue BRMBXR-3427 Description**

For every DPLL except the System DPLL:

If:

- The host makes any of the four configuration changes listed below to a DPLL.
- And, an already qualified reference has been selected for the DPLL.

Then:

- There is a chance that the DPLL feedback divider will not be properly aligned with the DPLL master divider. This situation will cause a constant phase offset between the DPLL input reference and the DPLL output clocks. The constant phase offset can exceed the Input - Output Alignment Variation ( $t_{ALIGN}$ ) datasheet limits.

The following are the applicable DPLL configuration changes:

1. DPLL\_n.DPLL\_MODE (trigger register) is written, after either of the following changes:
  - a. GLOBAL\_SYNC\_EN is changed from 0 to 1.
  - b. Source of the feedback clock for the DPLL is changed.
2. DPLL\_CTRL\_n.DPLL\_FOD\_FREQ register is written.
3. DPLL\_CTRL\_n.DPLL\_MASTER\_DIV register is written.
4. DPLL\_CTRL\_n.DPLL\_DCD\_FILTER\_CNFG is register is written.

This issue will not occur if the DPLL configuration changes are due to configurations loaded from EEPROM or OTP.

**Work-Around**

After the host executes one of the four configuration changes listed above, the host should:

1. Wait at least 10ms.
2. Trigger the input module for the currently selected reference by writing to INPUT\_n.IN\_MODE.

This work-around will cause the DPLL to properly align the feedback divider and the master divider and the DPLL will meet the Input - Output Alignment Variation ( $t_{ALIGN}$ ) datasheet limits.

**Issue BRMBXR-3431 Description**

If two consecutive DPLL restart events occur within 1ms then subsequent reference switching instructions may not be accepted by the DPLL state machine.

**Work-Around**

Ensure consecutive DPLL restart events do not occur within less than 1ms.

**Issue BRMBXR-3523 Description**

Satellite channels do not align properly when they are in phase measurement mode.

**Work-Around**

There is no work-around for this issue.

**Issue BRMBXR-3235 Description**

The outputs of a channel in phase measurement mode are affected when new inputs are selected for phase measurement.

**Work-Around**

There is no work-around for this issue.

**Issue BRMBXR-3553 Description**

When a channel is configured as a "satellite channel", it is controlled by an internal automatic alignment algorithm that maintains alignment between the satellite channel and its source channel. On rare occasions, the automatic alignment algorithm can apply an unintended and small FFO to a satellite channel for up to 35 minutes.

**Work-Around**

There is no work-around for this issue.

**Issue BRMBXR-3555 Description**

When a DISQUAL\_TIMER bit field is set to 1.25ms the reference monitor may generate false alarms.

**Work-Around**

Ensure the DISQUAL\_TIMER bit fields are not set to 1.25ms.

**Issue BRMBXR-3599 Description**

For coarse phase measurement mode, the phase measurement values are provided to the user in both the DPLLx\_FILTER\_STATUS field and the DPLLx\_PHASE\_STATUS field.

**Work-Around**

There is no work-around for this issue.

**Issue BRMBXR-3636 Description**

The DPLL phase pull-in procedure does not pull-in the phase offset when DPLL\_PHASE\_PULL\_IN\_OFFSET is 1ns and the DPLL\_PHASE\_PULL\_IN\_SLOPE\_LIMIT is 1ppb.

**Work-Around**

There is no work-around for this issue.

**Issue BRMBXR-3644 Description**

When `tod_frame_access_en = 1`, if TOD frames are not discarded by the user, then over the course of many hours, TOD frames can accumulate in the receive FIFO.

**Work-Around**

There is no work-around for this issue.

## IMPORTANT NOTICE AND DISCLAIMER

RENESAS ELECTRONICS CORPORATION AND ITS SUBSIDIARIES (“RENESAS”) PROVIDES TECHNICAL SPECIFICATIONS AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES “AS IS” AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, WITHOUT LIMITATION, ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, OR NON-INFRINGEMENT OF THIRD-PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for developers who are designing with Renesas products. You are solely responsible for (1) selecting the appropriate products for your application, (2) designing, validating, and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. Renesas grants you permission to use these resources only to develop an application that uses Renesas products. Other reproduction or use of these resources is strictly prohibited. No license is granted to any other Renesas intellectual property or to any third-party intellectual property. Renesas disclaims responsibility for, and you will fully indemnify Renesas and its representatives against, any claims, damages, costs, losses, or liabilities arising from your use of these resources. Renesas' products are provided only subject to Renesas' Terms and Conditions of Sale or other applicable terms agreed to in writing. No use of any Renesas resources expands or otherwise alters any applicable warranties or warranty disclaimers for these products.

(Disclaimer Rev.1.01 Jan 2024)

### Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,  
Koto-ku, Tokyo 135-0061, Japan  
[www.renesas.com](http://www.renesas.com)

### Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

### Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit [www.renesas.com/contact-us/](http://www.renesas.com/contact-us/).