

Thank you for using the Applilet3 for RL78.

This document describes the restrictions and points for caution. Read this document before using the product.

Contents

Chapter 1. Introduction	3
Chapter 2. Target Devices	4
Chapter 3. Operating Environment.....	10
Chapter 4. Changes	11
4.1 Details of Changes	11
4.1.1 Change of the note on Peripheral I/O Redirection Register(PIOR)	11
Chapter 5. Points for Caution	12
5.1 Cautions List.....	12
5.2 Cautions Details	13
5.2.1 Cautions when using a DTC function.....	13
5.2.2 Cautions of timer array unit input clock sauce	13
Chapter 6. Restrictions	14
6.1 List of Restrictions	14
6.2 Restrictions Details.....	15
6.2.1 Online Help.....	15
6.2.2 Restrictions of the coding rule of MISRA-C	15
6.2.3 Restrictions of High-speed on-chip oscillator frequency select register	15
6.2.4 Restrictions of internal low-speed or internal high-speed oscillator trimming.....	15
6.2.5 Restriction of a serial array unit.....	15
6.2.6 Restrictions of Flash memory CRC operation function (high-speed CRC).....	15
6.2.7 Restrictions of Port mode select register (PMS)	15
6.2.8 Restrictions of the LIN-bus function of UART	15
6.2.9 Restrictions of extension code, wakeup function and multimaster of serial interface IICA or IIC0	15
6.2.10 Restriction of CAN.....	15
6.2.11 Restriction of Safety functions.....	15

Chapter 7. Correction History	16
7.1 List of RENESAS TOOL NEWS	16
7.2 Details of RENESAS TOOL NEWS	18
7.2.1 RENESAS TOOL NEWS Document No.120801/tn8	18
7.2.2 RENESAS TOOL NEWS Document No.121001/tn1	18
7.2.3 RENESAS TOOL NEWS Document No.130201/tn6	19
7.2.4 RENESAS TOOL NEWS Document No.131016/tn3	19
7.2.5 RENESAS TOOL NEWS Document No.131016/tn4	20
7.2.6 RENESAS TOOL NEWS Document No.140416/tn8	20
7.2.7 RENESAS TOOL NEWS Document No.140816/tn6	21
7.2.8 RENESAS TOOL NEWS Document No.141216/tn5	21
7.2.9 RENESAS TOOL NEWS Document No.150716/tn2	22
7.2.10 RENESAS TOOL NEWS Document No.151116/tn2	22
7.2.11 RENESAS TOOL NEWS Document No.160116/tn5	23
7.2.12 RENESAS TOOL NEWS Document No.160216/tn5	23
7.2.13 RENESAS TOOL NEWS Document No.160316/tn1	24
7.2.14 RENESAS TOOL NEWS Document R20TS0038EJ0100	24

Chapter 1. Introduction

Applilet3 for RL78 is a software tool to generate control programs (device driver programs) for peripheral modules (timers, UART, A/D, etc.). It generates device driver codes using user settings through GUI. Initialize code and API (Application Programming Interface) functions are provided.

Chapter 2. Target Devices

Below is a list of devices supported by the Applilet3 for RL78/I1A V2.03.05.02	
PIN	Device name
20pin	R5F1076C
30pin	R5F107AC, R5F107AE
32pin	R5F107BC
38pin	R5F107DE
The Applilet3 is based on the following documents.	
Manual Name	Document Number
RL78/I1A User's Manual: Hardware	R01UH0169JJ0210 Rev.2.10
	R01UH0169EJ0210 Rev.2.10

Below is a list of devices supported by the Applilet3 for RL78/G12 V2.03.04.01	
PIN	Device name
20pin	R5F10266, R5F10267, R5F10268, R5F10269, R5F1026A R5F10366, R5F10367, R5F10368, R5F10369, R5F1036A
24pin	R5F10277, R5F10278, R5F10279, R5F1027A R5F10377, R5F10378, R5F10379, R5F1037A
30pin	R5F102A7, R5F102A8, R5F102A9, R5F102AA R5F103A7, R5F103A8, R5F103A9, R5F103AA
The Applilet3 is based on the following documents.	
Manual Name	Document Number
RL78/G12 User's Manual: Hardware	R01UH0200JJ0200 Rev.2.00
	R01UH0200EJ0200 Rev.2.00

Below is a list of devices supported by the Applilet3 for RL78/G13 V2.03.04.01	
PIN	Device name
20pin	R5F1006A, R5F1006C, R5F1006D, R5F1006E R5F1016A, R5F1016C, R5F1016D, R5F1016E
24pin	R5F1007A, R5F1007C, R5F1007D, R5F1007E R5F1017A, R5F1017C, R5F1017D, R5F1017E
25pin	R5F1008A, R5F1008C, R5F1008D, R5F1008E R5F1018A, R5F1018C, R5F1018D, R5F1018E
30pin	R5F100AA, R5F100AC, R5F100AD, R5F100AE, R5F100AF, R5F100AG R5F101AA, R5F101AC, R5F101AD, R5F101AE, R5F101AF, R5F101AG
32pin	R5F100BA, R5F100BC, R5F100BD, R5F100BE, R5F100BF, R5F100BG R5F101BA, R5F101BC, R5F101BD, R5F101BE, R5F101BF, R5F101BG
36pin	R5F100CA, R5F100CC, R5F100CD, R5F100CE, R5F100CF, R5F100CG R5F101CA, R5F101CC, R5F101CD, R5F101CE, R5F101CF, R5F101CG
40pin	R5F100EA, R5F100EC, R5F100ED, R5F100EE, R5F100EF, R5F100EG, R5F100EH R5F101EA, R5F101EC, R5F101ED, R5F101EE, R5F101EF, R5F101EG, R5F101EH
44pin	R5F100FA, R5F100FC, R5F100FD, R5F100FE, R5F100FF, R5F100FG, R5F100FH R5F100FJ, R5F100FK, R5F100FL R5F101FA, R5F101FC, R5F101FD, R5F101FE, R5F101FF, R5F101FG, R5F101FH R5F101FJ, R5F101FK, R5F101FL
48pin	R5F100GA, R5F100GC, R5F100GD, R5F100GE, R5F100GF, R5F100GG, R5F100GH R5F100GJ, R5F100GK, R5F100GL R5F101GA, R5F101GC, R5F101GD, R5F101GE, R5F101GF, R5F101GG, R5F101GH R5F101GJ, R5F101GK, R5F101GL
52pin	R5F100JC, R5F100JD, R5F100JE, R5F100JF, R5F100JG, R5F100JH R5F100JJ, R5F100JK, R5F100JL R5F101JC, R5F101JD, R5F101JE, R5F101JF, R5F101JG, R5F101JH R5F101JJ, R5F101JK, R5F101JL
64pin	R5F100LC, R5F100LD, R5F100LE, R5F100LF, R5F100LG, R5F100LH R5F100LJ, R5F100LK, R5F100LL R5F101LC, R5F101LD, R5F101LE, R5F101LF, R5F101LG, R5F101LH R5F101LJ, R5F101LK, R5F101LL
80pin	R5F100MF, R5F100MG, R5F100MH, R5F100MJ, R5F100MK, R5F100ML R5F101MF, R5F101MG, R5F101MH, R5F101MJ, R5F101MK, R5F101ML
100pin	R5F100PF, R5F100PG, R5F100PH, R5F100PJ, R5F100PK, R5F100PL R5F101PF, R5F101PG, R5F101PH, R5F101PJ, R5F101PK, R5F101PL
128pin	R5F100SH, R5F100SJ, R5F100SK, R5F100SL R5F101SH, R5F101SJ, R5F101SK, R5F101SL
The Applilet3 is based on the following documents.	
Manual Name	Document Number
RL78/G13 User's Manual: Hardware	R01UH0146JJ0300 Rev.3.00
	R01UH0146EJ0300 Rev.3.00

Below is a list of devices supported by the Applilet3 for RL78/G14 V2.04.05.01	
PIN	Device name
30pin	R5F104AA, R5F104AC, R5F104AD, R5F104AE, R5F104AF, R5F104AG
32pin	R5F104BA, R5F104BC, R5F104BD, R5F104BE, R5F104BF, R5F104BG
36pin	R5F104CA, R5F104CC, R5F104CD, R5F104CE, R5F104CF, R5F104CG
40pin	R5F104EA, R5F104EC, R5F104ED, R5F104EE, R5F104EF, R5F104EG, R5F104EH
44pin	R5F104FA, R5F104FC, R5F104FD, R5F104FE, R5F104FF, R5F104FG, R5F104FH R5F104FJ
48pin	R5F104GA, R5F104GC, R5F104GD, R5F104GE, R5F104GF, R5F104GG, R5F104GH R5F104GJ, R5F104GK, R5F104GL
52pin	R5F104JC, R5F104JD, R5F104JE, R5F104JF, R5F104JG, R5F104JH R5F104JJ, R5F104JK, R5F104JL
64pin	R5F104LC, R5F104LD, R5F104LE, R5F104LF, R5F104LG, R5F104LH R5F104LJ, R5F104LK, R5F104LL
80pin	R5F104MF, R5F104MG, R5F104MH, R5F104MJ
100pin	R5F104PF, R5F104PG, R5F104PH, R5F104PJ
The Applilet3 is based on the following documents.	
Manual Name	Document Number
RL78/G14 User's Manual: Hardware	R01UH0186JJ0200 Rev.2.00
	R01UH0186EJ0200 Rev.2.00

Below is a list of devices supported by the Applilet3 for RL78/G1A V2.03.05.01	
PIN	Device name
25pin	R5F10E8A, R5F10E8C, R5F10E8D, R5F10E8E
32pin	R5F10EBA, R5F10EBC, R5F10EBD, R5F10EBE
48pin	R5F10EGA, R5F10EGC, R5F10EGD, R5F10EGE
64pin	R5F10ELC, R5F10ELD, R5F10ELE
The Applilet3 is based on the following documents.	
Manual Name	Document Number
RL78/G1A User's Manual: Hardware	R01UH0305JJ0200 Rev.2.00
	R01UH0305EJ0200 Rev.2.00

Below is a list of devices supported by the Applilet3 for RL78/F12 V2.03.05.01	
PIN	Device name
20pin	R5F1096E, R5F1096D, R5F1096C, R5F1096B, R5F1096A, R5F10968
30pin	R5F109AE, R5F109AD, R5F109AC, R5F109AB, R5F109AA
32pin	R5F109BE, R5F109BD, R5F109BC, R5F109BB, R5F109BA
48pin	R5F109GE, R5F109GD, R5F109GC, R5F109GB, R5F109GA
64pin	R5F109LE, R5F109LD, R5F109LC, R5F109LB, R5F109LA
The Applilet3 is based on the following documents.	
Manual Name	Document Number
RL78/F12 User's Manual: Hardware	R01UH0231JJ0110 Rev.1.10
	R01UH0231EJ0111 Rev.1.11

Below is a list of devices supported by the Applilet3 for RL78/L12 V2.03.03.03	
PIN	Device name
32pin	R5F10RBC, R5F10RBA, R5F10RB8
44pin	R5F10RFC, R5F10RFA, R5F10RF8
48pin	R5F10RGC, R5F10RGA, R5F10RG8
52pin	R5F10RJC, R5F10RJA, R5F10RJ8
64pin	R5F10RLC, R5F10RLA
The Applilet3 is based on the following documents	
Manual Name	Document Number
RL78/L12 User's Manual: Hardware	R01UH0330JJ0200 Rev.2.00
	R01UH0330EJ0200 Rev.2.00

Below is a list of devices supported by the Applilet3 for RL78/D1A V2.03.04.01	
PIN	Device name
48pin	R5F10CGB, R5F10CGC, R5F10DGC, R5F10DGD, R5F10DGE
64pin	R5F10CLD, R5F10DLD, R5F10DLE
80pin	R5F10CMD, R5F10CME R5F10DMD, R5F10DME, R5F10DMF, R5F10DMG, R5F10DMJ
100pin	R5F10DPE, R5F10DPF, R5F10DPG, R5F10DPJ, R5F10TPJ
Applilet3 for RL78_D1A is based on the following documents	
Manual Name	Document Number
RL78/D1A User's Manual: Hardware	R01UH0317EJ0100 Rev.1.00

Below is a list of devices supported by the Applilet3 for RL78/F13 V2.02.05.01	
PIN	Device name
20pin	R5F10A6A, R5F10A6C, R5F10A6D, R5F10A6E
30pin	R5F10AAA, R5F10AAC, R5F10AAD, R5F10AAE R5F10BAC, R5F10BAD, R5F10BAE, R5F10BAF, R5F10BAG
32pin	R5F10ABA, R5F10ABC, R5F10ABD, R5F10ABE R5F10BBC, R5F10BBD, R5F10BBE, R5F10BBF, R5F10BBG
48pin	R5F10AGA, R5F10AGC, R5F10AGD, R5F10AGE, R5F10AGF, R5F10AGG R5F10BGC, R5F10BGD, R5F10BGE, R5F10BGF, R5F10BGG
64pin	R5F10BLC, R5F10ALD, R5F10ALE, R5F10ALF, R5F10ALG R5F10BLC, R5F10BLD, R5F10BLE, R5F10BLF, R5F10BLG
80pin	R5F10AME, R5F10AMF, R5F10AMG R5F10BME, R5F10BMF, R5F10BMG
The Applilet3 is based on the following documents.	
Manual Name	Document Number
RL78/F13,F14 User's Manual: Hardware	R01UH0368JJ0100 Rev.1.00
	R01UH0368EJ0100 Rev.1.00

Below is a list of devices supported by the Applilet3 for RL78/F14 V2.02.05.01	
PIN	Device name
30pin	R5F10PAD, R5F10PAE
32pin	R5F10PBD, R5F10PBE
48pin	R5F10PGD, R5F10PGE, R5F10PGF, R5F10PGG, R5F10PGH, R5F10PGJ
64pin	R5F10PLE, R5F10PLF, R5F10PLG, R5F10PLH, R5F10PLJ
80pin	R5F10PME, R5F10PMF, R5F10PMG, R5F10PMH, R5F10PMJ
100pin	R5F10PPE, R5F10PPF, R5F10PPG, R5F10PPH, R5F10PPJ
The Applilet3 is based on the following documents.	
Manual Name	Document Number
RL78/F13,F14 User's Manual: Hardware	R01UH0368JJ0100 Rev.1.00
	R01UH0368EJ0100 Rev.1.00

Below is a list of devices supported by the Applilet3 for RL78/F15 V1.00.05.01	
PIN	Device name
48pin	R5F113GL, R5F113GK
64pin	R5F113LL, R5F113LK
80pin	R5F113ML, R5F113MK
100pin	R5F113PL, R5F113PK, R5F113PJ, R5F113PH, R5F113PG
144pin	R5F113TL, R5F113TK, R5F113TJ, R5F113TH, R5F113TG
The Code Generator is based on the following documents	
Manual Name	Document Number
RL78/F15 User's Manual: Hardware	R01UH0559JJ0050 Rev.0.50
	R01UH0559EJ0050 Rev.0.50

Chapter 3. Operating Environment

Host machine

- IBM PC/AT compatibles (Windows® 10, Windows® 8.1, Windows® 7)
- Processor: 1 GHz or higher (must support hyper-threading, multi-core CPUs)
- Memory capacity: 2 GB or more recommended. Minimum requirement is 1 GB or more (64-bit Windows requires 2 G or more)
- Hard disk capacity: 200 MB or more spare capacity
- Display: 1024 x 768 or higher resolution, 65,536 or more colors
- All other necessary software environments in addition to WindowsOS
 - .NET Framework version4.5
 - Microsoft Visual C++ 2010 SP1 runtime library

▪ Development Environments

Product Name	Version
IAR Embedded Workbench for Renesas RL78	V2.21.1 or later
GNURL78	V15.02 or later
Renesas electronics Compiler for 78K0R [CA78K0R]	V1.72 or later
Renesas electronics Compiler for RL78 [CC-RL]	V1.04 or later

Chapter 4. Changes

This chapter describes change to the Applilet3 for RL78 V1.12.00.

No	Description	Version *1										
		RL78/F15	RL78/F14	RL78/F13	RL78/L12	RL78/F12	RL78/G1A	RL78/G12	RL78/G13	RL78/G14	RL78/1A	RL78/D1A
1	Change of the note on Peripheral I/O Redirection Register(PIOR)	○	○	○	/	○	○	/	/	/	/	/

○: Applicable, /: Not Applicable

Note 1: Version is described in the generated code.

4.1 Details of Changes

4.1.1 Change of the note on Peripheral I/O Redirection Register(PIOR)

The problem (1) was corrected about the following device.

RL78 family: RL78/F12, RL78/F13, RL78/F14, RL78/F15 and RL78/G1A groups

(1) RENESAS TOOL NEWS Document No. R20TS0045EJ0100 (CS+ for CC)(CS+ for CA,CX)

1. Peripheral I/O Redirection Register 0 (PIOR0)

RL78 family: RL78/G1F group (32- and 36-pin products)

For details of the problem, refer to the URL below.

<https://www.renesas.com/en-us/doc/toolnews/eng/2016/r20ts0045ej0100-cstnno.pdf>

Chapter 5. Points for Caution

This section describes points for caution regarding the Applilet3 for RL78 V1.12.00.

5.1 Cautions List

No	Description	Version *1										
		RL78/F15	RL78/F14	RL78/F13	RL78/L12	RL78/F12	RL78/G1A	RL78/G12	RL78/G13	RL78/G14	RL78/I1A	RL78/D1A
		V1.00.05.01	V2.02.05.01	V2.02.05.01	V2.03.03.03	V2.03.05.01	V2.03.05.01	V2.03.04.01	V2.03.04.01	V2.04.05.01	V2.03.05.02	V2.03.04.01
1	Cautions when using a DTC function	○	○	/	/	/	/	/	/	○	/	/
2	Cautions of timer array unit input clock sauce	○	○	○	/	/	/	/	/	/	/	/

○: Applicable, /: Not Applicable

Note 1: Version is described in the generated code.

5.2 Cautions Details


5.2.1 Cautions when using a DTC function

When DTC is used, the following warning message is displayed and an object file is not generated.

CC78K0R warning W0837: Output assembler source file , not object file

[Workaround]

Set up the following individual option of building.



5.2.2 Cautions of timer array unit input clock sauce

When the clock sauce of a timer input is set as a RTC1HZ output by setup of a timer array unit, a setup about the output of the RTC1HZ terminal of a real-time clock becomes invalid. The code which outputs RTC1HZ then is not generated.

[Workaround] When you set to a RTC1HZ signal by setup of a timer array unit, please choose a setup which uses a real-time clock and add the code which outputs RTC1HZ.

Chapter 6. Restrictions

This section describes the restrictions on the Applilet3 for RL78 V1.12.00.

6.1 List of Restrictions

No	Description	Version *1										
		RL78/F15	RL78/F14	RL78/F13	RL78/L12	RL78/F12	RL78/G1A	RL78/G12	RL78/G13	RL78/G14	RL78/I1A	RL78/D1A
		V1.00.05.01	V2.02.05.01	V2.02.05.01	V2.03.03.03	V2.03.05.01	V2.03.05.01	V2.03.04.01	V2.03.04.01	V2.04.05.01	V2.03.05.02	V2.03.04.01
1	Online Help	○	○	○	○	○	○	○	○	○	○	○
2	The coding rule of MISRA-C.	○	○	○	○	○	○	○	○	○	○	○
3	Restrictions of High-speed on-chip oscillator frequency select register	○	○	○	○	○	○	○	○	○	/	○
4	Restrictions of internal low-speed or internal high-speed oscillator trimming	○	○	○	○	○	○	○	○	○	○	○
5	Restriction of a serial array unit	/	/	/	/	/	/	/	/	/	○	/
6	Restrictions of Flash memory CRC operation function (high-speed CRC)	○	○	○	○	○	○	○	○	○	○	○
7	Restrictions of Port mode select register (PMS)	○	○	○	○	○	○	○	○	○	○	○
8	Restrictions of the LIN-bus function of UART	○	○	○	○	○	○	○	○	○	○	○
9	Restrictions of extension code, wakeup function and multimaster of serial interface IICA or IIC0	○	○	○	○	○	○	○	○	○	○	○
10	Restriction of CAN	○	○	○	/	/	/	/	/	/	/	/
11	Cautions of Safety Functions	○	○	○	○	○	○	○	○	○	○	○

○: Applicable, -: Not Applicable, /: Outside of function.

Note 1: Version is described in the generated code.

6.2 Restrictions Details

6.2.1 Online Help

Applilet3 is not supporting online help.

6.2.2 Restrictions of the coding rule of MISRA-C

Compliance with the MISRA-C (Guidelines for the Use of the C Language in Vehicle Based Software) coding convention is not supported for source code output by the Applilet3.

6.2.3 Restrictions of High-speed on-chip oscillator frequency select register

Applilet3 is not equivalent to a setup of high-speed on-chip oscillator frequency select register

6.2.4 Restrictions of internal low-speed or internal high-speed oscillator trimming

Applilet3 is not equivalent to a setup of internal low-speed or internal high-speed oscillator trimming register.

6.2.5 Restriction of a serial array unit

Applilet3 is not equivalent to a setup of single-wire UART mode and DMX512 communication.

6.2.6 Restrictions of Flash memory CRC operation function (high-speed CRC)

Applilet3 does not correspond to a flash memory CRC operation function (high-speed CRC). Please refer to application note r01an0736ej.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r01an0736ej>

6.2.7 Restrictions of Port mode select register (PMS)

Applilet3 does not correspond to a port mode select register (PMS).

6.2.8 Restrictions of the LIN-bus function of UART

The Applilet3 is not supporting the LIN-bus functions of serial interface UART0, UART2, UART3, UART6 or UARTF. Moreover, detection of the LIN communication Wakeup signal of INTPO isn't been supported.

6.2.9 Restrictions of extension code, wakeup function and multimaster of serial interface IICA or IIC0

The Applilet3 is not supporting the extension code, multimaster, wakeup function of serial interface IIC.

6.2.10 Restriction of CAN

Applilet3 is not supporting CAN.

6.2.11 Restriction of Safety functions

RAM parity error detection function of Safety Functions has not corresponded.

Chapter 7. Correction History

This section describes correction history of RENESAS TOOL NEWS.

7.1 List of RENESAS TOOL NEWS

Issue Date	Document No.	Description	Device Concerned	Fixed version
Aug. 01, 2012	120801/tn8	Problems arising in Applilet3 for RL78/G13 and Applilet3 for RL78/G14	RL78/G13, RL78/G14	V1.00.00
Oct. 01, 2012	121001/tn1	With generating code that make setting of using Multiple PWM	RL78/D1A	V1.00.00
Feb. 01, 2013	130201/tn6	With making settings of RD timer in PWM mode	RL78/G14	V1.00.00
		Making settings of RJ timer in pulse period measurement mode	RL78/G14	V1.00.00
Oct. 16, 2013	131016/tn4	With the key input interrupt setting	RL78/L12	V1.00.00
		With A/D converter operation setting	RL78/G1A	V1.00.00
Apr. 16, 2014	140416/tn8	With selecting the 20-pin, 30-pin, or 32-pin package for the RL78/F13 or RL78/F14 group	RL78/F13, RL78/F14	V1.00.00
		With using the remote control carrier wave mask signal in the RL78/L12 group	RL78/L12	V1.00.00
		With the case when ports that are not available in the MCU are displayed in the RL78/G14 group	RL78/G14	V1.00.00
Aug. 16, 2014	140816/tn6	With setting of port 1	RL78/G14	V1.06.00
Dec. 16, 2014	141216/tn5	3. Saving Projects with Settings for the A/D Converter	RL78/L1C	V1.07.00
Jul. 16, 2015	150716/tn2	1. Clock Generation Circuit (PLL Circuit Operation)	RL78/D1A, RL78/F13, RL78/F14	V1.10.00
		2. Setting P40 of Port 4	RL78/D1A, RL78/F12, RL78/F13, RL78/F14, RL78/G12, RL78/G13, RL78/G14, RL78/G1A, RL78/I1A, RL78/L12	V1.10.00
		3. Code Generated for UART0 and UARTF	RL78/F12	V1.10.00

Issue Date	Document No.	Description	Device Concerned	Fixed version
Nov. 16, 2015	151116/tn2	1. Indication of Channels of Serial Interface IICA	RL78/G14	V1.10.00
		2. Procedure for Setting the PLL Clock	RL78/F13, RL78/F14, RL78/F15	V1.10.00
Jan. 16, 2016	160116/tn5	Transfer of data with a length of 10 or more bits through an element of a serial array unit configured as a CSI or data with a length of 16 bits through an element configured as a UART	RL78/F12, RL78/F13, RL78/F14, RL78/F15, RL78/D1A	V1.10.00
Feb. 16, 2016	160216/tn5	1. Using the error interrupt of serial array unit 4 as UART4 or DALI4	RL78/I1A	V1.10.00
		2. Using serial array unit 4 as DALI4	RL78/I1A	V1.10.00
Mar. 16, 2016	160316/tn1	Pin settings for the IICA serial interface when setting the PIOR to change the assignment of pin functions	RL78/G12	V1.10.00
Jun. 16, 2016	R20TS0038EJ0100	Scan Mode of A/D Converter	RL78/F12, RL78/F13, RL78/F14, RL78/F15, RL78/G1A	V1.11.00

7.2 Details of RENESAS TOOL NEWS

7.2.1 RENESAS TOOL NEWS Document No.120801/tn8

This issue has been corrected in Applilet3 for RL78 V1.00.00.

(1) In Applilet3 for RL78/G13 V1.03.01

a. If code is generated so that timers TAUx (x is 1 to 7) of an 80-, 100-, or 128-pin MCU can output square waves, the values of the TOM1 and TOL1 registers, which control TAUx, are not set but those of the TOM0 and TOL0 registers are set.

b. If you make settings of ports, the TTL checkboxes for the P10 and P11 pins are not displayed.

(2) In Applilet3 for RL78/G14 V1.01.01

a. In the code for setting registers PIOR01 and PIOR04 to 1s in an arrangement of pin assignments, incorrect pins are assigned to INTP10 and INTP11 as follows:

Incorrect:	Correct:
P110 assigned to INTP10	P100 assigned to INTP10
P111 assigned to INTP11	P110 assigned to INTP11

b. If code is generated in an 80- or 100-pin MCU, no functions except "interval" can be selected in the functional selection of timer TAU1.

c. If the code is generated for making settings of UART2 and any of the ports except 13 and 14, an error arises in building it.

d. In the settings of DTC, the following error is found in the pulldown list of source and destination addresses of data transfer:

Erroneous statement: Address decremented
It must be read as Address incremented

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2012/120801tn8_e.pdf

7.2.2 RENESAS TOOL NEWS Document No.121001/tn1

This issue has been corrected in Applilet3 for RL78 V1.00.00.

· With generating code that make setting of using Multiple PWM

If the code is generated for making setting of using Multiple PWM on the TAU2 register in timer array unit 2, data is output on undefined channels in error.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2012/121001tn1_e.pdf

7.2.3 RENESAS TOOL NEWS Document No.130201/tn6

This issue has been corrected in Applilet3 for RL78 V1.00.00.

- With making settings of RD timer in PWM mode

(1) With generating incorrect code for cyclic register

If you select PWM from among the operating modes of the RD timer and 64 MHz from among the clock frequencies of the high-speed on-chip oscillator, the code generator generates incorrect code; that is, the value (duty ratio) of the cyclic register is erroneous.

(2) With using alternate-function pins

When the PWM mode is used, every pin for the PWM output, which is an alternate-function pin, cannot be used for the other function. So if you make settings for using these pins for the other functions than PWM, Applilet express an alarm (symbol "!"). However, if you have selected the PWM mode in the RD timer, this alarm is not expressed on the information setting area of the [Port].

- Making settings of RJ timer in pulse period measurement mode

If you select the Pulse Period Measurement Mode from among the operating modes of the RJ timer, the code generator generates erroneous code.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2013/130201tn6_e.pdf

7.2.4 RENESAS TOOL NEWS Document No.131016/tn3

This issue has been corrected in Applilet3 for RL78 V1.00.00.

- When the timer KB20 is in Use

When the timer KB20 is in use, the settings for Standalone mode (period controlled by external trigger input) and Interleave PFC (power factor correction) output mode may prevent the correct output of the API functions.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2013/131016tn3_e.pdf

7.2.5 RENESAS TOOL NEWS Document No.131016/tn4

This issue has been corrected in Applilet3 for RL78 V1.00.00.

- With the key input interrupt setting (RL78/L12 Group)

The setting of Key interrupt flag and Detection edge may not be saved. When saving the project after making the new setting and then reloading the project, the setting reverts to the original setting as the new one had not been saved.

- With A/D converter operation setting (RL78/G1A Group)

The Conversion time mode of the Conversion time setting may not be saved. When saving the project after making the new setting and then reloading the project, the setting reverts to the original setting as the new one had not been saved.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2013/131016tn4_e.pdf

7.2.6 RENESAS TOOL NEWS Document No.140416/tn8

This issue has been corrected in Applilet3 for RL78 V1.00.00.

- With selecting the 20-pin, 30-pin, or 32-pin package for the RL78/F13 or RL78/F14 group

When the 20-pin, 30-pin, or 32-pin package is selected for the RL78/F13 or RL78/F14 group and a divided frequency is selected for CPU and peripheral clock (fCLK) in the clock generator settings, the register settings are not output.

- With using the remote control carrier wave mask signal in the RL78/L12 group

There is an error in the R_TAU0_Channel2_Stop function for output when PWM output (remote control carrier wave mask signal) is selected in timer channel 2.

- With the case when ports that are not available in the MCU are displayed in the RL78/G14 group

When an RL78/G14 group MCU in the 80-pin package is selected, the settings for the P80 and P81 ports, which are not available in the selected MCU, are displayed.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2014/140416tn8_e.pdf

7.2.7 RENESAS TOOL NEWS Document No.140816/tn6

This issue has been corrected in Applilet3 for RL78 V1.06.00.

- With setting of port 1 (target: RL78/G14 group)

When the port pins listed below are selected for port 1, the Code Generator outputs the unnecessary operator and value "|_33_PMC1_DEFAULT". This is because the initial settings for unused bits in the PMC1 register are incorrect.

- P12
- P13
- P16
- P17

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2014/140816tn6_e.pdf

7.2.8 RENESAS TOOL NEWS Document No.141216/tn5

This issue has been corrected in Applilet3 for RL78 V1.07.00.

3. Saving Projects with Settings for the A/D Convertor (Applicable Products: RL78/L1C Group)

When a project configured with the below settings for the A/D convertor is read, the "A fatal error occurred" dialog box is displayed, after which CS+ operation is terminated.

- Selection of analog input pin from among ANI0-ANI2, ANI5, and ANI6:
ANI0-ANI1
- VREF(+)setting:
AVREFP
- VREF(-)setting:
AVREFM

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2014/141216tn5_e.pdf

7.2.9 RENESAS TOOL NEWS Document No.150716/tn2

This issue has been corrected in Applilet3 for RL78 V1.10.00.

1. Clock Generation Circuit (PLL Circuit Operation)

(Applicable MCUs: RL78/D1A, RL78/F13, and RL78/F14 groups)

Generated code includes an error when the PLL circuit is operating as the clock generation circuit.

A wait is required immediately after setting the PLL control register (PLLCTL).

2. Setting P40 of Port 4

(Applicable MCUs: RL78/D1A, RL78/F12, RL78/F13, RL78/F14, RL78/G12, RL78/G13, RL78/G14, RL78/G1A, RL78/I1A, and RL78/L12 groups)

Generated code has an error when P40 is set such that the on-chip pull-up resistor for P40 is not connected even though this is included in the settings of the on-chip pull-up resistors for port 4.

The code to set the pull-up resistor option register (PU4) of P40 is not generated.

3. Code Generated for UART0 and UARTF

(Applicable MCUs: RL78/F12 group)

(a) Generated code has an error when unit 0 of the serial array unit is used as UART0 and its configuration is set to transmission or transmission and reception. Unnecessary code is output to the function void R_UART0_Creat(void) which is in r_cg_serial.c

(b) Generated code has an error in the setting of the LTXD0 pin when the asynchronous serial interface LIN-UART (UARTF) is set for transmission or transmission and reception.

Incorrect code is output to the function void R_UARTF0_Create(void) which is in r_cg_serial.c.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2015/150716tn2_e.pdf

7.2.10 RENESAS TOOL NEWS Document No.151116/tn2

This issue has been corrected in Applilet3 for RL78 V1.10.00.

1. Indication of Channels of Serial Interface IICA

(Applicable MCUs: RL78/G14 group R5F104MK, R5F104PK, R5F104ML, and R5F104PL)

Since the GUI does not indicate the channel 1 IICA serial interface for the above products, graphically setting up its operation is impossible. Accordingly, code for channel 1 cannot be generated.

2. Procedure for Setting the PLL Clock

(Applicable MCUs: RL78/F13, RL78/F14, and RL78/F15 groups)

The generated code for setting the PLL clock in the clock generation circuit differs from the example of PLL settings in User's Manual: Hardware for the MCUs and is thus incorrect.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2015/151116tn2_e.pdf

7.2.11 RENESAS TOOL NEWS Document No.160116/tn5

This issue has been corrected in Applilet3 for RL78 V1.10.00.

- Transfer of data with a length of 10 or more bits through an element of a serial array unit configured as a CSI or data with a length of 16 bits through an element configured as a UART (Applicable MCUs: RL78/F12, RL78/F13, RL78/F14, RL78/F15, and RL78/D1A groups)

Generated code has an error when an element of a serial array unit is set up for use as a 3-line serial (CSI) port and the length of data is specified as 10 or more bits, or the unit is set up for use as a UART and the length of data is specified as 16 bits.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2016/160116tn5_e.pdf

7.2.12 RENESAS TOOL NEWS Document No.160216/tn5

This issue has been corrected in Applilet3 for RL78 V1.10.00.

1. Using the error interrupt of serial array unit 4 as UART4 or DALI4 (Applicable products: RL78/I1A group)

Since the generated code has an error when error interrupts from serial array unit 4 as UART4 or DALI4 (digital addressable lighting interface) are selected, errors cannot be detected.

2. Using serial array unit 4 as DALI4 (Applicable products: RL78/I1A group)

Since the generated code has an error when the length of units for sending is set to 16 bits or the length for reception is set to 16, 17, or 24 bits, and serial array unit 4 is to be used as DALI4, transfer will not operate correctly.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2016/160216tn5_e.pdf

7.2.13 RENESAS TOOL NEWS Document No.160316/tn1

This issue has been corrected in Applilet3 for RL78 V1.10.00.

- Pin settings for the IICA serial interface when setting the PIOR to change the assignment of pin functions

(Applicable MCUs: RL78/G12 group (20- and 24-pin products))

When the IICA pin functions are redirected in the following way by setting the peripheral I/O redirection register (PIOR) to change the pin assignment, the generated code for the pin setting will have an error. This makes the IICA clock and data pins unusable with this setting.

(1) In setting the arrangement of pins for the clock generation circuit, select peripheral I/O redirection by checking PIOR2 bit = 1, and click on the button to fix the given pins as the pins to use.

(2) Operation as a single master or as a slave is selected on the IICA0 tabbed page.

For details of the problem, refer to the URL below.

https://www.renesas.com/doc/toolnews/eng/2016/160316tn1_e.pdf

7.2.14 RENESAS TOOL NEWS Document R20TS0038EJ0100

This issue has been corrected in Applilet3 for RL78 V1.11.00.

- Scan Mode of A/D Converter

RL78 family: RL78/F12, RL78/F13, RL78/F14, RL78/F15, and RL78/G1A groups

The following error dialog boxes might be displayed when the A/D converter is used in serial scan mode or one-shot scan mode, and three or fewer analog input pins are selected.

For details of the problem, refer to the URL below.

https://www.renesas.com/en-us/doc/toolnews/eng/2016/r20ts0038ej0100_cstnno.pdf

Notice

1. Descriptions of circuits, software and other related information in this document are provided only to illustrate the operation of semiconductor products and application examples. You are fully responsible for the incorporation of these circuits, software, and information in the design of your equipment. Renesas Electronics assumes no responsibility for any losses incurred by you or third parties arising from the use of these circuits, software, or information.
2. Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.
3. Renesas Electronics does not assume any liability for infringement of patents, copyrights, or other intellectual property rights of third parties by or arising from the use of Renesas Electronics products or technical information described in this document. No license, express, implied or otherwise, is granted hereby under any patents, copyrights or other intellectual property rights of Renesas Electronics or others.
4. You should not alter, modify, copy, or otherwise misappropriate any Renesas Electronics product, whether in whole or in part. Renesas Electronics assumes no responsibility for any losses incurred by you or third parties arising from such alteration, modification, copy or otherwise misappropriation of Renesas Electronics product.
5. Renesas Electronics products are classified according to the following two quality grades: "Standard" and "High Quality". The recommended applications for each Renesas Electronics product depends on the product's quality grade, as indicated below.
"Standard": Computers; office equipment; communications equipment; test and measurement equipment; audio and visual equipment; home electronic appliances; machine tools; personal electronic equipment; and industrial robots etc.
"High Quality": Transportation equipment (automobiles, trains, ships, etc.); traffic control systems; anti-disaster systems; anti-crime systems; and safety equipment etc.
Renesas Electronics products are neither intended nor authorized for use in products or systems that may pose a direct threat to human life or bodily injury (artificial life support devices or systems, surgical implantations etc.), or may cause serious property damages (nuclear reactor control systems, military equipment etc.). You must check the quality grade of each Renesas Electronics product before using it in a particular application. You may not use any Renesas Electronics product for any application for which it is not intended. Renesas Electronics shall not be in any way liable for any damages or losses incurred by you or third parties arising from the use of any Renesas Electronics product for which the product is not intended by Renesas Electronics.
6. You should use the Renesas Electronics products described in this document within the range specified by Renesas Electronics, especially with respect to the maximum rating, operating supply voltage range, movement power voltage range, heat radiation characteristics, installation and other product characteristics. Renesas Electronics shall have no liability for malfunctions or damages arising out of the use of Renesas Electronics products beyond such specified ranges.
7. Although Renesas Electronics endeavors to improve the quality and reliability of its products, semiconductor products have specific characteristics such as the occurrence of failure at a certain rate and malfunctions under certain use conditions. Further, Renesas Electronics products are not subject to radiation resistance design. Please be sure to implement safety measures to guard them against the possibility of physical injury, and injury or damage caused by fire in the event of the failure of a Renesas Electronics product, such as safety design for hardware and software including but not limited to redundancy, fire control and malfunction prevention, appropriate treatment for aging degradation or any other appropriate measures. Because the evaluation of microcomputer software alone is very difficult, please evaluate the safety of the final products or systems manufactured by you.
8. Please contact a Renesas Electronics sales office for details as to environmental matters such as the environmental compatibility of each Renesas Electronics product. Please use Renesas Electronics products in compliance with all applicable laws and regulations that regulate the inclusion or use of controlled substances, including without limitation, the EU RoHS Directive. Renesas Electronics assumes no liability for damages or losses occurring as a result of your noncompliance with applicable laws and regulations.
9. Renesas Electronics products and technology may not be used for or incorporated into any products or systems whose manufacture, use, or sale is prohibited under any applicable domestic or foreign laws or regulations. You should not use Renesas Electronics products or technology described in this document for any purpose relating to military applications or use by the military, including but not limited to the development of weapons of mass destruction. When exporting the Renesas Electronics products or technology described in this document, you should comply with the applicable export control laws and regulations and follow the procedures required by such laws and regulations.
10. It is the responsibility of the buyer or distributor of Renesas Electronics products, who distributes, disposes of, or otherwise places the product with a third party, to notify such third party in advance of the contents and conditions set forth in this document, Renesas Electronics assumes no responsibility for any losses incurred by you or third parties as a result of unauthorized use of Renesas Electronics products.
11. This document may not be reproduced or duplicated in any form, in whole or in part, without prior written consent of Renesas Electronics.
12. Please contact a Renesas Electronics sales office if you have any questions regarding the information contained in this document or Renesas Electronics products, or if you have any other inquiries.

(Note 1) "Renesas Electronics" as used in this document means Renesas Electronics Corporation and also includes its majority-owned subsidiaries.

(Note 2) "Renesas Electronics product(s)" means any product developed or manufactured by or for Renesas Electronics.



SALES OFFICES

Renesas Electronics Corporation

<http://www.renesas.com>

Refer to "<http://www.renesas.com/>" for the latest and detailed information.

Renesas Electronics America Inc.

2801 Scott Boulevard Santa Clara, CA 95050-2549, U.S.A.
Tel: +1-408-588-6000, Fax: +1-408-588-6130

Renesas Electronics Canada Limited

9251 Yonge Street, Suite 8309 Richmond Hill, Ontario Canada L4C 9T3
Tel: +1-905-237-2004

Renesas Electronics Europe Limited

Dukes Meadow, Millboard Road, Bourne End, Buckinghamshire, SL8 5FH, U.K.
Tel: +44-1628-585-100, Fax: +44-1628-585-900

Renesas Electronics Europe GmbH

Arcadiastrasse 10, 40472 Düsseldorf, Germany
Tel: +49-211-6503-0, Fax: +49-211-6503-1327

Renesas Electronics (China) Co., Ltd.

Room 1709, Quantum Plaza, No.27 ZhiChunLu Haidian District, Beijing 100191, P.R.China
Tel: +86-10-8235-1155, Fax: +86-10-8235-7679

Renesas Electronics (Shanghai) Co., Ltd.

Unit 301, Tower A, Central Towers, 555 Langao Road, Putuo District, Shanghai, P. R. China 200333
Tel: +86-21-2226-0888, Fax: +86-21-2226-0999

Renesas Electronics Hong Kong Limited

Unit 1601-1611, 16/F., Tower 2, Grand Century Place, 193 Prince Edward Road West, Mongkok, Kowloon, Hong Kong
Tel: +852-2265-6688, Fax: +852 2886-9022

Renesas Electronics Taiwan Co., Ltd.

13F, No. 363, Fu Shing North Road, Taipei 10543, Taiwan
Tel: +886-2-8175-9600, Fax: +886 2-8175-9670

Renesas Electronics Singapore Pte. Ltd.

80 Bendemeer Road, Unit #06-02 Hyflux Innovation Centre, Singapore 339949
Tel: +65-6213-0200, Fax: +65-6213-0300

Renesas Electronics Malaysia Sdn.Bhd.

Unit 1207, Block B, Menara Amcorp, Amcorp Trade Centre, No. 18, Jln Persiaran Barat, 46050 Petaling Jaya, Selangor Darul Ehsan, Malaysia
Tel: +60-3-7955-9390, Fax: +60-3-7955-9510

Renesas Electronics India Pvt. Ltd.

No.77C, 100 Feet Road, HAL II Stage, Indiranagar, Bangalore, India
Tel: +91-80-67208700, Fax: +91-80-67208777

Renesas Electronics Korea Co., Ltd.

12F., 234 Teheran-ro, Gangnam-Gu, Seoul, 135-080, Korea
Tel: +82-2-558-3737, Fax: +82-2-558-5141