

This document outlines the device support, new features added in 4.0.2, fixed issues and open issues in e² studio 4.0.2.

1. Project Generator Support

| CPU | Family | Devices |
|-------|----------|---|
| RH850 | C1H | R7F701260, R7F701270,(Debug Support Only) |
| | C1M | R7F701263, R7F701271,(Debug Support Only) |
| | E1L | R7F701201, R7F701205,(Debug Support Only) |
| | E1M-S | R7F701202, R7F701204,(Debug Support Only) |
| | E1x-FCC1 | R7F701Z05, R7F701Z06, R7F701Z07,(Debug Support Only) |
| | F1H | R7F701501, R7F701502xAFP, R7F701503, R7F701506, R7F701507, R7F701508, R7F701511, R7F701512, R7F701513,(Debug Support Only) |
| | F1H-GW | R7F701521, R7F701522, R7F701524, R7F701525,(Debug Support Only) |
| | F1L | R7F701006xAFP, R7F701007xAFP, R7F701008xAFP, R7F701009xAFP, R7F701010xAFP, R7F701011xAFP, R7F701012xAFP, R7F701013xAFP, R7F701014xAFP, R7F701015xAFP, R7F701016xAFP, R7F701017xAFP, R7F701018xAFP, R7F701019xAFP, R7F701020xAFP, R7F701021xAFP, R7F701022xAFP, R7F701023xAFP, R7F701024xAFP, R7F701025xAFP, R7F701026xAFP, R7F701027xAFP, R7F701028xAFP, R7F701029xAFP, R7F701030xAFP, R7F701032xAFP, R7F701033xAFP, R7F701034xAFP, R7F701040, R7F701041, R7F701042, R7F701043, R7F701044, R7F701045, R7F701046, R7F701047, R7F701048, R7F701049, R7F701050, R7F701051, R7F701052, R7F701053, R7F701054, R7F701055, R7F701056, R7F701057,(Debug Support Only) |
| | F1L-GW | R7F701002xAFP, R7F701003xAFP,(Debug Support Only) |
| | F1M | R7F701544, R7F701545, R7F701548, R7F701549, R7F701552, R7F701553, R7F701564, R7F701565, R7F701568, R7F701569, R7F701572, R7F701573,(Debug Support Only) |
| | P1M | R7F701304, R7F701305, R7F701310, R7F701311, R7F701312, R7F701313, R7F701314, R7F701315, R7F701318, R7F701319, R7F701320, R7F701321, R7F701322, R7F701323,(Debug Support Only) |
| | - | R7F701060xAFP, R7F701062xAFP, R7F701064xAFP, R7F701065xAFP, R7F701067xAFP, R7F701069xAFP, R7F701071xAFP,(Debug Support Only) |
| RL78 | D1A | R5F10CGB, R5F10CGC, R5F10CGD, R5F10CLD, R5F10CMD, R5F10CME, R5F10DGC, R5F10DGD, R5F10DGE, R5F10DLA, R5F10DLE, R5F10DMD, R5F10DME, R5F10DMF, R5F10DMG, R5F10DMJ, R5F10DPE, R5F10DPF, R5F10DPG, R5F10DPJ, R5F10DPK, R5F10DPL, R5F10DSJ, R5F10DSK, R5F10DSL, R5F10TPJ |
| | F12 | R5F10968, R5F1096A, R5F1096B, R5F1096C, R5F1096D, R5F1096E, R5F109AA, R5F109AB, R5F109AC, R5F109AD, R5F109AE, R5F109BA, R5F109BB, R5F109BC, R5F109BD, R5F109BE, R5F109GA, R5F109GB, R5F109GC, R5F109GD, R5F109GE, R5F109LA, R5F109LB, R5F109LC, R5F109LD, R5F109LE |
| | F13 | R5F10A6A, R5F10A6C, R5F10A6D, R5F10A6E, R5F10AAA, R5F10AAC, R5F10AAD, R5F10AAE, R5F10ABA, R5F10ABC, R5F10ABD, R5F10ABE, R5F10AGA, R5F10AGC, R5F10AGD, R5F10AGE, R5F10AGF, R5F10AGG, R5F10ALC, R5F10ALD, R5F10ALE, R5F10ALF, R5F10ALG, R5F10AME, R5F10AMF, R5F10AMG, R5F10BAC, R5F10BAD, R5F10BAE, R5F10BAF, R5F10BAG, R5F10BBC, R5F10BBD, R5F10BBE, R5F10BBF, R5F10BBG, R5F10BGC, R5F10BGD, R5F10BGE, R5F10BGF, R5F10BGG, R5F10BLC, R5F10BLD, R5F10BLE, R5F10BLF, R5F10BLG, R5F10BME, R5F10BMF, R5F10BMG |

| | |
|-----|--|
| F14 | R5F10PAD, R5F10PAE, R5F10PBD, R5F10PBE, R5F10PGD, R5F10PGE, R5F10PGF, R5F10PGG, R5F10PGH, R5F10PGJ, R5F10PLE, R5F10PLF, R5F10PLG, R5F10PLH, R5F10PLJ, R5F10PME, R5F10PMF, R5F10PMG, R5F10PMH, R5F10PMJ, R5F10PPE, R5F10PPF, R5F10PPG, R5F10PPH, R5F10PPJ |
| F1A | R5F114GC, R5F114GD, R5F114GE, R5F114GF, R5F114GG |
| G10 | R5F10Y14, R5F10Y16, R5F10Y17, R5F10Y44, R5F10Y46, R5F10Y47 |
| G12 | R5F10266, R5F10267, R5F10268, R5F10269, R5F1026A, R5F10277, R5F10278, R5F10279, R5F1027A, R5F102A7, R5F102A8, R5F102A9, R5F102AA, R5F10366, R5F10367, R5F10368, R5F10369, R5F1036A, R5F10377, R5F10378, R5F10379, R5F1037A, R5F103A7, R5F103A8, R5F103A9, R5F103AA |
| G13 | R5F1006A, R5F1006C, R5F1006D, R5F1006E, R5F1007A, R5F1007C, R5F1007D, R5F1007E, R5F1008A, R5F1008C, R5F1008D, R5F1008E, R5F100AA, R5F100AC, R5F100AD, R5F100AE, R5F100AF, R5F100AG, R5F100BA, R5F100BC, R5F100BD, R5F100BE, R5F100BF, R5F100BG, R5F100CA, R5F100CC, R5F100CD, R5F100CE, R5F100CF, R5F100CG, R5F100EA, R5F100EC, R5F100ED, R5F100EE, R5F100EF, R5F100EG, R5F100EH, R5F100FA, R5F100FC, R5F100FD, R5F100FE, R5F100FF, R5F100FG, R5F100FH, R5F100FJ, R5F100FK, R5F100FL, R5F100GA, R5F100GD, R5F100GE, R5F100GF, R5F100GG, R5F100GH, R5F100GJ, R5F100GK, R5F100GL, R5F100JC, R5F100JD, R5F100JE, R5F100JF, R5F100JG, R5F100JH, R5F100JJ, R5F100JK, R5F100JL, R5F100LC, R5F100LD, R5F100LE, R5F100LF, R5F100LG, R5F100LH, R5F100LJ, R5F100LK, R5F100LL, R5F100MF, R5F100MG, R5F100MH, R5F100MJ, R5F100MK, R5F100ML, R5F100PF, R5F100PG, R5F100PH, R5F100PJ, R5F100PK, R5F100PL, R5F100SH, R5F100SJ, R5F100SK, R5F100SL, R5F1016A, R5F1016C, R5F1016D, R5F1016E, R5F1017A, R5F1017C, R5F1017D, R5F1017E, R5F1018A, R5F1018C, R5F1018D, R5F1018E, R5F101AA, R5F101AC, R5F101AD, R5F101AE, R5F101AF, R5F101AG, R5F101BA, R5F101BC, R5F101BD, R5F101BE, R5F101BF, R5F101BG, R5F101CA, R5F101CC, R5F101CD, R5F101CE, R5F101CF, R5F101CG, R5F101EA, R5F101EC, R5F101ED, R5F101EE, R5F101EF, R5F101EG, R5F101EH, R5F101FA, R5F101FC, R5F101FD, R5F101FE, R5F101FF, R5F101FG, R5F101FH, R5F101FJ, R5F101FK, R5F101FL, R5F101GA, R5F101GC, R5F101GD, R5F101GE, R5F101GF, R5F101GG, R5F101GH, R5F101GJ, R5F101GK, R5F101GL, R5F101JC, R5F101JD, R5F101JE, R5F101JF, R5F101JG, R5F101JH, R5F101JJ, R5F101JK, R5F101JL, R5F101LC, R5F101LD, R5F101LE, R5F101LF, R5F101LG, R5F101LH, R5F101LJ, R5F101LK, R5F101LL, R5F101MF, R5F101MG, R5F101MH, R5F101MJ, R5F101MK, R5F101ML, R5F101PF, R5F101PG, R5F101PH, R5F101PJ, R5F101PK, R5F101PL, R5F101SH, R5F101SJ, R5F101SK, R5F101SL |
| G14 | R5F104AA, R5F104AC, R5F104AD, R5F104AE, R5F104AF, R5F104AG, R5F104BA, R5F104BC, R5F104BD, R5F104BE, R5F104BF, R5F104BG, R5F104CA, R5F104CC, R5F104CD, R5F104CE, R5F104CF, R5F104CG, R5F104EA, R5F104EC, R5F104ED, R5F104EE, R5F104EF, R5F104EG, R5F104EH, R5F104FA, R5F104FC, R5F104FD, R5F104FE, R5F104FF, R5F104FG, R5F104FH, R5F104FJ, R5F104GA, R5F104GC, R5F104GD, R5F104GE, R5F104GF, R5F104GG, R5F104GH, R5F104GJ, R5F104GK, R5F104GL, R5F104JC, R5F104JD, R5F104JE, R5F104JF, R5F104JG, R5F104JH, R5F104JJ, R5F104LC, R5F104LD, R5F104LE, R5F104LF, R5F104LG, R5F104LH, R5F104LJ, R5F104LK, R5F104LL, R5F104MF, R5F104MG, R5F104MH, R5F104MJ, R5F104MK, R5F104ML, R5F104PF, R5F104PG, R5F104PH, R5F104PJ, R5F104PK, R5F104PL |
| G1A | R5F10E8A, R5F10E8C, R5F10E8D, R5F10E8E, R5F10E8A, R5F10EBC, R5F10EBD, R5F10EBE, R5F10EGA, R5F10EGC, R5F10EGD, R5F10EGE, R5F10ELC, R5F10ELD, R5F10ELE |
| G1C | R5F10JBC, R5F10JGC, R5F10KBC, R5F10KGC |
| G1D | R5F11AGG, R5F11AGH, R5F11AGJ |
| G1E | R5F10FLC, R5F10FLD, R5F10FLE, R5F10FMC, R5F10FMD, R5F10FME |
| G1F | R5F11B7C, R5F11B7E, R5F11BBC, R5F11BBE, R5F11BCC, R5F11BCE, R5F11BGC, R5F11BGE, R5F11BLC, R5F11BLE |

| | | |
|----|-----|--|
| | G1G | R5F11EA8, R5F11EAA, R5F11EB8, R5F11EBA, R5F11EF8, R5F11EFA |
| | I1A | R5F1076C, R5F107AC, R5F107AE, R5F107DE |
| | I1B | R5F10MME, R5F10MMG, R5F10MPE, R5F10MPG, R5F11CBC, R5F11CCC |
| | I1D | R5F11768, R5F1176A, R5F11778, R5F1177A, R5F117A8, R5F117AA, R5F117AC, R5F117BA, R5F117BC, R5F117GA, R5F117GC |
| | L12 | R5F10RB8, R5F10RBA, R5F10RBC, R5F10RF8, R5F10RFA, R5F10RFC, R5F10RG8, R5F10RGA, R5F10RGC, R5F10RJ8, R5F10RJA, R5F10RJC, R5F10RLA, R5F10RLC |
| | L13 | R5F10WLA, R5F10WLC, R5F10WLD, R5F10WLE, R5F10WLF, R5F10WLG, R5F10WMA, R5F10WMC, R5F10WMD, R5F10WME, R5F10WMF, R5F10WMG |
| | L1C | R5F110ME, R5F110MF, R5F110MG, R5F110MH, R5F110MJ, R5F110NE, R5F110NF, R5F110NG, R5F110NH, R5F110NJ, R5F110PE, R5F110PF, R5F110PG, R5F110PH, R5F110PJ, R5F111ME, R5F111MF, R5F111MG, R5F111MH, R5F111MJ, R5F111NE, R5F111NF, R5F111NG, R5F111NH, R5F111NJ, R5F111PE, R5F111PF, R5F111PG, R5F111PH, R5F111PJ |
| | 110 | R5F51101, R5F51103, R5F51104, R5F51105, R5F5110H, R5F5110J |
| | 111 | R5F51111, R5F51113, R5F51114, R5F51115, R5F51116, R5F51117, R5F51118, R5F5111J |
| | 113 | R5F51135, R5F51136, R5F51137, R5F51138 |
| | 210 | R5F52103, R5F52104, R5F52105, R5F52106, R5F52107, R5F52108, R5F5210A, R5F5210B |
| | 21A | R5F521A6, R5F521A7, R5F521A8 |
| | 220 | R5F52201, R5F52203, R5F52205, R5F52206 |
| | 230 | R5F52305, R5F52306 |
| | 231 | R5F52315, R5F52316, R5F52317, R5F52318 |
| | 23T | R5F523T3, R5F523T5 |
| | 610 | R5F56104, R5F56106, R5F56107, R5F56108 |
| | 621 | R5F56216, R5F56217, R5F56218 |
| | 62G | R5F562G7, R5F562GA |
| | 62N | R5F562N7, R5F562N8 |
| | 62T | R5F562T6, R5F562T7, R5F562TA |
| | 630 | R5F56307, R5F56308, R5F5630A, R5F5630B, R5F5630D, R5F5630E, R5F56316, R5F56317, R5F56318, R5F5631A, R5F5631B, R5F5631D, R5F5631E, R5F5631F, R5F5631G, R5F5631J, R5F5631K, R5F5631M, R5F5631N, R5F5631P, R5F5631W, R5F5631Y, R5S56310 |
| | 631 | R5F5631MF, R5F5631PF,(Debug Support Only) |
| | 634 | R5F5634B, R5F5634D, R5F5634E R5F5634B_5V, R5F5634D_5V, R5F5634EW, R5F5634E_5V,(Debug Support Only) |
| | 63N | R5F563NA, R5F563NB, R5F563ND, R5F563NE, R5F563NF, R5F563NK, R5F563NW, R5F563NY |
| | 63T | R5F563T4, R5F563T5, R5F563T6, R5F563TB, R5F563TC, R5F563TE R5F563TB_5V, R5F563TC_5V, R5F563TE_5V,(Debug Support Only) |
| | 64M | R5F564MF, R5F564MG, R5F564MJ, R5F564ML |
| | 71M | R5F571MF, R5F571MG, R5F571MJ, R5F571ML |
| RX | | |

| | | |
|----|---------------|--|
| | | R7S72100, R7S721001, R7S72101, R7S72102 |
| | A1 | R7S721001_DualSPI, R7S721020, R7S721020_DualSPI, R7S721021, R7S721021_DualSPI,(Debug Support Only) |
| RZ | | R7S910001, R7S910002, R7S910006, R7S910007, R7S910011, R7S910013, R7S910015, R7S910016, R7S910017, R7S910018, R7S910101, R7S910102, R7S910106, R7S910107, R7S910111, R7S910113, R7S910115, R7S910116, R7S910117, R7S910118 |
| | T1 | R7S910015_M3, R7S910016_M3, R7S910017_M3, R7S910018_M3, R7S910115_M3, R7S910116_M3, R7S910117_M3, R7S910118_M3,(Debug Support Only) |
| | | CUSTOM_DEVICE_1, SH-2A_C_1C3A_3, SH-2A_C_1C3A_4, SH-2A_C_1C3A_5, SH-2A_C_1C3A_6, SH-2A_C_1C3A_F, SH-2_CUSTOM_MCU, SH2A_CUSTOM_MCU1, SH2A_CUSTOM_SOC_1, SH2A_CUSTOM_SOC_2, SH2A_CUSTOM_SOC_3, SH2A_CUSTOM_SOC_4, SH2A_CUSTOM_SOC_5, SH70835A, SH70835R, SH70845A, SH70845R, SH70855A, SH70855R, SH70865R, SH71243, SH71253, SH71464R, SH71494A, SH71494R, SH7214, SH72145AD, SH72145BD, SH72146AD, SH72146BD, SH72147AD, SH72147BD, SH7215, SH72165BD, SH72166AD, SH72166BD, SH72167AD, SH72167AD_Option, SH72167BD, SH72265, SH72266, SH72267, SH72275, SH72276, SH72277, SH72314L, SH72315A, SH72315L, SH72374A, SH72374B, SH72375B, SH72394A, SH72395A, SH72395B, SH72531, SH72531FCC, SH72531RFCC, SH72533, SH72533FCC, SH72543R, SH72544R, SH72546R, SH72612, SH7261_FPULess, SH72621, SH72622, SH72623, SH72624, SH72625, SH72626, SH72627, SH72631, SH72632, SH72633, SH72641, SH72642, SH72643, SH72644, SH72645, SH72646, SH72647, SH72660, SH72661, SH72662, SH72663, SH72670, SH72671, SH72672, SH72673, SH72680, SH72681, SH72691, SH7606, SH7618A, SH7671, SH7672, SH7673,(Debug Support Only) |
| SH | | |
| | SH2 | SH7047F, SH70834A, SH70844A, SH70854A, SH70865A, SH71242, SH71252, SH7144F, SH7145F, SH71464A, SH71491R, SH7615, SH7616, SH7618, SH7619 |
| | SH2A-FPU | SH72394B |
| | SH2a | SH7201, SH7203, SH72165AD, SH72546RFCC, SH72611, SH72620, SH72630, SH72640, SH72690, SH7670 |
| | SH2a (No FPU) | SH7206, SH7211, SH7243, SH7285, SH7286 |

2. Code Generator Support

| CPU | Family | Devices |
|------|--------|--|
| RL78 | F12 | R5F10968, R5F1096A, R5F1096B, R5F1096C, R5F1096D, R5F1096E, R5F109AA, R5F109AB, R5F109AC, R5F109AD, R5F109AE, R5F109BA, R5F109BB, R5F109BC, R5F109BD, R5F109BE, R5F109GA, R5F109GB, R5F109GC, R5F109GD, R5F109GE, R5F109LA, R5F109LB, R5F109LC, R5F109LD, R5F109LE |
| | F13 | R5F10A6A, R5F10A6C, R5F10A6D, R5F10A6E, R5F10AAA, R5F10AAC, R5F10AAD, R5F10AAE, R5F10ABA, R5F10ABC, R5F10ABD, R5F10ABE, R5F10AGA, R5F10AGC, R5F10AGD, R5F10AGE, R5F10AGF, R5F10AGG, R5F10ALC, R5F10ALD, R5F10ALE, R5F10ALF, R5F10ALG, R5F10AME, R5F10AMF, R5F10AMG, R5F10BAC, R5F10BAD, R5F10BAE, R5F10BAF, R5F10BAG, R5F10BBC, R5F10BBD, R5F10BBE, R5F10BBF, R5F10BBG, R5F10BGC, R5F10BGD, R5F10BGE, R5F10BGF, R5F10BGG, R5F10BLC, R5F10BLD, R5F10BLE, R5F10BLF, R5F10BLG, R5F10BME, R5F10BMF, R5F10BMG |
| | F14 | R5F10PAD, R5F10PAE, R5F10PBD, R5F10PBE, R5F10PGD, R5F10PGE, R5F10PGF, R5F10PGG, R5F10PGH, R5F10PGJ, R5F10PLE, R5F10PLF, R5F10PLG, R5F10PLH, R5F10PLJ, R5F10PME, R5F10PMF, R5F10PMG, R5F10PMH, R5F10PMJ, R5F10PPE, R5F10PPF, R5F10PPG, R5F10PPH, R5F10PPJ |
| | G10 | R5F10Y14, R5F10Y16, R5F10Y17, R5F10Y44, R5F10Y46, R5F10Y47 |
| | G12 | R5F10266, R5F10267, R5F10268, R5F10269, R5F1026A, R5F10277, R5F10278, R5F10279, R5F1027A, R5F102A7, R5F102A8, R5F102A9, R5F102AA, R5F10366, R5F10367, R5F10368, R5F10369, R5F1036A, R5F10377, R5F10378, R5F10379, R5F1037A, R5F103A7, R5F103A8, R5F103A9, R5F103AA |
| | G13 | R5F1006A, R5F1006C, R5F1006D, R5F1006E, R5F1007A, R5F1007C, R5F1007D, R5F1007E, R5F1008A, R5F1008C, R5F1008D, R5F1008E, R5F100AA, R5F100AC, R5F100AD, R5F100AE, R5F100AF, R5F100AG, R5F100BA, R5F100BC, R5F100BD, R5F100BE, R5F100BF, R5F100BG, R5F100CA, R5F100CC, R5F100CD, R5F100CE, R5F100CF, R5F100CG, R5F100EA, R5F100EC, R5F100ED, R5F100EE, R5F100EF, R5F100EG, R5F100EH, R5F100FA, R5F100FC, R5F100FD, R5F100FE, R5F100FF, R5F100FG, R5F100FH, R5F100FJ, R5F100FK, R5F100FL, R5F100GA, R5F100GC, R5F100GD, R5F100GE, R5F100GF, R5F100GG, R5F100GH, R5F100GJ, R5F100GK, R5F100GL, R5F100JC, R5F100JD, R5F100JE, R5F100JF, R5F100JG, R5F100JH, R5F100JJ, R5F100JK, R5F100JL, R5F100LC, R5F100LD, R5F100LE, R5F100LF, R5F100LG, R5F100LH, R5F100LJ, R5F100LK, R5F100LL, R5F100MF, R5F100MG, R5F100MH, R5F100MJ, R5F100MK, R5F100ML, R5F100PF, R5F100PG, R5F100PH, R5F100PJ, R5F100PK, R5F100PL, R5F100SH, R5F100SJ, R5F100SK, R5F100SL, R5F1016A, R5F1016C, R5F1016D, R5F1016E, R5F1017A, R5F1017C, R5F1017D, R5F1017E, R5F1018A, R5F1018C, R5F1018D, R5F1018E, R5F101AA, R5F101AC, R5F101AD, R5F101AE, R5F101AF, R5F101AG, R5F101BA, R5F101BC, R5F101BD, R5F101BE, R5F101BF, R5F101BG, R5F101CA, R5F101CC, R5F101CD, R5F101CE, R5F101CF, R5F101CG, R5F101EA, R5F101EC, R5F101ED, R5F101EE, R5F101EF, R5F101EG, R5F101EH, R5F101FA, R5F101FC, R5F101FD, R5F101FE, R5F101FF, R5F101FG, R5F101FH, R5F101FJ, R5F101FK, R5F101FL, R5F101GA, R5F101GC, R5F101GD, R5F101GE, R5F101GF, R5F101GG, R5F101GH, R5F101GJ, R5F101GK, R5F101GL, R5F101JC, R5F101JD, R5F101JE, R5F101JF, R5F101JG, R5F101JH, R5F101JJ, R5F101JK, R5F101JL, R5F101LC, R5F101LD, R5F101LE, R5F101LF, R5F101LG, R5F101LH, R5F101LJ, R5F101LK, R5F101LL, R5F101MF, R5F101MG, R5F101MH, R5F101MJ, R5F101MK, R5F101ML, R5F101PF, R5F101PG, R5F101PH, R5F101PJ, R5F101PK, R5F101PL, R5F101SH, R5F101SJ, R5F101SK, R5F101SL |

| | | |
|----|-----|--|
| | G14 | R5F104AA, R5F104AC, R5F104AD, R5F104AE, R5F104AF, R5F104AG, R5F104BA, R5F104BC, R5F104BD, R5F104BE, R5F104BF, R5F104BG, R5F104CA, R5F104CC, R5F104CD, R5F104CE, R5F104CF, R5F104CG, R5F104EA, R5F104EC, R5F104ED, R5F104EE, R5F104EF, R5F104EG, R5F104EH, R5F104FA, R5F104FC, R5F104FD, R5F104FE, R5F104FF, R5F104FG, R5F104FH, R5F104FJ, R5F104GA, R5F104GC, R5F104GD, R5F104GE, R5F104GF, R5F104GG, R5F104GH, R5F104GJ, R5F104GK, R5F104GL, R5F104JC, R5F104JD, R5F104JE, R5F104JF, R5F104JG, R5F104JH, R5F104JJ, R5F104LC, R5F104LD, R5F104LE, R5F104LF, R5F104LG, R5F104LH, R5F104LJ, R5F104LK, R5F104LL, R5F104MF, R5F104MG, R5F104MH, R5F104MJ, R5F104MK, R5F104ML, R5F104PF, R5F104PG, R5F104PH, R5F104PJ, R5F104PK, R5F104PL |
| | G1A | R5F10E8A, R5F10E8C, R5F10E8D, R5F10E8E, R5F10E8A, R5F10E8C, R5F10EBD, R5F10EBE, R5F10EGA, R5F10EGC, R5F10EGD, R5F10EGE, R5F10ELC, R5F10ELD, R5F10ELE |
| | G1C | R5F10JBC, R5F10JGC, R5F10KBC, R5F10KGC |
| | G1D | R5F11AGG, R5F11AGH, R5F11AGJ |
| | G1E | R5F10FLC, R5F10FLD, R5F10FLE, R5F10FMC, R5F10FMD, R5F10FME |
| | G1F | R5F11B7C, R5F11B7E, R5F11BBC, R5F11BBE, R5F11BCC, R5F11BCE, R5F11BGC, R5F11BGE, R5F11BLC, R5F11BLE |
| | G1G | R5F11EA8, R5F11EAA, R5F11EB8, R5F11EBA, R5F11EF8, R5F11EFA |
| | I1A | R5F1076C, R5F107AC, R5F107AE, R5F107DE |
| | I1B | R5F10MME, R5F10MMG, R5F10MPE, R5F10MPG |
| | I1D | R5F11768, R5F1176A, R5F11778, R5F1177A, R5F117A8, R5F117AA, R5F117AC, R5F117BA, R5F117BC, R5F117GA, R5F117GC |
| | L12 | R5F10RB8, R5F10RBA, R5F10RBC, R5F10RF8, R5F10RFA, R5F10RFC, R5F10RG8, R5F10RGA, R5F10RGC, R5F10RJ8, R5F10RJA, R5F10RJC, R5F10RLA, R5F10RLC |
| | L13 | R5F10WLA, R5F10WLC, R5F10WLD, R5F10WLE, R5F10WLF, R5F10WLG, R5F10WMA, R5F10WMC, R5F10WMD, R5F10WME, R5F10WMF, R5F10WVG |
| | L1C | R5F110ME, R5F110MF, R5F110MG, R5F110MH, R5F110MJ, R5F110PE, R5F110PF, R5F110PG, R5F110PH, R5F110PJ, R5F111ME, R5F111MF, R5F111MG, R5F111MH, R5F111MJ, R5F111PE, R5F111PF, R5F111PG, R5F111PH, R5F111PJ |
| RX | 110 | R5F51101, R5F51103, R5F51104, R5F51105, R5F5110H, R5F5110J |
| | 111 | R5F51111, R5F51113, R5F51114, R5F51115, R5F51116, R5F51117, R5F51118, R5F5111J |
| | 113 | R5F51135, R5F51136, R5F51137, R5F51138 |
| | 230 | R5F52305, R5F52306 |
| | 231 | R5F52315, R5F52316, R5F52317, R5F52318 |
| | 23T | R5F523T3, R5F523T5 |
| | 64M | R5F564MF, R5F564MG, R5F564MJ, R5F564ML |
| | 71M | R5F571MF, R5F571MG, R5F571MJ, R5F571ML |
| RZ | T1 | R7S910001, R7S910002, R7S910006, R7S910007, R7S910011, R7S910013, R7S910015, R7S910016, R7S910017, R7S910018, R7S910101, R7S910102, R7S910106, R7S910107, R7S910111, R7S910113, R7S910115, R7S910116, R7S910117, R7S910118 |

3. Current Smart Manual support



Smart manual support is delivered independently of e² studio releases when available. The following devices are available as of the 22nd of July, 2015:


- RX62G
- RX62T
- RX63N
- RX63T
- RX64M
- RX71M
- RX110
- RX111
- RX113
- RX210
- RX220
- RX631

4. What is new in 4.0.2?


| Component | Description |
|-------------------|--|
| RX Device support | RX device support updated. New groups: RX231, RX230 |
| Code Generator | New support added for: RL78/G1D RX231 RX230 |

5. What is new in 4.0.1?


| Component | Description |
|--------------------------|---|
| <p>Debugger</p> | <p>e² studio 4.0.1 has support for the new Renesas E2 Lite emulator.</p> <p>This is available by selecting the “E2 Lite (RX)” selection in the Debug hardware drop list in the Debug Configurations dialog.</p>  |
| <p>Device Support</p> | <p>New RX device support added and updated.</p> <p>New group: RX23T, RX634.</p> |
| <p>Language Support</p> | <p>Traditional Chinese support added for CDT menus.</p> |
| <p>Breakpoint</p> | <p>Improved breakpoint setting dialog added to the breakpoints plugin to allow source line breakpoints to be added to a file not currently open.</p> |
| <p>Project Generator</p> | <p>When adding FIT modules via the project generator it is now easier to find the RX driver package module (RDP) in the FIT module download dialog.</p> <p>Show RX Driver Package Only (Unchecked)</p>  <p>Show RX Driver Package Only (Checked)</p> |



6. What is new in 4.0.0?

| Component | Description |
|------------------------|---|
| Application | <p>e² studio 4.0 has updated Eclipse version to Luna SR2.</p> <p>In addition CDT was updated to 8.6.</p> <p>For a list of added features see below:</p> <p>http://wiki.eclipse.org/CDT/User/NewIn85</p> <p>http://wiki.eclipse.org/CDT/User/NewIn86</p> |
| Installer | <p>A new installer has been developed for e² studio 4.0. It enables some improvements :</p> <ul style="list-style-type: none"> • You can download an installer capable of delivering full product and associated installers for tool chains, etc. in a single install operation. • You can download just the support for the device you want to use, reducing the download time. • The download and installation time has been reduced. |
| Debugger | <p>Stepping performance has been improved by around 20% across all debugger families.</p> |
| CCRL Toolchain support | <p>The new Renesas CCRL toolchain is now supported. This toolchain is used to build code for the RL78 device family.</p>  |
| ARM Debugging | <p>For the ARM Segger J-link debugger we now pass GDB run commands also at reset. This ensures the target board is automatically re-configured after the reset is issued.</p> |
| RZ | <p>Support for the RZ/T1 has been added to e² studio.</p> |
| Debugging | <p>Real-time memory has been enhanced to allow shorter memory update intervals and better user feedback if the refresh interval is overflowing. E.g. A memory fetch cannot be performed in the user requested time interval.</p> |
| Multicore Debugging | <p>e² studio 3.1 supported synchronous multicore debugging for RH850. In version 4.0 asynchronous multicore debugging has also been implemented.</p> |


This is available for configuration on the RH850 debug configuration dialog:



FIT plugin


Improvements have been made to the FIT plugin and also the project generator to integrate the FIT system more effectively within e² studio. The FIT configurator has also been developed to enhance usability. This can be opened by Renesas Views->e2 solution toolkit->FIT Configurator.

Now it is possible to create a FIT project from within the project generator in e² studio.



This page also dynamically links to the Renesas website to download suitable modules for use in the project.

The FIT plugin has also been enhanced to provide a more user friendly experience to the user.




The FIT configurator has improved features which were missing from the FIT plugin such as:

- Adding dependent libraries automatically to the project that the FIT modules need.
- When adding a new FIT module, if dependent FIT modules are required you are informed.
- A “user” selection has been added to the target board selection control. When this is used the r_bsp module is not added to the project.
- Depending on the target board selection the FIT configurator automatically modifies the code to ensure the correct “platform.h” definition.
- When the r_bsp is selected the correct target board files are automatically copied by the plugin.

Smart Browser

The smart browser has been enhanced. This release of the tool can import sample source code when downloaded from the Renesas website via the Smart Browser user interface.

In addition there are improved filtering options to reduce the scope of the smart browser search results:



Optimization Assistant

The optimization assistant has been improved in e² studio 4.0. It now provides the following features in addition to those implement in 3.1.

- When using non-Renesas toolchains, clicking Create Configuration shows the manage configurations dialog.
- Stack size entry now provided on the dialog.

Application



A new “Show View” menu has been added to e² studio. This enables quick and easy access to the Renesas views.

Partner RTOS

Partner OS plugin has been updated to support the Smalight OS and ThreadX.

ARM Debugging

Semi-hosting has been implemented for the ARM debugger so that printf commands can be output in the Renesas Debug Virtual Console.

| <p>Waveform plugin</p> | <p>In e² studio 4.0 we have added the function to save the data to wav format file. This allows users to check the sound stored in memory in an external package to make sure it is correct.</p> <p>We have also added the function to read the data from wav format file and display the data.</p>  <p>The waveform plugin can also play audio directly from the waveform view.</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|------------------------|---|---------|---------------|-------------|---------------|-------------|-------------|-------|----|-------|--|-----------|-----------|-----|---|----|-------|--|-----------|-----------|-----|---|-----|--------------------|--|-----------|-----------|---|---|-----|------|--|-----------|-----------|---|---|-----|--------------------|--|-----------|-----------|---|---|-----|------|--|-----------|-----------|---|---|---|--------------------|--|-----------|-----------|------|---|---|------|--|-----------|-----------|---|---|-----------|---------|--|-----------|-----------|----|---|-----|----------|--|------------|------------|---|---|-----|----------|--|------------|------------|---|---|---|----------|--|------------|------------|----|---|
| <p>Map view plugin</p> | <p>The memory usage plugin will be used to get the map file from the project. This will list out the total memory size, usage of ROM and RAM and detailed information of sections, objects and symbols used in the project.</p>  <table border="1"> <thead> <tr> <th>Section</th> <th>Object</th> <th>Symbol</th> <th>Start address</th> <th>End address</th> <th>Size (byte)</th> <th>Align</th> </tr> </thead> <tbody> <tr> <td>SU</td> <td>Stack</td> <td></td> <td>0x0000004</td> <td>0x0000103</td> <td>256</td> <td>4</td> </tr> <tr> <td>SI</td> <td>Stack</td> <td></td> <td>0x0000104</td> <td>0x0000403</td> <td>768</td> <td>4</td> </tr> <tr> <td>B_1</td> <td>Uninitialized Data</td> <td></td> <td>0x0000404</td> <td>0x0000404</td> <td>0</td> <td>1</td> </tr> <tr> <td>R_1</td> <td>Data</td> <td></td> <td>0x0000404</td> <td>0x0000404</td> <td>0</td> <td>1</td> </tr> <tr> <td>B_2</td> <td>Uninitialized Data</td> <td></td> <td>0x0000404</td> <td>0x0000404</td> <td>0</td> <td>1</td> </tr> <tr> <td>R_2</td> <td>Data</td> <td></td> <td>0x0000404</td> <td>0x0000404</td> <td>0</td> <td>1</td> </tr> <tr> <td>B</td> <td>Uninitialized Data</td> <td></td> <td>0x0000404</td> <td>0x0000803</td> <td>1024</td> <td>4</td> </tr> <tr> <td>R</td> <td>Data</td> <td></td> <td>0x0000804</td> <td>0x0000807</td> <td>4</td> <td>4</td> </tr> <tr> <td>PResetPRG</td> <td>Program</td> <td></td> <td>0xFFE8000</td> <td>0xFFE8030</td> <td>49</td> <td>1</td> </tr> <tr> <td>C_1</td> <td>Constant</td> <td></td> <td>0xFFE80031</td> <td>0xFFE80031</td> <td>0</td> <td>1</td> </tr> <tr> <td>C_2</td> <td>Constant</td> <td></td> <td>0xFFE80031</td> <td>0xFFE80031</td> <td>0</td> <td>1</td> </tr> <tr> <td>C</td> <td>Constant</td> <td></td> <td>0xFFE80034</td> <td>0xFFE80067</td> <td>52</td> <td>4</td> </tr> </tbody> </table> | Section | Object | Symbol | Start address | End address | Size (byte) | Align | SU | Stack | | 0x0000004 | 0x0000103 | 256 | 4 | SI | Stack | | 0x0000104 | 0x0000403 | 768 | 4 | B_1 | Uninitialized Data | | 0x0000404 | 0x0000404 | 0 | 1 | R_1 | Data | | 0x0000404 | 0x0000404 | 0 | 1 | B_2 | Uninitialized Data | | 0x0000404 | 0x0000404 | 0 | 1 | R_2 | Data | | 0x0000404 | 0x0000404 | 0 | 1 | B | Uninitialized Data | | 0x0000404 | 0x0000803 | 1024 | 4 | R | Data | | 0x0000804 | 0x0000807 | 4 | 4 | PResetPRG | Program | | 0xFFE8000 | 0xFFE8030 | 49 | 1 | C_1 | Constant | | 0xFFE80031 | 0xFFE80031 | 0 | 1 | C_2 | Constant | | 0xFFE80031 | 0xFFE80031 | 0 | 1 | C | Constant | | 0xFFE80034 | 0xFFE80067 | 52 | 4 |
| Section | Object | Symbol | Start address | End address | Size (byte) | Align | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SU | Stack | | 0x0000004 | 0x0000103 | 256 | 4 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SI | Stack | | 0x0000104 | 0x0000403 | 768 | 4 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| B_1 | Uninitialized Data | | 0x0000404 | 0x0000404 | 0 | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| R_1 | Data | | 0x0000404 | 0x0000404 | 0 | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| B_2 | Uninitialized Data | | 0x0000404 | 0x0000404 | 0 | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| R_2 | Data | | 0x0000404 | 0x0000404 | 0 | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| B | Uninitialized Data | | 0x0000404 | 0x0000803 | 1024 | 4 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| R | Data | | 0x0000804 | 0x0000807 | 4 | 4 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| PResetPRG | Program | | 0xFFE8000 | 0xFFE8030 | 49 | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C_1 | Constant | | 0xFFE80031 | 0xFFE80031 | 0 | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C_2 | Constant | | 0xFFE80031 | 0xFFE80031 | 0 | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C | Constant | | 0xFFE80034 | 0xFFE80067 | 52 | 4 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

7. Useful workarounds and information for 4.0

| ID | Component | Workaround or information |
|------|----------------|--|
| | Application | <p>This version of e² studio is based on Eclipse Luna SR2 and CDT 8.6. This release note does not describe the Eclipse framework and CDT plugin issues and fixes. You can find the detailed information on the sites below:</p> <p>For information on the Luna release see here: https://projects.eclipse.org/releases/luna http://archive.eclipse.org/eclipse/downloads/drops4/R-4.4-201406061215/news/</p> <p>CDT: https://wiki.eclipse.org/CDT/User/NewIn86</p> <p>The Eclipse bug tracker is here: https://bugs.eclipse.org/bugs/</p> <p>The bug list for Luna is available using the following query: https://bugs.eclipse.org/bugs/buglist.cgi?bug_status=RESOLVED&bug_status=VERIFIED&bug_status=CLOSED&classification=Eclipse&list_id=12238007&product=Platform&query_format=advanced&resolution=FIXED&target_milestone=4.4&target_milestone=4.4%20M1&target_milestone=4.4%20M2&target_milestone=4.4%20M3&target_milestone=4.4%20M4&target_milestone=4.4%20M5&target_milestone=4.4%20M6&target_milestone=4.4%20M7&target_milestone=4.4%20RC1&target_milestone=4.4%20RC2&target_milestone=4.4%20RC3&target_milestone=4.4%20RC4&target_milestone=4.4.1&target_milestone=4.4.2</p> <p>Bug List for CDT is: https://bugs.eclipse.org/bugs/buglist.cgi?bug_status=RESOLVED&bug_status=VERIFIED&bug_status=CLOSED&classification=Tools&list_id=12238014&product=CDT&query_format=advanced&resolution=FIXED&target_milestone=8.5&target_milestone=8.6.0</p> |
| 5954 | Application | <p>If you experience the error message “org.eclipse.swt.SWTError: No more handles” this can be caused by certain multi-monitor software and the Eclipse framework.</p> <p>If this error occurs there are 2 workarounds:</p> <ol style="list-style-type: none"> 1. Use a single monitor display. 2. Uninstall the multiple monitor software from your graphics chipset vendor and revert to the standard Windows multi-monitor feature. |
| 6981 | RL78 Debugging | <p>When debugging IAR C source file with an OCD emulator (E1), the Monitor program area (0x00002-0x00003) is used.</p> <p>So this area must be excluded from usable address space. Please add '-HFF' in the linker option.</p> <ul style="list-style-type: none"> - Open Property. - Select [C/C++ build]-[Settings] at left side. - Select 'IAR RL78 Xlink linker' at right side, add '-HFF' at the textbox 'command'. |

| | | |
|------|----------------------|---|
| | | Not doing this will cause problems with connection and download when using interrupts. |
| NA | ARM Debugging | In e ² studio 4.0.1 the RZ/T1 Cortex M3 core is now supported for debugging only. Cortex M3 projects are not available in the project generator so start-up code can only be created for the RZ Cortex R4F core. |
| NA | Application | <p>If you are experiencing slow building of projects within e² studio there are some possibilities to improve.</p> <p>The system environment will attempt to find the make.exe tool via the system environment. If you ensure the directory make resides in is at the start of the path variable it will find it more quickly. Especially important if there are network drives in the path.</p> <p>In the project properties, C/C++ Build tab, behavior tab you can switch on parallel build. This will take advantage of the multi-cores on your host machine if it has them. In e² studio 2.1 or later this now defaults to on for new projects.</p> |
| NA | RZ GCC | <p>In 3.0 the KPIT GCC RZ toolchain was support at version 14.01. This version is no longer supported within e² studio.</p> <p>KPIT have modified the name of their ARM toolchain to be ARM-none-eabi to follow standard ARM naming convention like other GCC toolchain vendors.</p> <p>The toolchain is available at version 14.01 and 14.02 from the KPIT website. The binaries in the 14.01 version is identical to that used in the 14.01 RZ toolchain.</p> <p>Once the toolchain is installed your projects will be imported and ported to ensure there is as little disruption as possible due to this change.</p> |
| NA | GCC Build Plugin | The GNU toolchain linker file format was changed in 3.0. This means projects that are developed in 3.0 or later and opened in 2.x will still continue to build. However you may experience issues visiting the GCC Linker Sections user interface. |
| 5041 | Code Generator | <p>Code Generator can delete user code between /* Start */ End comments in some situations.</p> <p>Using the code generator if the following code is placed in the main function: <pre>//if(data_in!=0xAA){</pre> On a line by itself, all of the main code will be removed when Generate Code button is pressed.</p> <p>The key issue is that the {brace is on the same line as the comment.</p> |
| 2010 | HEW Importer | <p>Symptoms: Project fails to build after import from HEW</p> <p>Conditions: If a long filename or path is used, and the HEW project importer is used, the project may fail to build.</p> <p>Workaround: Move the original HEW project to a shallow directory structure (i.e.) C:\Workspace and import from there. Also ensure that the HEW project is relocated before importing into e² studio.</p> |
| 2421 | Debug Configurations | <p>Debug configurations have been modified since e² studio 2.x. So although you can re-use the workspace and projects from e² studio 1.x when you open the debug launch configuration for the first time it is updated.</p> <p>Before doing this you should back-up the .launch file if you need to keep a 1.x version.</p> |

| | | |
|------|---------------------|---|
| NA | Application | It is not possible to import e ² studio 1.x projects which are for the V850 device into e ² studio 2.0. |
| 1922 | Application | <p>Symptoms: Project fails to build in first instance after archive project import (not from HEW)</p> <p>Conditions: If an archived project is imported it may fail to build the first time, due to a residual .d file.</p> <p>Workaround: Clean and Build a second time.</p> |
| 2762 | CODAN | <p>When using assembly code within a C source file, Codan errors can be observed in the editor. Even though the project builds successfully.</p> <p>We do not have a workaround for this at this time.</p> <p>On occasion you may also see this for C source files. This is normally a case of the indexer needing to be refreshed.</p> <p>Right click on the project, select Index->Freshen all files. Then right click again select Index-Rebuild. This should solve unexpected CODAN errors in C source files.</p> |
| 2728 | GDB | <p>Step into does not always work when using the CCRX 1.02.01 toolchain.</p> <p>To ensure this behaves correctly you will need to use CCRX 2.00.00 or greater as this issue with the debug information is corrected in this release.</p> |
| NA | Eventpoints | If eventpoints do not always work just after they are set, you can use the "Apply to Target" toolbar button in the Eventpoint view to send the Eventpoints to the target manually. This will always ensure the debugger target has all the required eventpoint updates before execution starts. |
| 5772 | IAR Plugins | <p>The IAR Plugin Manager is now included in e² studio. This provides support for RX, RL78, RH850 and RZ (ARM).</p> <p>This is a tool which simplifies installation and configuration of IAR toolchain plugins. You can access this through Help -> IAR Embedded Workbench plugin manager.</p> |
| 5903 | Code Generator | <p>For the following RL78 code generator project, "Peripheral Functions" view tabs may not be operated with double-clicking "Peripheral Functions" branch of Project Explorer view.</p> <p>After creating/loading the project, please show "Code Preview" view by double-clicking of "Code preview" branch at Project Explorer tree at first. Then, please access Code Generator setting tabs by double-clicking Project Explorer tree or using pull-down menu by pressing triangle button at the up-right corner of Peripheral Functions view.</p> <p>RL78/G12, RL78/G13, RL78/G14, RL78/G1A, RL78/I1A, RL78/F13, RL78/F14, RL78/F12, RL78/L12</p> |
| 6184 | RL78/CCRL debugging | <p>When the load module for RL78/G10 which created at CC-RL is debugged in E1, please specify the following option:</p> <p>[Linker] -> [Device] -> "Set enable/disable on-chip debug by link option</p> |

| | | |
|------|--------------------------|---|
| 5995 | CCRX to GNU RX Converter | When converting from CCRX to GCC projects some comments like <code>/** comment */</code> are left intact which will result in an error if standard is set to C89. Changing the standard to C99 or above will fix this problem. |
| 6800 | RZ/T1 Project Generation | The program which is downloaded to RAM and executes in the RAM does not work well. e2 studio only supports the program which is downloaded to NOR flash or serial flash with the standard generated project. |
| | RZ/T1 Debugging | The Segger J-Link emulator executes the boot program prepared for RZ/T1 before downloading your user program. This means that your user program will need to be downloaded twice by disconnecting and re-connecting the e2 studio debugger, if the parameters for the loader area were changed or not written correctly on board. |
| 6798 | RZ/T1 Debugging | On RZ/T1 devices the CPSR register is shown endian reversed. |
| 7217 | Application | The restore default settings does not restore all of the options set during project generation. Instead it sets the defaults to the base settings for the device family in use. |

8. Fixed issues in 4.0.2.8

| ID | Component | Description |
|------|----------------|---|
| 7293 | RL78 GCC Build | When RL78/G1D project is generated, it does not add "-mg13" option for it. RL78/G1D is S2 core device. |
| 7260 | Application | When deselecting the e ² studio update site from the update site list and closing e ² studio. The update site is removed. This should not happen and should remain available but unchecked. |
| 7208 | Code Generator | <p>Code Generator for RX231, RX230</p> <ol style="list-style-type: none"> RX231 and RX230 devices more than 100pin have Open Drain setting for PORT J. But, Code Generator doesn't support Open Drain item on PORT GUI. If necessary, please add ODR0 register setting code manually. RX230 devices have the following pins. But, Code Generator doesn't support items for them. PORT H cannot be set as I/O port and other multiplexed pin function. PH0/CACREF, PH1/IRQ0/TMO0, PH2/IRQ1/TMRI0, PH3/TMCI0. PinView (Pin List, Top View) is not supported about the following RX231 devices. 48pin: R5F52315CxNE, R5F52316CxNE, R5F52315CxFL, R5F52316CxFL 64pin: R5F52315CxND, R5F52316CxND, R5F52315CxFM, R5F52316CxFM, R5F52315CxLF, R5F52316CxLF 100pin: R5F52315CxLA, R5F52316CxLA, R5F52315CxFP, R5F52316CxFP At RX231 and RX230. When MTU2 is used with Complementary PWM Mode n, build error occurs because of no macro definition. Please modify the code. File: R_MTU2_Create(), r_cg_mtu2.c; Error line: MTU3.TCNT = xxxxxxx; Modified code: please set the same value for MTU.TDDR register. e.g.) original code: MTU3.TCNT = _00A0_3TCNT_VALUE; // error ... MTU.TDDR = _00A0_TDDR_VALUE; modified code: MTU3.TCNT = _00A0_TDDR_VALUE; ... MTU.TDDR = _00A0_TDDR_VALUE; |
| 7289 | RX GCC Build | When RX23T GNURX project is generated, compiler option "-nofpu" is set and "-mcpu=rx64m" is not set. |

9. Fixed issues in 4.0.1.7

| ID | Component | Description |
|------|-----------------------|--|
| 5394 | CCRX Build plugin | <p>""Problem""</p> <p>If a source file folder (already included in C option) is deleted, its path was added to Assemble include.</p> <p>""Workaround""</p> <p>Remove the path in "include file directories" will stop the warning.</p> |
| 5826 | GDB Server RZ | Using Move to Line with an RZ target can cause the GUI to stop responding. Set the PC directly via the Registers window instead. |
| 6470 | Performance Analysis | <p>To acquire the 64 bit value in Performance Analysis View for RX, the following steps will be required:</p> <ul style="list-style-type: none"> - Start with both timers enabled and all settings the same - Enabled "link timers" for Timer1. - Timer1 and Timer2 are now linked and the 64bit counter is being used. |
| 6531 | CCRL Build plugin | <p>In some cases CCRL code is not seen as source code and you cannot set breakpoints on the source line.</p> <p>The issue is the indexer does not understand the "near" keyword and treats it as a syntax error.</p> |
| 6678 | GDB server | <p>Removing a previously set breakpoint by double clicking the Line Breakpoint marker at the side of the editor, sometimes does not remove the breakpoint.</p> <p>Disconnecting and re-connecting the debugger does resolve the issue.</p> |
| 6757 | Application | <p>CCRX to GNURX: Project Build fails after conversion for RX64M and RX71M targets.</p> <p>User will need to delete the un-used .fvectors and .exvectors sections from the converted projects for targets RX64M and RX71M.</p> <p>The RESETVECT and EXCEPTVECT sections are being used in the application instead of .fvectors and .exvectors.</p> |
| 6798 | Application | On RZ/T1 devices the CPSR register is shown endian reversed |
| 6814 | Device Support RX | <p>New RX device support added and updated.</p> <p>New group: RX23T, RX634</p> |
| 6853 | Application | Creating breakpoints from the Eclipse breakpoint dialog now possible for C/C++ source lines. |
| 6906 | CodeGenerator plugin | New code generator support for RL78/G1F and RX23T. |
| 6915 | RL78 GCC build plugin | RL78 G10 start-up code incorrect. The HL register used in the BSS initialization routine is not initialized properly. Due to incorrect bank selected while loading the start address of .bss section. |
| 6936 | Application | <p>When downloading an IAR project the 0x2 and 0x3 memory areas which are reserved for the on-chip debugger are not protected. In previous versions of e2 studio the debugger would write FF to these values. However this is not correct operation.</p> <p>The side effect for IAR is that this can cause the download to fail when interrupts are enabled.</p> <p>One workaround is to add the -HFF option into IAR RL78 XLink command to set 0xFF for unused address(including 0x03-0x03). Once added this then enables the connection/download to succeed.</p> |
| 6981 | Application | When debugging IAR C source file with an OCD emulator (E1), the Monitor program area (0x000002-0x000003) is used. |

| | | |
|------|----------------------|--|
| | | <p>So this area must be excluded from usable address space. Please add '-HFF' in the linker option.</p> <ul style="list-style-type: none"> - Open Property. - Select [C/C++ build]-[Settings] at left side. - Select 'IAR RL78 Xlink linker' at right side, add '-HFF' at the textbox 'command'. |
| 6987 | Installer | e2 studio Integration Service and the CCRX to GNU converter are not present when e2 studio 4.0.0 is installed using the installer. |
| 6994 | Application | Traditional Chinese language pack support added to the e2 studio installer. |
| 7013 | CCRX Build plugin | The linkage order cannot be changed for CCRX projects when they contain more than one virtual folder. |
| 7071 | CodeGenerator plugin | <p>If "debug" is enabled in the RL78 GCC code generator, a linker overlap error is generated during build.</p> <p>Please comment out the following code to avoid build error and E1 emulator download error. The following code is unnecessary.)</p> <pre>in r_cg_vector_table.c #define OCDRAM_SECT attribute ((section (".ocd_ram"))) uint8_t Ocd_Ram[512] OCDRAM_SECT;</pre> |
| 7079 | CodeGenerator plugin | <p>When Trace function is used at Code Generator GUI, Code Generator adds 'ocd_traceram' section to linker section. However, the address of section is wrong, it causes the download error to E1 emulator. Please change the address of section 'ocd_traceram' at property after code generation.</p> <p>Target device: RL78/I1D, R5F117xC (x = A, B, G)</p> <p>Wrong address: 0xFE300</p> <p>Correct address: 0xFF700</p> |
| 7086 | Application | <p>During code generator the linker section options are modified. However when the user presses build the linker script file is not re-generated.</p> <p>There is still a limitation in that although the file is re-generated the build is not marked as dirty. So please clean and the rebuild the project.</p> |
| 7098 | Integration Server | Help plugins were not installed when certain components were not selected in the installation procedure. |

10. Open issues in 4.0.2.8

| ID | Component | Description |
|------|---------------------|--|
| 7103 | CCRX Build plugin | <p>""Problem""</p> <p>If two or more source file folder (already included in C option) are deleted, its path was added to Assemble include.</p> <p>""Workaround""</p> <p>Remove the path in "include file directories" will stop the warning.</p> |
| 7101 | Application | <p>When using the RL78 GCC toolchain with a debug configuration for the simulator problems can occur with building once the code has been generated for the first time.</p> <p>r178-elf-ld: section .option_bytes loaded at [000000c0,000000c3] overlaps section .text loaded at [00000080,0000029b]</p> |
| 7097 | Debug Configuration | <p>Large projects may timeout when connecting for the first time. A reconnection will succeed. This can be seen with RZ projects in some situations.</p> |
| 7095 | Application | <p>CCRX to GNURX conversion fails for per file build settings in assembly source files.</p> |
| 7092 | Application | <p>When using the GNU ARM toolchain the project build fails when 'Dwarf3' option is selected.</p> |
| 7072 | GDB Server RZ | <p>When CM3 debugging is started and expand register view to see "misc" register, "_ReadRegIfNecessary(): Register 32 is not marked as valid" error is shown.</p> |
| 7057 | Application | <p>When adding an event point to an external source code file. (File added using "Link to file in the file system" option). There can be problems adding the event point in this case.</p> |
| 7011 | Project Generation | <p>In some cases the file list displayed in "Project Summary" dialog of the project generator does not match the actually generated files.</p> |
| 7005 | Application | <p>Debugging with the RL78 GDB simulator with the IAR project generators is not straight forward.</p> <p>The default IAR debug configuration uses the GDB executable name "GDB".</p> <p>This launch will not work and you need to point it at "r178-elf-gdb.exe" included in the e2 studio debugcomp directory.</p> <p>However if you have not launched a Renesas debug configuration it won't be present. On the first launch of a Renesas debug configuration for RL78 the file is uncompressed from the package zip file.</p> <p>So to work around you need to launch a RL78 E1 session first so the GDB application for RL78 exists.</p> |
| 6998 | GDB Server RZ | <p>Reload on RZ/T does not work well. Modify code on RZ/T project. Build. The code is download but not executed</p> <p>The old code is executed. Press reset button on the hardware and modified code is executed correctly.</p> |
| 6953 | GDB Server SH | <p>For SH2a-FPU devices the register view may show incorrect values for the SR register and the MACHL register</p> |
| 6859 | CDT | <p>In some cases after reload symbols are not being updated correctly. Appears to be related to caching with CDT. GDB symbol information is correctly updated, and expressions which directly access fields in structures updated correctly, but overall structures are not correct.</p> |

| | | |
|------|----------------------|--|
| 6852 | Project Generation | <p>The combination of "C++ project" and "CC-RL" toolchain can be selected.</p> <p>But, "CC-RL" toolchain does not support "C++ project".</p> <p>So, do not select the combination of "C++ project" and "CC-RL" toolchain.</p> |
| 6770 | Trace plugin | <p>Loading saved trace data in the trace view when using the RZ/A1 device does not work and shows an error.</p> |
| 6741 | CodeGenerator plugin | <p>Code Generator registration needs the administrator privileges. Please start e2 studio once after the installation using an admin account, before using Code Generator on the PC.</p> |
| 6731 | CodeGenerator plugin | <p>When changing the "On-chip debug setting" to "Used" for GNU RL78 devices, after clicking Generate code the linker change is not immediately reflected in the build.</p> <p>The .ocd_ram section is not added until the user opens the linker settings and clicks Apply.</p> <p>In some cases this causes a build failure.</p> |
| 6705 | GDB Server RZ | <p>Automatically selecting a connected JLink debugger from the debug configuration does not work correctly. The user is still required to manually select from the JLink dialog.</p> |
| 6704 | Application | <p>For RZ/T1 target a user can select Profile View. When selecting button 'Turn Profiling On' this is allowed to be enabled although this is not supported.</p> |
| 6701 | GDB server | <p>For RX devices, when 'step' command is invoked for WAIT instruction, GDB might report an error.</p> <p>Please use 'resume' command for WAIT instruction instead.</p> |
| 6696 | CodeGenerator plugin | <p>"Problem"</p> <p>When the configuration which generated code is changed into a different configuration, a build error occurs.</p> <p>"Workaround"</p> <p>Please change the address of "FIXEDVECT" section into 0xFFFFFDD0.</p> |
| 6685 | Installer | <p>The modify feature for standalone installer does not remember proxy settings.</p> |
| 6676 | Application | <p>The "Renesas GDB Hardware Attach" causes a NullPointerException. This results in this feature not being usable.</p> |
| 6674 | CodeGenerator plugin | <p>Code Generator doesn't have the property to change the encoding (character code).</p> <p>Code Generator loads/saves the generated source file according to the default encoding of Windows.</p> <p>Therefore, when the comment with the different encoding from the Windows default one is added into the generated file by Code generator, it is not properly encoded and it cannot be displayed properly at the editor.</p> |
| 6657 | Coverage plugin | <p>If the workspace is copied or moved from the original folder, coverage information may not be displayed.</p> <p>Please re-build the program in the new workspace.</p> |
| 6616 | Event points plugin | <p>When adding a new Data Access eventpoint, the Compare value (on the Data Access Settings tab) is always converted to hex and subsequently displayed in hex even if the value entered does not include an 0x prefix.</p> |

| | | |
|------|------------------------|--|
| 6605 | Event points plugin | <p>The enable state of eventpoints for any debug configuration is not restored when the debug configuration is launched for the first time after e2 studio is started.</p> <p>In subsequent launches the eventpoints are enabled/disabled appropriately.</p> |
| 6594 | Static Analysis plugin | <p>1.</p> <p>Due to the optimization of the compiler, the static function is not sometimes indicated in Static Analysis View.</p> <p>In this case, please select "Debug Precedence" in "Level of optimization".</p> <p>2.</p> <p>The label indication of static function is different between CC-RX and CC-RL.</p> <p>This difference is due to CCRL and CCRL Compiler spec.</p> <p><Example></p> <pre>static int function01(int a) {...}</pre> <p>CC-RX: function01</p> <p>CC-RL: fucntion01@1</p> <p>In case of CC-RL, "@1" string is added to the function label.</p> |
| 6566 | Real-time Watch | In some situations the RH850 multicore real-time expression update does not work. |
| 6557 | GDB Server RH850 | Breakpoints are not always being cleared completely when a breakpoint is removed. |
| 6549 | Profile plugin | The Profile View 'Execution Time' and 'Average Execution Time' columns are showing as zero after suspending the current debug session (for all targets). |
| 6545 | Profile plugin | No profile data is displayed in the profile view for GNUSH or SHC projects. |
| 6529 | CDT | After restart on occasion the disassembly window can be empty. Refreshing the window or stepping works around the problem. |
| 6525 | Trace plugin | The Trace View does not show disassembly when tracing through code in a memory area not in the download module. |
| 6484 | Application | Additional build tabs contributed by other third party tools can be hidden by e2 studio. This is caused by Renesas/KPIT build plugins replacing the standard build settings page with a custom one. |
| 6463 | Application | Memory view requires manual refresh to see changes when downloading auxiliary file. |
| 6450 | Application | When "Prevent debugger from re-writing on-chip Program ROM" is checked and "Force Hardware Breakpoints" is set to No setting breakpoint fails and the program will not execute. |
| 6408 | Application | <p>When User boot mode is selected at the setting for Mode pin in CPU Operating Mode, the warning for USB boot program is displayed even if the device does not have USB boot program.</p> <p>Please click 'yes' if the device does not have USB boot program.</p> |
| 6394 | GDB server RX | Trace Record event point does not filter correctly with Segger RX63N. |

| | | |
|------|----------------------|---|
| 6350 | Application | <p>NullPointerException is observed when adding a custom configuration and selecting the same configuration within the "Multiple Configuration" selection at the same time.</p> <p>This issue only occurs if user has not applied after creating new config: https://bugs.eclipse.org/bugs/show_bug.cgi?id=352047</p> |
| 6336 | Application | <p>Start / Stop Function Settings are sent once on connecting. If the address for start function or stop function is changed by building the program, please disconnect from target and reconnect again.</p> |
| 6208 | Application | <p>When debugging with RX there are problems with setting breakpoints when the hardware breakpoint resources have been exhausted and the software breakpoint setting also fails.</p> <p>In this case the breakpoint appears to be valid but the debugger will not stop.</p> <p>This can often be seen when the option "Program re-writes internal Data Flash" is set to yes. As this means software breakpoints cannot be set.</p> |
| 5911 | DS-5 importer | <p>The current DS-5 importer in e2 studio imports KPIT GNU "Application" project types only. Other projects cannot be imported at this time.</p> |
| 5903 | CodeGenerator plugin | <p>For the following RL78 code generator project, "Peripheral Functions" view tabs may not be operated with double-clicking "Peripheral Functions" branch of Project Explorer view.</p> <p>After creating/loading the project, please show "Code Preview" view by double-clicking of "Code preview" branch at Project Explorer tree at first. Then, please access Code Generator setting tabs by double-clicking Project Explorer tree or using pull-down menu by pressing triangle button at the up-right corner of Peripheral Functions view.</p> <p>RL78/G12, RL78/G13, RL78/G14, RL78/G1A, RL78/I1A, RL78/F13, RL78/F14, RL78/F12, RL78/L12</p> |
| 5778 | Debug Configuration | <p>When importing a project and debugging before visiting the debug configuration the debug connection will fail.</p> <p>Visiting the debug configuration or creating a new project uncompressed the support files. Once this has happened debug connection can continue as normal.</p> |
| 5770 | Application | <p>RX targets and IO registers greater than 1 byte.</p> <p>e.g.</p> <p>winA 0x88028</p> <p>winB 0x8802a</p> <p>View register in both IO view and register view.</p> <p>Value in memory view is reversed.</p> <p>This is because the IO, (like all RX memory for little endian targets is reversed).</p> |
| 5721 | CDT | <p>When modifying code that changes the line an already set breakpoint is located at the breakpoint is not moved according to the modification.</p> |
| 5669 | Application | <p>An invisible breakpoint is left in the project following a 'Move To Line' operation. Program execution continues to halt at this location once the Move to Line operation has been performed.</p> |

| | | |
|------|------------------------------|---|
| 5668 | Coverage plugin | In some cases when using the Coverage facility with the RL78 IECUBE some lines are shown as 'branch' or partial coverage when they should be 100% covered. |
| 5637 | Multicore | For RH850 multicore devices, disassembly result may be different from the expected. In this case, please refresh the view after changing the debug context to the other PE. |
| 5632 | Multicore | When using multicore projects the Debug View may show an incorrect name for the second loaded module (as a duplicate of the first) |
| 5551 | Application | If the maximum number of break points are used for RX with E1/E20 emulator, the connection or the program execution may fail. In this case, please reduce the using break points. |
| 5547 | Application | To use the data access events as trace start, trace stop or trace record for RH850 with E1 emulator, please do not use the "Compare Settings" condition for the event. |
| 5530 | Application | Indexer settings are not persisted on a project import into e2 studio. |
| 5467 | Memory View plugin | Settings in the 'Format' dialog (Memory view) are not restored. |
| 5290 | CCRX Build plugin | When you add a new configuration, please do not specify 'Default Configuration' as a configuration used as a base. If you specify the 'Default Configuration', the configuration which does not operate correctly is created. |
| 5201 | Application | If you create a project and debug session for a GDB simulator before executing a hardware debug session it will fail. This is because the debugger support is not unpacked until a hardware debug session is used. To work around setup and launch a hardware debug session. You do not actually need hardware to do this. |
| 5179 | CubeSuite+ importer/exporter | When CubeSuite+ project imports to e2 studio, Build cannot perform sometimes. [Workaround] Please add the <root folder> to "C/C++ General -> Paths and Symbol -> Source Location" |
| 5171 | CCRX Build plugin | Files included in the Pre-include build options are not analyzed for the pre-processor statement in the editor. This can give the impression that code is not included in the build when it is. |
| 5124 | Application | Active configuration lost while importing project (which is exported as file system). |
| 5110 | GDB | For some RX devices the default display of PSW the IPL is displayed wrong. The MSB is not shown. |
| 5083 | CubeSuite+ importer/exporter | Folder level options are not converted correctly |
| 5063 | Application | Dependency scanning is not working for assembler file. This is for GCC build plugins. |
| 5056 | GDB server RX | Timestamp setting on the Trace view has no effect on results for Profile view for RX devices. |

| | | |
|------|------------------------------|---|
| 5041 | CodeGenerator plugin | Code Generator can delete user code between /* Start */ End comments in some situations. Using the code generator if the following code is placed in the main function: <pre>//if(data_in!=0xAA){</pre> on a line by itself, all of the main code will be removed when Generate Code button is pressed. The key issue is that the { brace is on the same line as the comment. |
| 4876 | Application | When debugging with RX, if the settings are in flash write mode, the debugger features should be disabled. |
| 4869 | Memory View plugin | The "Memory" view always opened on launch of a debug session. It should not be re-opened on launch if it has been closed in the previous debug session. |
| 4819 | CCRX Build plugin | Individual compile is not execute when Level2 is specified at the "Perform inter-module optimization". |
| 4783 | Performance Analysis | The option to Reset timer before each run, which is setup on the "Performance Analysis" dialog box is not reflected for RL78. The specification for RL78 is that the values are reset all of the time so the option has no meaning. |
| 4607 | GDB server | When sub menu "Add Watchpoint" is performed from a Memory view, it seems to have been registered correctly in the Breakpoints view even if there is an error condition. An error occurs by "Add Watchpoint", when the maximum number of events was exceeded, or when a ROM area is specified. |
| 4597 | Application | In some cases when a before PC eventpoint is set just after a break point, the program execution will not stop at the address the eventpoint is located at. |
| 4515 | CCRX Build plugin | When building projects with CCRX that are in deep directory structures it is possible to experience build issues. e2 studio is unable to build projects which create command lines greater than 8191 characters. |
| 4492 | Application | The Module View of e2 studio does not display any information when an executable which includes debug information was downloaded to the target. |
| 4450 | CCRX Build plugin | Linker section settings of Renesas toolchain are not getting saved for multiple configurations. |
| 4422 | Application | When debugging a project that has been imported but that has not been rebuilt you need to setup the debugger to look in the original source file location. This is done via the Source tab of the Debug Configurations dialog. |
| 4350 | CubeSuite+ importer/exporter | When importing a project from CubeSuite+ to e2 studio the "toolchain version is changed" dialog is always displayed. This is because the version string in imported project file and the toolchain information in e2 studio does not match. Ignoring this dialog and continuing should result in a successful import. |
| 4314 | GDB Server SH | For the SH debugger the Debug Tool Settings -> Use User Stack option is not processed by the debugger. The setting is not used. |

| | | |
|------|-----------------------|--|
| 4303 | RL78 GCC build plugin | <p>When the project has a toolchain that does not match the path for the toolchain installed on the machine problems with build can occur.</p> <p>Workaround is to delete the 'org.eclipse.cdt.core.prefs' file from .settings folder and then import the project.</p> <p>Alternatively you can modify the toolchain path from Properties > C/C++ Build > Environment. Modifying the toolchain path builds the project successfully.</p> |
| 4191 | GDB server RX | <p>When using Segger JLink, with the "Force Hardware Breakpoints" debug option enabled, adding more than the maximum amount of breakpoints for a device and then removing some can lead to none of the breakpoints firing. Workaround is to add a single breakpoint back in to trigger the reapply of all others.</p> |
| 4189 | Project Generation | <p>It is not possible to build project which has more than 98 characters in its project name.</p> |
| 4105 | Application | <p>When using GCC on Japanese Windows. If you create a new workspace on the desktop the default GCC projects fail to build correctly.</p> |
| 4104 | Application | <p>When the project is re-named. If the user then uses the feature project > Build Configurations > Build All. The active configuration builds successfully but subsequent configurations fail.</p> |
| 3992 | Application | <p>When importing projects from HEW into e2 studio when the files are read only, build errors occur following import. Ensure the files are writable.</p> |
| 3950 | Application | <p>Breakpoints cannot be unset within the editor when code is #ifdef out.</p> <p>These breakpoints will need to be removed from the breakpoints plugin.</p> |
| 3945 | Application | <p>When importing a HEW project if it contains folders with the same name at the same hierarchy then not all the files will import successfully.</p> <p>i.e.</p> <p>"...\\WorkSpace\\WorkSpace\\Developments\\src\\embOS\\Util\\MEASUREMENT.c"</p> <p>"...\\WorkSpace\\WorkSpace\\Developments\\src\\protocols\\util\\SerialUtil.c"</p> |
| 3928 | CCRX Build plugin | <p>By default the e2 studio editor character code is set to UTF-8. This means it is possible to enter characters that are then not supported by default by the CCRX toolchain.</p> <p>CCRX default input is SJIS.</p> <p>To enable UTF-8 for the toolchain you must first select C99 support.</p> |
| 3836 | Application | <p>Dependencies with file name that have spaces may cause dependency scanning issues. Where possible it is better to avoid using spaces in dependency file names.</p> |
| 3813 | Event points plugin | <p>OA event break event points not breaking at correct addresses on SH7203 (External Flash) target.</p> |
| 3804 | Application | <p>The code generator is not automatically registered when installing into generic Eclipse. Browse to the CG plugin and then run the batch files that reside in the tools directory.</p> <p>e.g.</p> |

| | | |
|------|----------------------|---|
| | | C:\Renesas\e2_studio\eclipse\plugins\com.renesas.cg_1.0.0.201309061659\CodeGenerator\Tools |
| 3663 | Application | <p>With 2 targets connected, clicking between the two debug contexts in the Debug View will update the source addresses in the open Editor files.</p> <p>However changing debug context does not seem to get detected if clicking on the top-level of the debug context rather than on the lower level.</p> |
| 3626 | Trace plugin | Snapshot trace - adding IO register eventpoints increases the data shown in the trace view, but as they were removed there was no change in the data shown. |
| 3585 | Application | The GDB server crashes when an E1 emulator is connected to a debug configuration configured for the Segger emulator. |
| 3550 | Application | Custom placeholders are not expanded when importing a project from HEW. This is currently expected behaviour but may be improved in a future version. |
| 3526 | Profile plugin | In some cases when using RX with the CCRX compiler the profile view does not display the source file name and path in the window. |
| 3470 | Application | When debugging with the RX210 the FPSW register is displayed on the register view. This should not be the case as the RX210 does not have the FPSW register. |
| 3389 | Application | When debugging files with the same name show source addresses even though it may not be correct for the file in question. The full file path is not considered just the filename and current debug context. This can lead to e2 studio showing addresses unnecessarily. |
| 2910 | GDB | Registers do not display properly on SH2A 72691. |
| 2859 | CDT | When using IAR projects the SFR names (e.g. PIOR1_bit.no1) are not understood correctly in the editor. |
| 2762 | Application | When using assembly code within a C source file, Codan errors can be observed in the editor. Even though the project builds successfully. |
| 2716 | GDB server RL78 | Before PC events on IECube temporarily hard coded limit of 4. |
| 2693 | Application | <p>HEW Importer, output file (.P/.PP) is not generated while building the project.</p> <p>Workaround: User will need to select Settings -> Compiler -> Object -> output file type -> Preprocessed source file -> OK after importing the project and then build the project.</p> |
| 2537 | Performance Analysis | <p>Performance Analysis: Performance time is not updating following changes to start and stop performance addresses.</p> <p>For the G13 IECube it supports one run/break timer. Currently e2 studio is setting the support to 3.</p> |
| 2486 | Profile plugin | Acquiring profile results can take a very long time following RX Simulator debugging. |
| 2416 | Project Generation | <p>Use of duplicate register is allowed for RXC project generation.</p> <ol style="list-style-type: none"> 1. Create RXC project 2. Go to RXC Global option page, select "ROM" -> "R8" 3. Select the same value for any other register (e.g. "RAM" -> "R8"), it gives error message and prevents the user from project creation. |

| | | |
|------|-----------------------|--|
| | | 4. Now select "R8" again for "RAM" register. It doesn't show any error message and allows user to create the project. |
| 2299 | RX GCC build plugin | It is possible for .c and .C files to be treated in the same manner in certain situations which is not correct. (.C extension is changed to .c during project build). |
| 2081 | Application | After building a project if user changes anything in linker subcommand file option, only ObjCopy is gets invoked. Linker should get invoked. |
| 2010 | HEW Project Converter | HEW Project Import fails to build file due to File or path name too long. This is due to the difference between HEW and Eclipse. In HEW object files are output to the configuration directory. In Eclipse the files are output alongside the source file in the same directory. |
| 1982 | RX GCC build plugin | For Renesas CCRX the Converter phase gets invoked even when using the external linker subcommand option. This should not happen. |
| 1950 | HEW Project Converter | A user tries to import a already imported project (in a different workspace) again. However the project is deleted from the previous workspace. This results in the following error message "The selected .hwp file overlaps the location of another project". See attached dialog. This is because when the project is removed from the project tree the Eclipse projects are not physically removed. Deleting the Eclipse project files from the directory allows the operation to continue. |
| 1889 | Application | Due to file extension issue with .s and .S and due to known bug, e2studio users wont be able to use .s or .S effectively to pre-process assembly files that need GCC. Hence we suggest renaming these files to use: .S -> .asm .s -> .src |
| 1859 | GDB server | Program execution stops inside a range when Range Exclusive is specified in the address settings for OA event points. |
| 1808 | HEW Project Converter | Import a HEW RX project in e2studio using the HEW project importer. Check: Project > Properties > Compiler > Source > Include file directories. Paths are duplicated |
| 1778 | Application | When setting the 'Internal Flash Memory Overwrite' debug option, it is possible to exceed the maximum number of non-continuous memory blocks supported. No warning is given if this limit is exceeded. When setting this option ensure the limit (16 for RX devices) is not exceeded. |
| 1645 | Event points plugin | For the SH7216 target (and most likely other targets), when using the address conditions and associated mask, the boolean parameter (parameter 17) 'address mask compare type' is not being set to true. |

| | | |
|------|---------------------|---|
| 1642 | Application | <p>Erase flash on startup option on RL78 should be executed once.</p> <p>When e2studio connects successfully to RL78 target and erases the flash, this option should return to false, so that flashing is not done everytime target is connected.</p> |
| 1640 | Application | <p>After creation a project cannot be deleted straight away. If the user waits around 30 seconds the project can then be deleted.</p> |
| 1616 | RX GCC build plugin | <p>The options of a Build Configuration were not correct after specifying Multiple Configurations... functionality.</p> |
| 1486 | Application | <p>Breakpoint properties do not work when set in the CDT dialogs. For example using the filter operation and removing the breakpoint for the process being debugged.</p> |
| 987 | Application | <p>Exporting project if linker sections are modified and not saved generates an error. Resource not synchronized is the message.</p> |
| 874 | Event points plugin | <p>Execution Address Eventpoints with trigger count do not work with Breakpoints on Segger RX.</p> <p>Setting an execution address eventpoint with a trigger count on Segger JLink RX62N is not possible if any breakpoints exist, including the default at main.</p> <p>If an execution address eventpoint with a trigger count is set with a breakpoint both the eventpoint & the breakpoint do not function. Multiple breakpoint are set then only 1 does not work. Additional eventpoints function as normal.</p> |