

Microcomputer Technical Information

CP(K), O

<p style="text-align: center;">IE-78K0K1-ET In-Circuit Emulator for 78K0/KB1, KC1, KD1, KE1, KF1, KB1+, KC1+, KD1+, KE1+, KF1+</p> <p style="text-align: center;">Usage Restrictions</p>		Document No.	ZBG-CD-04-0035	1/2
		Date issued	July 8, 2004	
		Issued by	Development Tool Group Multipurpose Microcomputer Systems Division 3rd Systems Operations Unit NEC Electronics Corporation	
Related documents	IE-78K0K1-ET Preliminary User's Manual: U16604EJ1V0UM00	Notification classification	√	Usage restriction
				Upgrade
				Document modification
				Other notification

1. Affected product

IE-78K0K1-ET

Control code^{Note}: A, B, C

2. Details of restrictions

The bugs No.15 to No.18 have been added. See attachment 1 for details.

3. Workarounds

See attachment 1 for details.

4. Modification schedule

Products in which No.15 to No.18 are modified are scheduled for release as follows.

Newly shipped products: From the shipment at the end of October 2004 (control code: D)

Upgrade for already shipped products: Available from October 2004

Upgrading to control code C is suspended due to bugs No.17 and No.18.

See attachment 2 for details.

* Note that this schedule is subject to change without notice. For the detailed release schedule of modified products, contact an NEC Electronics sales representative.

Note The "control code" is the second digit from the left in the 10-digit serial number in the warranty supplied with the product you purchased. If the product has been upgraded, a label indicating the new version is attached to the product and the x in V-UP LEVEL x on this label indicates the control code.

5. List of restrictions
See attachment 1.

6. Document revision history

IE-78K0K1-ET In-Circuit Emulator for 78K0/KB1, KC1, KD1, KE1, KF1, KB1+, KC1+, KD1+, KE1+, KF1+

Usage Restrictions

Document Number	Issued on	Description
SBG-DT-03-0074-E	February 26, 2003	Addition of bugs (No.1 to No.10)
SBG-DT-04-0114	March 12, 2004	Addition/change of specification (No.11 to No.14)
ZBG-CD-04-0035	July 8, 2004	Addition of bugs (No.15 to No.18) Addition of attachment 2

Notes on Using IE-78K0K1-ET

1. Product Version

Control Code ^{Note}	Remark
A	μPD78F0148GC 2.0
B	μPD78F0148GC 2.1
C	μPD78F0148HGC 1.0

Note The “control code” is the second digit from the left in the 10-digit serial number in the warranty supplied with the product you purchased (if it has not been upgraded). If the product has been upgraded, a label indicating the new version is attached to the product and the x in V-UP LEVEL x on this label indicates the control code.

2. Product History (from this edition, restrictions are no longer a separate item)

No.	Bugs and Changes/Additions to Specifications	Control Code ^{Note}		
		A	B	C
1	The initial value of the SFR PCC differs between the target device and IE system	Permanent restriction		
2	The connection of the RESET pin differs from that in the target device	Permanent restriction		
3	Do not use an accessing method that generates a wait request for the WDTM, ASIS0, ASIS6, ADM, ADS, PFM, PFT, and ADCR registers when operating with the subsystem clock and with the input clock stopped	Permanent restriction		
4	SFRs may not be able to be accessed when operating at a frequency of over 5 MHz and at 3.3 to 4.0 V	×	√	√
5	Transmit data cannot be written to the buffer RAM using the 3-wire serial interface with automatic transfer function (CSIA0) of the target device 78K0/KF1	×	√	√
6	The values of the RESF, LVIM, and LVIS registers are initialized by applying a reset from the target system even if RESET is masked	Permanent restriction		
7	The values of the RESF, LVIM, and LVIS registers are not initialized by the CPU reset button of the integrated debugger ID78K0-NS	Permanent restriction		
8	Some restrictions apply if Break (peripheral functions stopped) is specified as Peripheral Break in the Configuration dialog box of the integrated debugger ID78K0-NS	Permanent restriction		
9	The long-type emulation probe for 80-pin package cannot be used	×	√	√
10	An internal reset may not be generated by the watchdog timer	×	√	√
11	The integrated debugger may not start when it is restarted	×	×	√
12	Some 78K0/Kx1+ functions are now supported [Addition of specification]	–	–	√
13	Restrictions on using 78K0/Kx1+	Permanent restriction		
14	Bug related to RINGMSK operation during HALT	×	×	×
15	Bug related to reset	×	×	×
16	Bug related to STOP mode	×	×	×
17	Bug related to conflict between write to SFR in which a wait occurs and interrupt	√	√	×
18	Bug related to conflict between SFR access and interrupt	√	√	×

×: Restriction applies

√: Restriction does not apply or already corrected

–: Specification not supported

3. Details of Bugs and Additions to Specifications

No.1 The initial value of the SFR PCC differs between the target device and IE system.

[Description]

The initial value of the SFR PCC differs between the target device and IE system.

Target device: 00H IE system: 04H

[Workaround]

Set 00H when the target device is started or reset.

Regard this as a permanent restriction.

No.2 The connection of the $\overline{\text{RESET}}$ pin differs from that in the target device.

[Description]

The connection of the $\overline{\text{RESET}}$ pin differs from that in the target device.

Target device: Without pull-up IE system: 4.7 k Ω pull-up in the IE system

[Workaround]

There is no workaround. Regard this as a permanent restriction.

No.3 Do not use an accessing method that generates a wait request for the WDTM, ASIS0, ASIS6, ADM, ADS, PFM, PFT, and ADCR registers when operating with the subsystem clock and with the input clock stopped

[Description]

Do not use an accessing method that generates a wait request for the WDTM, ASIS0, ASIS6, ADM, ADS, PFM, PFT, and ADCR registers when operating with the subsystem clock and with the input clock stopped.

[Workaround]

LED2 (RETRY) that indicates the wait (retry) status stays lit in the IE system, the integrated debugger ID78K0-NS hangs up. Apply a reset by using either of the following methods to restore from the hang-up status.

- Reset applied from a circuit on the target device
- Internal reset by comparing the power supply voltage of the POC circuit and detection voltage
- Internal reset by comparing the power supply voltage of the low-voltage detector (LVI) and detection voltage
- Clock monitor reset by pressing emulation switch SW2 on the clock monitor

Regard this as a permanent restriction.

No.4 SFRs may not be able to be accessed when operating at a frequency of over 5 MHz and at 3.3 to 4.0 V

[Description]

SFRs may not be able to be accessed when operating at the following frequency and voltage.

Voltage	Frequency
3.3 to 4.0 V	Over 5 MHz

[Workaround]

There is no workaround.

This restriction has been corrected in control code B.

No.5 Transmit data cannot be written to the buffer RAM using the 3-wire serial interface with automatic transfer function (CSIA0) of the target device 78K0/KF1

[Description]

When writing transmit data to the buffer RAM using the 3-wire serial interface with automatic transfer function (CSIA0) of the target device 78K0/KF1, data may not be written correctly depending on the instruction executed after the write instruction (see SBG-DT-0128-E for details).

[Workaround]

See [Workaround] (3) in SBG-DT-0128-E.

This restriction has been corrected in control code B.

No.6 The values of the RESF, LVIM, and LVIS registers are initialized by applying a reset from the target system even if RESET is masked

[Description]

The values of the RESF, LVIM, and LVIS registers are initialized by applying a reset from the target system to the IE system even if RESET is masked in the Configuration dialog box of the integrated debugger ID78K0-NS. (The values of other registers are not initialized.)

[Workaround]

There is no workaround. Regard this as a permanent restriction.

No.7 The values of the RESF, LVIM, and LVIS registers are not initialized by the CPU reset button of the integrated debugger ID78K0-NS.

[Description]

The values of the RESF, LVIM, and LVIS registers are not initialized by the CPU reset button of the integrated debugger ID78K0-NS.

[Workaround]

Initialization can be implemented using the following resets.

<RESF register>

- Reset applied from a circuit on the target device
- Internal reset by comparing the power supply voltage of the POC circuit and detection voltage

<LVIM and LVIS registers>

- Reset applied from a circuit on the target device
- Internal reset by comparing the power supply voltage of the POC circuit and detection voltage
- Clock monitor reset by pressing emulation switch SW2 on the clock monitor
- Reset applied from the watchdog timer

Regard this as a permanent restriction.

No.8 Some restrictions apply if Break (peripheral functions stopped) is specified as Peripheral Break in the Configuration dialog box of the integrated debugger ID78K0-NS

[Description]

(1) Prohibition of write

Do not write data to the TMC00, TMC01, WDTM, ADM, ADS, PFM, and PFT registers in the SFR window and Watch window and the buffer RAM area in the Memory window (there is no problem if data is written by the program.).

(2) Restriction on display

The value of the ADCR register in the SFR window and Watch window is illegal (there is no problem when Non Break is specified. In addition, there is no problem with the read value in the program.)

(3) Restriction on non-real-time execution

Writing to the TMC00, TMC01, WDTM, ADM, ADS, PFM, and PFT registers and the buffer RAM area may not be performed when a non-real-time execution (step-in, next over, or slow motion) is performed.

(4) Restriction on break immediately before/after write operation to I/O register that generates a wait

Writing to the TMC00, TMC01, WDTM, ADM, ADS, PFM, and PFT registers and the buffer RAM area may not be performed normally when a break is set immediately before/after the write operation.

[Workaround]

There is no workaround. Regard this as a permanent restriction.

No.9 The long-type emulation probe for 80-pin package cannot be used

[Description]

The long-type emulation probe for 80-pin package (NP-H80GC-TQ and NP-H80GK-TQ) cannot be used.

[Workaround]

There is no workaround. This restriction has been corrected in control code B.

No.10 An internal reset may not be generated by the watchdog timer

[Description]

An internal reset may not be generated by the watchdog timer.

[Workaround]

There is no workaround. This restriction has been corrected in control code B.

No.11 The integrated debugger may not start when it is restarted

[Description]

The integrated debugger may not start after it is shut down and restarted.

[Workaround]

Be sure to disconnect the power supply to the IE-78K0K1-ET after the integrated debugger is shut down.

This restriction has been corrected in control code C.

No.12 Some 78K0/Kx1+ functions are now supported. [Addition of specification]

[Description]

Some 78K0/Kx1+ functions are now supported in control code C, but restrictions apply.

See No.13 for details.

No.13 Restrictions on using 78K0/Kx1+

[Description]

- (1) Accessing the system control register (VSWC) is not possible. VSWC operates with the initial value 0H.
- (2) An operating voltage lower than 2.5 V is not supported.
 - The POC function of the device generates a POC reset when the voltage becomes 2.1 ± 0.1 V, but the target voltage cannot be set to lower than 2.5 V in the IE-78K0K1-ET. Therefore, the POC reset cannot be emulated in the IE-78K0K1-ET.
 - A detection voltage (VLVI) of 2.35 ± 0.1 V cannot be used for the LVI function. Use a detection voltage of 2.6 ± 0.1 V or higher.
- (3) The self-programming function is not supported.
- (4) The boot swap function is not supported.
- (5) The maximum operating frequency of the device is 16 MHz, but the IE-78K0K1-ET does not support operation at a frequency higher than 12 MHz. Therefore, use the IE-78K0K1-ET with an operating frequency of 12 MHz or lower.
- (6) The option byte function is not supported. Set RINGOSC using the mask option of the debugger.

[Workaround]

There is no workaround. Regard this as a permanent restriction.

No.14 Bug related to RINGMSK operation during HALT

[Description]

The watchdog timer operation does not stop even if NONMSK (Ring-OSC can be stopped by software) is set for the mask option RINGMSK and the HALT instruction is executed, as long as the operation clock to the watchdog timer does not stop. As a result, a reset signal is generated.

[Workaround]

There is no workaround. This bug will be corrected in the next revision.

No.15 Bug related to reset

[Description]

The reset vector may be illegal after a reset.

[Workaround]

There is no workaround. This bug will be corrected in the next revision.

No.16 Bug related to STOP mode

[Description]

When an interrupt occurs in STOP mode, an interrupt flag is set but the interrupt vector may be illegal.

[Workaround]

There is no workaround. This bug will be corrected in the next revision.

No.17 Bug related to conflict between write to SFR in which a wait occurs and interrupt

[Description]

If a conflict occurs between writing to an SFR (TMC00, WDTM, ADM, ADS, PFM, or PFT) in which a wait occurs or writing to the buffer RAM and an interrupt, the interrupt vector may be illegal.

[Workaround]

There is no workaround. This bug will be corrected in the next revision.

No.18 Bug related to conflict between SFR access and interrupt

[Description]

If an interrupt occurs while accessing an SFR related to the functions shown below, the interrupt vector may be illegal. However, this bug does not occur in operation at a frequency of 12 MHz or lower.

Ports (except for 4, 5, and 6), A/D converter, 16-bit timer 0, 8-bit timer, watchdog timer, low-voltage detector, UART0, UART6, CS11, CSIA0, watch timer, key interrupt, and registers for multiplication/division

[Workaround]

There is no workaround. This bug will be corrected in the next revision.

4. Cautions

No.1 LED3 (POC RESET)

[Description]

LED3 (POC RESET) is lit during the reset shown below. Do not perform a break when LED3 is lit; otherwise the integrated debugger ID78K0-NS will hang up.


- Internal reset by comparing the power supply voltage and detection voltage of the POC circuit

No.2 SW6

[Description]

Use SW6 in the default setting (3-side). (SW6 is a switch used for maintenance.)

Package Drawing of Emulation board (S-780148 Board)



No.3 Product information

[Description]

NEC Electronics' Microcomputer website (http://www.necel.com/micro/index_e.html) provides product information, FAQs on development tools, the latest development tools, user's manuals, and a device file download service, etc.

No.4 General cautions on handling this product

a) Cases in which NEC Electronics warranty does not apply

- When the product is disassembled, reconstructed, or modified by the user
- When the product receives a heavy shock such as being dropped or falling down
- When the product is used with excessive voltage or is stored outside the guaranteed
- When power is applied while the AC adapter, interface cable, or target system is not connected securely

- When the AC adapter cable, interface cable, or extension probe is excessively twisted or stretched
- When an AC adapter other than the one supplied with the product is used
- When water is spilled on the product
- When the product and target system are connected in a system in which the voltage potential between the GND of the product and the target system GND differ
- When the connector or cable is connected or disconnected while the power is being applied to the product
- When an excessive load is applied to the connector or socket

b) Cautions on safe use

- The product heats up (to approx. 50 to 60°C) when it operates for a long time. Take care not to receive injuries such as burns from a rise in the temperature.
- Be very careful to avoid electric shocks. There is risk of electric shock if the product is used as described in item a) above.

5. Difference Manual

This section explains changes from control code C and differences from the user's manual.

Target manual: IE-78K0K1-ET In-Circuit Emulator Preliminary User's Manual (document number: U16604E)

(1) Addition of 78K0/KB1+, 78K0/KC1+, 78K0/KD1+, 78K0/KE1+, 78K0/KF1+ to target devices

[Location] Cover, pages 3, 6, 8, 10, and 17

(2) Change of supported low-voltage range from "2.7 V to 5.5 V" to "2.5 V to 5.5 V"

[Location] Page 10

(3) Deletion of SW8

[Location] Pages 13, 14, and 31

(4) Change of description of PD78F0148 to PD78F0148H in figures

[Location] Pages 23 and 29

(5) Change of description "2.0 MHz to 10.0 MHz" to "2.0 MHz to 12.0 MHz"

[Location] Page 24

(6) Addition of multiplication circuit setting

[Location] Page 32

Main System Clock Frequency	SW2	SW3
10 MHz to 12 MHz	1, 6 ON (Other: OFF)	4, 6 ON (Other: OFF)

(7) Deletion of **3.10**

[Location] Page 33

(8) Addition of 78K0/KB1+ to target devices

[Location] Page 35

(9) Addition of 78K0/KC1+ to target devices

[Location] Page 39

(10) Addition of 78K0/KD1+ to target devices

[Location] Page 43

(11) Addition of 78K0/KE1+ to target devices

[Location] Page 47

(12) Addition of 78K0/KF1+ to target devices


[Location] Page 51

(13) Change of emulation CPU from μ PD78F0148 to μ PD78F0148H

[Location] Pages 35 to 37, 39 to 41, 43 to 45, 47 to 49, and 51 to 53

(14) Addition of reset mask circuit

[Location] Pages 37, 41, 45, 49, and 53



(15) Addition of case for 78K0/Kx1+ to mask option settings

[Location] Page 33

(a) When target device is 78K0/Kx1

- Ring-OSC
- POC ON/OFF and detection voltage 2.85 V, 3.5 V
- P60 to P63 (these ports are not provided in the μ PD780101, 780102, 780103, and 78F0103)

Set the mask options in the integrated debugger.

Open the mask option window from [Option] → [Mask Option] and set the mask options.

Refer to the ID78K0-NS Ver.2.52 Integrated Debugger Operation (U16488E) for details.

- | | | |
|--------------|--------|--|
| • RINGMSK | NONMSK | Ring-OSC stop by software enabled
Watchdog timer stop enabled |
| | MSK | Ring-OSC stop by software disabled
Watchdog timer stop disabled |
| • POC | ON | POC function ON |
| | OFF | POC function OFF |
| • POCV | 2.85 V | POC detection voltage 2.85 V |
| | 3.5 V | POC detection voltage 3.5 V |
| • P60 to P63 | ON | Pulled up by the mask option resistor |
| | OFF | No mask option resistor |

(b) When target device is 78K0/Kx1+

- Ring-OSC

Set the mask options in the integrated debugger.

Open the mask option window from [Option] → [Mask Option] and set the mask options.

Refer to the ID78K0-NS Ver.2.52 Integrated Debugger Operation (U16488E) for details.

- | | | |
|-----------|--------|--|
| • RINGMSK | NONMSK | Ring-OSC stop by software enabled
Watchdog timer stop enabled |
| | MSK | Ring-OSC stop by software disabled
Watchdog timer stop disabled |

Caution When emulating the 78K0/Kx1+, “78K0Kx1plus” is displayed in the mask option window, but this does not need to be set.

Handling of IE-78K0K1-ET Until October

NEC Electronics has been accepting applications to upgrade the IE-78K0K1-ET to control code C, but we have found that bugs No.17 and No.18, which are newly reported in this document, also apply to control code C. Therefore, we have decided to suspend upgrading to control code C. Please read the following descriptions for details this decision.

1. Suspension of upgrading to control code C

Applications to upgrade to control code C, reported in the document shown below, will be suspended from July 2004 due to bugs No.17 and No.18.

<Microcontroller Technical Information>

Document name: IE-78K0K1-ET In-Circuit Emulator for 78K0/KB1, KC1, KD1, KE1, KF1 Upgrade

Document number: SBG-DT-04-0115

Date issued: March 12, 2004

In line with this suspension, the application period of upgrade to control code B, reported in the document shown below, will be extended until upgrading to control code D is started.

<Microcontroller Technical Information>

Document name: IE-78K0K1-ET In-Circuit Emulator for 78K0/KB1, KC1, KD1, KE1, KF1 Upgrade

Document number: SBG-DT-03-0075-E

Date issued: February 26, 2003

The schedule for upgrading to control code D will be reported when available.

2. Response to repair requests

NEC Electronics will accept requests for repairing IE-78K0K1-ET control codes A, B, and C. Note, however, that products will be returned as control code B products after repair. Therefore, also note the bugs that apply to control code B.