

Exclusively for design purposes! No part of this may be disclosed to a third party without the consent of NEC Electronics

<b>Concerned Products:</b>  IE-78K0-SL-P01	<b>Customer Notification</b>		Date: November 18, 1998
			NEC-Electronics (Europe) GmbH EAD – Technical Product Support
	<b>Bug Report</b>		Source Doc: SBB-T-8816, SBB-T-8939, SBG-T-0585
			Author: A. Wohlfahrt
Date of initial issue: Nov. 18th, 98	Doc. No.: TPS-LE-B-0T005		
1 <sup>st</sup> revision :	Doc. No.: TPS-LE		
2 <sup>nd</sup> revision :	Doc. No.: TPS-LE		

Exclusively for design purposes! No part of this may be disclosed to a third party without the consent of NEC Electronics

**(A) BUG LIST (1/2)**

Bug No.	Outline	IE-78K0-SL-P01					
		V1.00 Code "A"	V1.01 Code "B"	V1.11 Code "C"	V1.21 Code "D"	V1.21 Code "E"	V1.31 Code "E"
1	AD-converter precision	☞	✓	✓	✓	✓	✓
2	Emulation device assignment	☞☼	☞	✓	✓	✓	✓
3	Reading SFR	☞☼	☞☼	☞	✓	✓	✓
4	Reading FIP RAM	☞☼	☞☼	☞☼	☞	✓	✓
5	Problem on debugger start-up	☞☼	☞☼	☞☼	☞☼	☞	✓
6	Problem on restarting the debugger	☞☼	☞☼	☞☼	☞☼	☞	✓
7	Low voltage operation	☞☼	☞☼	☞☼	☞☼	☞	✓
8	Wait pin	☞☼	☞☼	☞☼	☞☼	☞☼	☞

✓: No problem

☞: Bug (will be corrected by next version upgrade)

☞☼: Bug (restriction, not corrected by version upgrade)

Exclusively for design purposes! No part of this may be disclosed to a third party without the consent of NEC Electronics

**(B) BUG DESCRIPTION**

<b>Bug No.</b>	<b>Outline</b>	<b>Description</b>
1	AD-converter precision	The AD-converter precision is not correct
2	Emulation device assignment	The initial setting of the SFR's is not correctly assigned and the debugger does not start-up correctly
3	Reading SFR	The SFR's at address FF1xh may not be read correctly
4	Reading FIP RAM	The FIP RAM can not be read with the IE-780228-SL-EM1
5	Problem on debugger start-up	When starting the debugger ID78K0 and port 4 is connected to VSS a "Receive timeout" error occurs.
6	Problem on restarting the debugger	After terminating the debugger ID78K0, the restart of the debugger causes a "Receive timeout" error Workaround: After terminating the debugger ID78K0, turn the power supply of before restarting it.
7	Low voltage operation	When the hardware trigger start function of the AD-converter is active, the signal output level is fixed to 5V. This function can not be used at a low voltage operation
8	Wait pin	The Wait pin can not be used as port pin when the external memory access is activated.