

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPD

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
Renesas Technology Corp.

Product Category	User Development Environment		Document No.	TN-EML-A127A/E	Rev.	1.0
Title	Problem with trigger output for on-chip break function		Information Category	Technical Notification		
Applicable Product	H8SX E6000H emulator (V.3.03 Release 00 or earlier): HS1650EPH60H or HS1527KEPH60H	Lot No.	Reference Document	H8SX E6000H Emulator User's Manual (REJ10B0036-0400H Rev.4.00)		
		See the applicable products				

When you use the trigger output ([Output Trigger] option) for the on-chip break function of the H8SX E6000H emulator, the regulation stated below will be applied. Please read this document carefully before use.

[Problem]

Even if the trigger output for the on-chip break function is enabled, no trigger output is possible by satisfaction of a condition.

[Regulation]

For the on-chip break function, the trigger output by satisfaction of a condition cannot be used. If you wish to use the trigger output by satisfaction of a condition, apply [Trace Acquisition Condition Channel] of the trace function instead.