

Customer Notification

V850E/Dx3

32-Bit Single-Chip Microcontrollers

Operating Precautions

μPD70F3421

μPD70F3422

μPD70F3423

μPD70F3424

μPD70F3425

μPD70F3426

μPD70F3427

DISCLAIMER

The related documents in this customer notification may include preliminary versions. However, preliminary versions may not have been marked as such.

The information in this customer notification is current as of its date of publication. The information is subject to change without notice. For actual design-in, refer to the latest publications of NEC's data sheets or data books, etc., for the most up-to-date specifications of NEC PRODUCT(S). Not all PRODUCT(S) and/or types are available in every country. Please check with an NEC sales representative for availability and additional information.

No part of this customer notification may be copied or reproduced in any form or by any means without prior written consent of NEC. NEC assumes no responsibility for any errors that may appear in this customer notification. NEC does not assume any liability for infringement of patents, copyrights or other intellectual property rights of third parties by or arising from the use of NEC PRODUCT(S) listed in this customer notification or any other liability arising from the use of such PRODUCT(S).

No license, express, implied or otherwise, is granted under any patents, copyrights or other intellectual property rights of NEC or others. Descriptions of circuits, software and other related information in this customer notification are provided for illustrative purposes of PRODUCT(S) operation and/or application examples only. The incorporation of these circuits, software and information in the design of customer's equipment shall be done under the full responsibility of customer. NEC assumes no responsibility for any losses incurred by customers or third parties arising from the use of these circuits, software and information.

While wherever feasible, NEC endeavors to enhance the quality, reliability and safe operation of PRODUCT(S) the customer agree and acknowledge that the possibility of defects and/or erroneous thereof cannot be eliminated entirely. To minimize risks of damage to property or injury (including death) to persons arising from defects and/or errors in PRODUCT(S) the customer must incorporate sufficient safety measures in their design, such as redundancy, fire-containment and anti-failure features.

The customer agrees to indemnify NEC against and hold NEC harmless from any and all consequences of any and all claims, suits, actions or demands asserted against NEC made by a third party for damages caused by one or more of the items listed in the enclosed table of content of this customer notification for PRODUCT(S) supplied after the date of publication.

Applicable Law:

The law of the Federal Republic of Germany applies to all information provided by NEC to the Customer under this Operating Precaution document without the possibility of recourse to the Conflicts Law or the law of 5th July 1989 relating to the UN Convention on Contracts for the International Sale of Goods (the Vienna CISG agreement).

Düsseldorf is the court of jurisdiction for all legal disputes arising directly or indirectly from this information. NEC is also entitled to make a claim against the Customer at his general court of jurisdiction.

If the supplied goods/information are subject to German, European and/or North American export controls, the Customer shall comply with the relevant export control regulations in the event that the goods are exported and/or re-exported. If deliveries are exported without payment of duty at the request of the Customer, the Customer accepts liability for any subsequent customs administration claims with respect to NEC.

- Notes:**
1. "NEC" as used in this statement means NEC Electronics Corporation and also includes its direct or indirect owned or controlled subsidiaries.
 2. "PRODUCT(S)" means 'NEC semiconductor products' (NEC semiconductor products means any semiconductor product developed or manufactured by or for NEC) and/or 'TOOLS' (TOOLS means 'hardware and/or software development tools' for NEC semiconductor products' developed, manufactured and supplied by 'NEC' and/or 'hardware and/or software development tools' supplied by NEC but developed and/or manufactured by independent 3rd Party vendors worldwide as their own product or on contract from NEC)

- (A) Table of Operating Precautions 3**
 - (A).1 μ PD70F3421, μ PD70F3422, μ PD70F3423 3**
 - (A).2 μ PD70F3424, μ PD70F3425, μ PD70F3426, μ PD70F3427 5**

- (B) Description of Operating Precautions. 7**

- (C) Valid Specification 24**

- (D) Revision History 25**

(A) Table of Operating Precautions

(A).1 μ PD70F3421, μ PD70F3422, μ PD70F3423

No.	Outline	μ PD70F3421	μ PD70F3422	μ PD70F3423				
		Rev.	1.1	1.1	1.0	1.1		
		Rank ^{Note}	IE	IE		ZE		
No. 1	Flash Memory: Flash memory block operations (Technical limitation)	✓	✓	✗	✓			
No. 2	CPU: RAM mirror access (Specification change notice)	✓	✓	✓	✓			
No. 3	Ports: PDSCn registers mirrors (Specification change notice)	✗	✗	✗	✗			
No. 4	Code Protection and Security: Limitation of flash memory extra area and reset vector reprogramming (Specification change notice)	✓	✓	✗	✓			
No. 5	External Interrupt - Input Filter Timing Port P07/ INTP6: Shortened pulse rejection time	✗	✗	✗	✗			
No. 6	External Interrupt - Input Filter Timing - All external interrupt input channels (except Port P07/ INTP6): Shortened pulse rejection time	✓	✓	✓	✓			
No. 7	AFCAN: Sleep Mode Wakeup (Specification change notice)	✗	✗	✗	✗			
No. 8	On-Chip Debug Unit: Maximum input clock for the Debug Control Unit (DCU) is limited to 10 MHz	✗	✗	✗	✗			
No. 9	On-Chip Debug Unit: Execution of BROM-Startup Code can be unintentionally interrupted at User S/W Breakpoint Addresses	✗	✗	✗	✗			
No. 10	CSIB: CSIB may stop operating	✗	✗	✗	✗			
No. 11	On-Chip Debug Unit: Reconfiguration of N-Wire pins during N-Wire debug mode	✓	✓	✓	✓			
No. 12	Flash Memory: Increased Power Consumption when CPU is operating on the Sub Oscillator Clock	✓	✓	✓	✓			
No. 13	Flash Memory: Increased Power Consumption when CPU is operating on the Sub Oscillator Clock (iRAM operation)	✗	✗	✗	✗			
No. 14	Flash Memory: Flash Access Timing Violation after System Clock (f_{CPU}) Supply Switch	✗	✗	✗	✗			

Operating Precautions for V850E/Dx3

No.	Outline	μPD70F3421	μPD70F3422	μPD70F3423				
		Rev.	1.1	1.1	1.0	1.1		
		Rank ^{Note}	IE	IE		ZE		
No. 15	CPU: HALT instruction (1) (Specification change notice)	✓	✓	✓	✓			
No. 16	CPU: HALT instruction (2) (Specification change notice)	✓	✓	✓	✓			
No. 17	DMA: MLE Bit Usage (Specification change notice)	X	X	X	X			
No. 18	Linear code execution across address 0x00010000 and 0x00008000 when boot sectors are swapped (Direction of use)	✓	✓	✓	✓			

✓ : Not applicable

X : Applicable

Note: The rank is indicated by the letter appearing at the 5th position from the left in the lot number, marked on each product.

(A).2 μ PD70F3424, μ PD70F3425, μ PD70F3426, μ PD70F3427

No.	Outline	μ PD70F3424		μ PD70F3425		μ PD70F3426	μ PD70F3427		
		Rev.	1.0	1.1	1.1	2.0	1.0		1.0
		Rank ^{Note}		KE		KE	IE		
No. 1	Flash Memory: Flash memory block operations (Technical limitation)	X	✓	X	✓	✓	✓		
No. 2	CPU: RAM mirror access (Specification change notice)	✓	✓	X	X	✓	✓		
No. 3	Ports: PDSCn registers mirrors (Specification change notice)	X	X	X	X	X	X		
No. 4	Code Protection and Security: Limitation of flash memory extra area and reset vector reprogramming (Specification change notice)	X	✓	X	✓	✓	✓		
No. 5	External Interrupt - Input Filter Timing Port P07/INTP6: Shortened pulse rejection time	X	X	X	✓	✓	✓		
No. 6	External Interrupt - Input Filter Timing - All external interrupt input channels (except Port P07/INTP6): Shortened pulse rejection time	✓	✓	X	X	✓	✓		
No. 7	AFCAN: Sleep Mode Wakeup (Specification change notice)	X	X	X	X	X	X		
No. 8	On-Chip Debug Unit: Maximum input clock for the Debug Control Unit (DCU) is limited to 10 MHz	X	X	X	X	X	X		
No. 9	On-Chip Debug Unit: Execution of BROM-Startup Code can be unintentionally interrupted at User S/W Breakpoint Addresses	X	X	X	X	X	X		
No. 10	CSIB: CSIB may stop operating	X	X	X	X	X	X		
No. 11	On-Chip Debug Unit: Reconfiguration of N-Wire pins during N-Wire debug mode	✓	✓	✓	✓	✓	X		
No. 12	Flash Memory: Increased Power Consumption when CPU is operating on the Sub Oscillator Clock	✓	✓	✓	✓	X	✓		
No. 13	Flash Memory: Increased Power Consumption when CPU is operating on the Sub Oscillator Clock (iRAM operation)	X	X	X	X	X	X		
No. 14	Flash Memory: Flash Access Timing Violation after System Clock (f_{CPU}) Supply Switch	X	X	X	X	X	X		

Operating Precautions for V850E/Dx3

No.	Outline	μPD70F3424		μPD70F3425		μPD70F3426	μPD70F3427	
		Rev.						
			1.0	1.1	1.1	2.0	1.0	1.0
	Rank ^{Note}		KE		KE	IE		
No. 15	CPU: HALT instruction (1) (Specification change notice)	✓	✓	✓	✓	X	✓	
No. 16	CPU: HALT instruction (2) (Specification change notice)	X	X	X	X	X	X	
No. 17	DMA: MLE Bit Usage (Specification change notice)	X	X	X	X	X	X	
No. 18	Linear code execution across address 0x00010000 and 0x00008000 when boot sectors are swapped (Direction of use)	X	X	X	X	X	X	

✓ : Not applicable

X : Applicable

Note: The rank is indicated by the letter appearing at the 5th position from the left in the lot number, marked on each product.

(B) Description of Operating Precautions

No. 1	Flash Memory: Flash memory block operations (Technical Limitation)
<p><u>Details</u></p> <p>When calling flash operations based on blocks, e.g. "BlockErase", this operation is not executed correctly for certain combinations of start and end blocks. This applies only to block combinations, where the area between the start block and the end block exceeds the 128 blocks boundary 7F_H. For example, a block operation with start block = 10_H and end block = FF_H will fail, since the 128 blocks boundary 7F_H is exceeded.</p> <p><u>Workaround</u></p> <p>Flash block operations have to be separated into two steps such that the operations are separately executed within a single 128 blocks area 00_H to 7F_H, respectively 80_H to FF_H.</p> <p>Example by using functions of the self-programming library: SelfLib_Erase(0x10,0xff) has to be separated into SelfLib_Erase(0x10,0x7f) and SelfLib_Erase(0x80, 0xff).</p>	

No. 2 CPU: RAM mirror access (μ PD70F3425 only)
(Specification change notice)

Details

The 32 KB RAM area $3FF\ 0000_H$ to $3FF\ 7FFF_H$ is mirrored to the 32 KB address range $3FF\ 8000_H$ to $3FF\ FFFF_H$. Since the upper 4 KB $3FF\ F000_H$ to $3FF\ FFFF_H$ overlaps the fixed peripheral I/O area, the RAM can not be accessed via this address range.

Following an overview of the RAM areas and it's images:

RAM		RAM image	
address range	accessibility	address range	accessibility
$3FF\ 0000_H - 3FF\ 3FFF_H$	yes	$3FF\ 8000_H - 3FF\ BFFF_H$	yes
$3FF\ 4000_H - 3FF\ 6FFF_H$	yes	$3FF\ C000_H - 3FF\ EFFF_H$	yes
$3FF\ 7000_H - 3FF\ 7FFF_H$	yes	$3FF\ F000_H - 3FF\ FFFF_H$	no

Workaround

Do not access the RAM area $3FF\ 7000_H - 3FF\ 7FFF_H$ via it's mirror area $3FF\ F000_H - 3FF\ FFFF_H$.

No. 3 Ports: PDSCn registers mirrors
(Specification change notice)

Details

The port drive strength control registers PDSCn are mirrored to a second address. Following an overview of the PDSCEn register addresses:

Register	Original address	Mirror address
PDSC0	FFFF F300 _H	FFFF F320 _H
PDSC1	FFFF F302 _H	FFFF F322 _H
PDSC2	FFFF F304 _H	FFFF F324 _H
PDSC3	FFFF F306 _H	FFFF F326 _H
PDSC4	FFFF F308 _H	FFFF F328 _H
PDSC5	FFFF F30A _H	FFFF F32A _H
PDSC6	FFFF F30C _H	FFFF F32C _H
PDSC7	FFFF F30E _H	FFFF F32E _H
PDSC8	FFFF F310 _H	FFFF F330 _H
PDSC9	FFFF F312 _H	FFFF F332 _H
PDSC10	FFFF F314 _H	FFFF F334 _H

Workaround

Though the PDSCn registers are accessible via both addresses, the original address is referenced as the only address. For instance, the mirror addresses will not be listed in the devices' header files.

No. 4 Code Protection and Security: Limitation of flash memory extra area and reset vector reprogramming
(Specification change notice)

Details

The security function which limits reprogramming of the flash memory's extra area and reset vector via an external programmer is not provided with μ PD70F3425 DS1.1.

Workaround

There is no workaround available.

No. 5 External Interrupt - Input Filter Timing Port P07/ INTP6: Shortened pulse rejection time

Details

The pulse rejection time for the analogue input filter of the port P07/ INTP6's external interrupt input filter is shorter than for the other external interrupt input channels. The effective pulse rejection time for the port P07/ INTP6 is:

min. 25,30 ns and max. 163,08 ns

Workaround

There is no workaround available.

No. 6 External Interrupt - Input Filter Timing - All external interrupt input channels (except Port P07/ INTP6): Shortened pulse rejection time

Details

The pulse rejection time for the analogue input filter of the port P07/ INTP6's external interrupt input filter is shorter than for the other external interrupt input channels. The effective pulse rejection time for the port P07/ INTP6 is:

min. 25,30 ns and max. 163,08 ns

Workaround

There is no workaround available.

<p>No. 7</p>	<p>AFCAN: Sleep Mode Wakeup (Specification change notice)</p>
	<p><u>1. Description</u></p> <p>When the AFCAN macro is set into SLEEP mode, it can be waken up by CAN bus activity. This waking up is asynchronous to the operation of the macro and the CPU. By configuration setting, a WAKEUP interrupt can be generated by the AFCAN macro on the wakeup event. While the interrupt is generated asynchronously, the AFCAN macro may need another dominant edge on the CAN bus, or software clearing of the SLEEP mode, in order to restart its synchronous operation.</p> <p>During the time, after the interrupt already has been indicated, and before the CAN macro has restarted its synchronous operation, the registers of the AFCAN macro will not operate, because the AFCAN macro still remains in SLEEP mode. This time we will refer to as “wakeup dead time” in the following context.</p> <p>To resolve from the <i>wakeup dead time</i>, software and/or hardware measures are required.</p> <p><u>2. Exclusions</u></p> <p>This Operating Precaution is only applicable to applications, which are fulfilling at least one of the following three conditions:</p> <ul style="list-style-type: none"> • SLEEP Mode of AFCAN is used and the possibility to wake up AFCAN by CAN-Bus events is given (see remark 1 below). • During SLEEP mode of the AFCAN macro, a CAN-Bus wakeup condition occurs, while the AFCAN macro is supplied with clock (see remark 2 below) and <ul style="list-style-type: none"> - after waking up from SLEEP mode of the AFCAN macro, the application software does not wait until the SLEEP mode is released by polling the CnCTRL (PSMODE) register, before continuing operation with the AFCAN macro (see remark 3 below) and - the CPU can reach instructions, where AFCAN registers are accessed while the AFCAN macro is still in SLEEP mode, due to the missing waiting condition. • During SLEEP mode of the AFCAN macro, a CAN-Bus wakeup condition occurs, while the AFCAN macro is supplied with clock (see remark 2 below) and <ul style="list-style-type: none"> - after waking up from SLEEP mode of the AFCAN macro, the CAN Bus Transceiver generates a long-lasting or permanent dominant level to the CRXD input of the AFCAN macro, instead of the propagated CAN-Bus level. <p>Remarks:</p> <ol style="list-style-type: none"> 1. If the CAN-Bus Transceiver does not propagate the CAN-Bus signal, while the AFCAN macro is in SLEEP mode, and also does not forward a wakeup signal to CRXD, this Operating Precaution is not applicable. 2. The clock supply to the AFCAN macro can be stopped, depending on the features of the device, and the system design of the application. If the clock supply to the AFCAN macro is stopped, while a wakeup condition occurs, this Operating Precaution is not applicable. 3. The maximum waiting time for this loop can be up to 10 bits of the CAN-Bus Baudrate. Waiting while retrying to clear CnINTS (Bit 5) can be used alternatively. <p>All other applications are not affected by this Operating Precaution.</p>


No. 7 AFCAN: Sleep Mode Wakeup
(Specification change notice)

3. Application Dependency

3.1 Overview

The following flowchart illustrates, how and whether additional measures have to be taken in software, to avoid the *wakeup dead time*.

Figure: Additional Measures in case AFCAN clock is active when waking up



3.2 Not affected Applications

3.2.1 Applications not using SLEEP mode

If SLEEP mode is not used, **this Operating Precaution is not applicable.**

3.2.2 Applications waking up from SLEEP mode by User Request only

If there is no condition, when SLEEP mode can be left by CAN-Bus activity, but only on User Request (by clearing the PSMODE flag by software), **this Operating Precaution is not applicable.**

3.2.3 Applications using a CPU Power Save Mode

If the clock to the AFCAN macro is disabled, while it is waken up from SLEEP mode, **this operating precaution is not applicable.**

This means, if the user selects a power save mode of the target device, which switches off the clock of the AFCAN macro, immediately after it had been set into SLEEP mode, like the CPU STOP mode, the precaution needs not to be considered.

This is associated with the software improvement hints below.

No. 7	AFCAN: Sleep Mode Wakeup (Specification change notice)
<p><u>3.3 Affected Applications</u></p> <p><u>3.3.1 Applications not waiting until SLEEP mode is left</u></p> <p>If bus transceivers are used in conjunction with AFCAN, which will propagate the CAN bus signal to AFCAN permanently (not switched off or not in power saving modes), or, if bus transceivers are used in conjunction with AFCAN, which will propagate the unmodified CAN-Bus signal when waking up from a power save mode, the wakeup dead time lasts from the first recessive-to-dominant edge of the CAN-Bus signal, which generates the wake-up, until the next recessive-to-dominant edge of the CAN-Bus signal.</p> <p>The worst case (maximum length) of the wakeup dead time, is given by the CAN bus speed and the rule of the CAN bus about the frequency of recessive-to-dominant edges. Given by the stuffing rule, at least every 10 bits, a recessive-to-dominant edge must occur.</p> <p>If during the wakeup dead time, the CPU waits until the SLEEP mode is indicated to be cleared (either by polling the PSMODE flag, or by retrying to clear CnINTS[5]), this operating precaution is not applicable. In this case, the improvement hint according to 4.2.2 is followed implicitly.</p> <p>If during the wakeup dead time, the CPU does not perform any access to the AFCAN macro in any case, this operating precaution is not applicable.</p> <p><u>3.3.2 Applications using Bus Transceivers generating long-lasting dominant CAN-Bus Signals</u></p> <p>If bus transceivers are used in conjunction with AFCAN, which <i>generate a permanent or long-lasting dominant level</i> when waking up from a power save mode, the operating precaution must be considered in any case.</p> <p>In this case, the wakeup dead time lasts from the first recessive-to-dominant edge of the CAN bus signal, which generates the wake-up, until the next recessive-to-dominant edge of the CAN bus signal, depending on the behaviour of the CAN bus transceiver.</p> <p>If no further dominant edge on the CAN bus occurs (in case of some CAN transceivers, which only provide one single edge on waking up), the time until SLEEP mode is left may become endless. Therefore, the waking up procedure of AFCAN regarding software, must be adjusted according to 4.1.1.</p> <p><u>4. Software Improvement Hints</u></p> <p><u>4.1 Recommended WAKEUP Handling by Software</u></p> <p><u>4.1.1 Clearing the SLEEP Mode by Software</u></p> <p>Within the WAKEUP interrupt routine, before accessing any other register or area of AFCAN, the SLEEP mode can be cancelled by software, followed by a clearance of the WAKEUP interrupt flag.</p> <p>Doing so, the AFCAN macro will start its synchronous operation right after these accesses.</p> <p>In the following C-code example, replace the objects in "<>" brackets by the hardware locations within your implementation. Use the appropriate access types, as described in the User's Manual.</p> <pre> WAKEUP INTERRUPT VECTOR --> <CnCTRL_PSMODE> = 0; /* Clear SLEEP Mode */ <CnINTS_CINTS5> = 1; /* Clear INTS5 */ ... /* following other parts of interrupt routine */ ... </pre> <p>Remark: Clearing INTS5 is required to get another WAKEUP interrupt anyway, by specification.</p>	

No. 7 AFCAN: Sleep Mode Wakeup
(Specification change notice)

4.2 Other WAKEUP Handling Hints

4.2.1 Switching off the Clock Supply to AFCAN, while in SLEEP Mode

If the clock supply to the AFCAN macro is stopped, while it is in SLEEP mode, the synchronisation of the WAKEUP works without any restriction. To achieve this, the documentation of clock controlling unit of the User's Manual must be consulted. Usually this is performed by setting the STOP/WATCH/Sub-WATCH mode of the CPU of the target device.

However, the user has to consider, that there must not be any WAKEUP condition (dominant level on the CAN-Bus), while the software is executing between setting SLEEP mode and stopping the AFCAN clock.

4.2.2 Using a Waiting Loop within the WAKEUP interrupt routine

Within the WAKEUP interrupt routine, create a waiting loop, which tests the capability of clearing the WAKEUP interrupt flag within AFCAN, by checking the actual power save mode.

In the following C-code example, replace the objects in "<>" brackets by the hardware locations within your implementation. Use the appropriate access types, as described in the User's Manual.

```
do
{
    AFCAN_SleepStatus = <CnCTRL_PSMODE>

    if( AFCAN_SleepStatus != 0 )
    {
        /* macro is still in SLEEP mode (waiting for latency time) */
        <CnINTS_CINTS5> = 1; /* repeated trying to clear CINTS5 */
    }

} while( AFCAN_SleepStatus != 0 );
```

This improvement hint **cannot be applied**, if a CAN-Bus-Transceiver is attached to AFCAN, which generates a permanent or long-lasting dominant level to the FCRXDn receive input pin, if a wakeup condition occurs. Missing another dominant edge on the bus, the synchronisation will not happen, and the loop could run endlessly.

4.2.3 Using INIT Mode instead of SLEEP Mode

In this case, the waking up by CAN-bus activity must be performed via another free external interrupt. The CAN receive signal must be distributed on the FCRXDn pin, and to another external interrupt pin in parallel.

Using this external interrupt, the AFCAN macro can be restored into the previous operation mode. This implementation will not use the SLEEP mode of AFCAN at all, and use the INIT mode instead.

No. 8 On-Chip Debug Unit: Maximum input clock for the Debug Control Unit (DCU) is limited to 10 MHz

Description

On-chip debugging is not possible in case that the input clock for the Debug Control Unit (DCU) has been set to 20 MHz.

Workaround

Implement all of the following measures:

- While debugging with any N-Wire based emulator, do limit the maximum input clock of the DCU to 10 MHz.
- Do consult the latest concerned tool documentation in order to verify that no OCD option is configured in your environment that will configure a higher DCU input clock than 10 MHz.
- Set the following environment variable:
IE850_JCNDREGINIT=320

Special hint for 850Eserv:

Above mentioned configuration can be achieved by setting the On-Chip-Debugger (OCD) emulator option:"-2m".

Do never set the OCD emulator option:"-dck20", since it would configure a DCU input clock of 20 MHz.

No. 9 On-Chip Debug Unit: Execution of BROM-Start-up Code can be unintentionally interrupted at User S/W Breakpoint Addresses

Description

If during program execution a Reset occurs (either from any internal Reset source or from the external Reset pin), the On-Chip Debugger may stop on the address of a previously configured S/W or H/W Breakpoint during the execution of the BROM's startup code. In this case, the following error message may be output:

```
"Couldn't read flash memory at xxx 0xc25 user system error (mask rom
>area) "
```

Workaround

Implement all of the following measures when debugging with the On-Chip Debug Unit:

- Do not set any kind of breakpoint (either S/W or H/W Breakpoint) within any of the address ranges mentioned below:

```
0x0000 ... 0x000F
0x06D0 ... 0x2B23
```

Special hint:

Reserve the address range 0x06D0 ... 0x2B23 for constant data placement. In case using NEC's directive files, which are part of the Device-File package, this is the default assignment. If the program requires less constant data than that address space offers, modify the linker directive file in a way, that program code does not start before the address 0x2B24.

No. 10 CSIB: CSIB may stop operating

Details - Master Mode Operation

When any channel of CSIB is operated with a peripheral clock source different to the clock source of the CPU, the CSIB may stop operating. Depending on the CSIB operating configuration the CSIB behaves as described below.

- Transmit mode or transmit/receive mode:
Any write to the related CBnTX0 register will no longer start a transmission sequence. Furthermore the related transmission interrupt request will not be generated.
- Receive mode:
Any read from the related CBnRX0 register will no longer start a receive sequence. Furthermore the related receive interrupt request will not be generated.

The described CSIBn stuck condition can be escaped by initiating a system reset or by a sequential clear and set of the CBnCTL0.CBnPWR bit.

Details - Slave Mode Operation

When any channel of CSIB is operated in slave mode and an external clock signal is input via the SCKBn pin while no transmission or reception sequence is in progress the CSIB may stop operating. Depending on the CSIB operating configuration the CSIB behaves as described below.

- Transmit mode or transmit/receive mode
Any further write to the CBnTX0 register followed by an external input clock signal input will no longer start a transmission sequence. Furthermore the related transmission interrupt request will not be generated.
- Receive mode:
Any read from the related CBnRX0 register followed by an external input clock signal input will no longer start a receive sequence. Furthermore the related receive interrupt request will not be generated.

The described CSIBn stuck condition can be escaped by initiating a system reset or by a sequential clear and set of the CBnCTL0.CBnPWR bit.

Workaround - Master Mode Operation #1

In order to avoid the CSIBn stuck condition in master mode use only the following CPU clock to CSIBn input clock combinations::

CPU Clock Source	SPSEL0	PERIC	SPCLK1 (BRGn) Source	CSIB Clock Input
4 MHz Main Osc	0	0	4 MHz Main OSC	PCLK6 .. 1, BRGn
	0	1	4 MHz Main OSC	PCLK6 .. 2, BRGn
	1	0	PLL	PCLK6 .. 1
	1	1	PLL	PCLK6 .. 2
PLL	1	0	PLL (Divided)	BRGn
	1	1		PCLK1, BRGn

No. 10	CSIB: CSIB may stop operating
<p>(cont.)</p> <p><u>Master Mode Operation - Workaround #2</u> In order to avoid the CSIBn stuck condition in master mode set bit CBnCTL1.CBnDAP to '1'. Pls. be aware of the changed CSIB communication type that comes along with this measure. By choosing workaround #2 no dedicated clock combination like in workaround #1 must be followed.</p> <p>or</p> <p><u>Master Mode Operation - Workaround #3 (Detection of CSIBn Stuck Condition)</u> In order to avoid a permanent stop of the CSIBn communication that may be caused by the CSIBn stuck limitation, the application software must be able to detect the CSIBn stuck condition by itself in order to restart the interrupted data transfer. The stop of the CSIBn communication can be recognized by missing interrupt generation of INTCBnR or INTCBnT before the actual data transfer has finished (INTCBnR/ INTCBnT according to the selected operation mode Continuous/ Single transfer). By choosing this method in order to detect a CSIBn stuck condition no dedicated clock combination as described in workaround #1 and no dedicated configuration of the bit CBnCTL1.CBnDAP as explained in workaround #2 must be followed.</p> <p><u>Workaround - Slave Mode Operation</u> In order to avoid the CSIBn stuck condition in slave mode take the following precautions.</p> <ul style="list-style-type: none"> • Transmit mode or transmit/receive mode: Make sure the external CSIBn clock is not input in parallel when writing to the CBnTX0 register after a transmission sequence is finished. • Receive mode: Make sure the external CSIBn clock is not input in parallel when reading from the CBnRX0 register after a reception sequence is finished. 	

No. 11	On-Chip Debug Unit: Reconfiguration of N-Wire pins during N-Wire debug mode (μPD70F3427 only)
<p><u>Details</u> During N-Wire debug mode the configuration of the N-Wire interface pins can be changed by the concerned port mode register PM5. That register contents will not be ignored in case of an active N-Wire debug mode (OCDM0 = 1). As a consequence the application software is able to disable the N-Wire operation in case the concerned port mode register is enabling output configuration for the concerned N-Wire interface pins.</p> <p><u>Workaround</u> The application software must check whether the device is operating in the N-wire debug mode or not. If it is operating in N-wire debug mode, any modifications to the related port mode register should be omitted. N-wire debug mode should be identified by checking whether the OCDM bit of the reset-controller is set and PPR05 is high.</p>	

No. 12 Flash Memory: Increased Power Consumption when CPU is operating on the Sub Oscillator Clock (μ PD70F3426 only)

Details

The device μ PD70F3426 is equipped with two separate flash clusters. Each of those clusters does contain 1 MB of flash memory. One flash cluster is accessible via the VFB (V850 Fetch Bus, Address range: 0000 0000_H to 000F FFFF_H). The other flash cluster is accessible via the VSB (Address range: 0010 0000_H to 001F FFFF_H).

The Flash-cluster that is not accessed by CPU/DMAC when CPU starts operating on the Sub-Oscillator clock ($f_{CPU} = 32$ kHz), will not enter the dedicated low-current operating mode that is normally active during that operating mode. As a consequence of that the device's current consumption will exceed the specified current consumption for this operating mode.

Workaround

In case the CPU need to operate using the Sub-Oscillator clock as CPU clock both of the device's flash clusters must be accessed at least once by CPU/DMAC in order to enable the concerned low-current operation mode for both flash clusters.

No. 13 Flash Memory: Increased Power Consumption when CPU is operating on the Sub Oscillator Clock (iRAM operation).

Details

In case the CPU starts operation using the Sub-Oscillator clock as CPU clock ($f_{CPU} = 32$ kHz) and is only executing instructions and reading data that are not located within the internal flash-memory (so the accessed instructions/ data are located within the internal RAM or external memory in case of μ PD70F3427) the internal flash-memory will not enter the dedicated low-current operating mode. As a consequence of that the device's current consumption will exceed the specified current consumption in this operating mode.

Workaround

In case the CPU need to start operation using the Sub-Oscillator clock as CPU clock supply ($f_{CPU} = 32$ kHz) and furthermore the CPU does not apply any access to its internal flash-memory, the flash memory must be accessed at least once by CPU/DMAC in order to enable the low-current operating mode of the flash memory.

For the derivative μ PD70F3426 both of the device's flash clusters must be accessed at least once by CPU/DMAC in order to enable the concerned low-current operation mode for both flash clusters.

No. 14 Flash Memory: Flash Access Timing Violation after System Clock (f_{CPU}) Supply Switch

Details

In case the system clock (f_{CPU}) is changed from the clock of the Sub-Oscillator ($f_{CPU} = 32$ kHz) to the clock of the Main-Oscillator or to any clock of SSCG or PLL, a CPU access to the internal flash-memory may violate the flash-timing. As a consequence to that the concerned read data respectively the read instruction code may be corrupted.

This behaviour will appear in case one of the below described sequences is applied from the application:

Precondition

The CPU operates using the sub-oscillator as the clock source ($f_{CPU} = 32$ kHz). As a consequence of that the flash memory is operating in the low-current operating mode (In case of μ PD70F3426 it's assumed that both flash-clusters are operating in the low-current operating mode).

(1A) The system clock (f_{CPU}) that is the clock of the Sub-Oscillator ($f_{CPU} = 32$ kHz) is switched to another clock-source (Main-Oscillator or any clock of the SSCG or PLL) by immediate configuration of PCC.

(2A) A read/fetched data/instruction is corrupted due to a timing violation on the flash-cluster.

or

(1B) The CPU enters the STOP stand-by mode.

(2B) After the stand-by mode has been released by an appropriate wake-up event, the CPU starts operation using the Main-Oscillator clock as the system clock ($f_{CPU} = 4$ MHz) after having passed the oscillator stabilization time. This is the default configuration after having been released from the STOP mode.

(3B) A read/fetched data/instruction is corrupted due to a timing violation on the flash-cluster.

or

(1C) The CPU enables and enters the Sub-WATCH stand-by mode with the following configuration of the Power save mode register PSM:

PSM.OSCDIS = 0 // Main Oscillator enabled

(2C) After the stand-by mode has been released by an appropriate wake-up event, the CPU starts operation using the Main-Oscillator clock as the system clock ($f_{CPU} = 4$ MHz) after having passed the oscillator stabilization time. This is according to the configuration of the Power save mode register PSM: PSM.OSCDIS = 0.

(3C) The read/fetched data/instruction is corrupted due to a timing violation on the flash-cluster.

No. 14 Flash Memory: Flash Access Timing Violation after System Clock (f_{CPU}) Supply Switch

(cont.)

Workaround

For any application requesting a switch of the system clock from Sub-Oscillator clock ($f_{CPU} = 32$ kHz) to any other clock (e.g. Main-Oscillator or SSCG or PLL) do implement all of the following measures:

- Do never directly change the system clock from Sub-Oscillator clock ($f_{CPU} = 32$ kHz) to the clock of the Main-Oscillator or any clock of the SSCG or PLL by executing the concerned instructions from the internal flash-memory.
- In case the application requests to enter the Sub-Watch-Mode:
 - Do never enter the Sub-WATCH mode with the following configuration of the Power save mode register PSM:
 PSM.OSCDIS = 0 // Main Oscillator enabled
 - Do always enter the Sub-WATCH mode with the following configuration of the Power save mode register PSM:
 PSM.OSCDIS = 1 // Main Oscillator disabled
 - After the Sub-WATCH standby-mode has been released by an appropriate wake-up event and furthermore the application requires another system clock (f_{CPU}) than the clock of the Sub-Oscillator, first do enable the Main-Oscillator by clearing the bit OSCDIS of the Power Save Mode register PSM:
 PSM.OSCDIS = 0 // Main Oscillator enabled
 - Do wait until the Main-Oscillator has stabilized by verifying the status flag OSCSTAT in the Clock Generator Status register CGSTAT.
 - In case any clock of the SSCG or PLL should be used as the system clock (f_{CPU}), do enable the desired clock source and wait for the specified stabilization time.
 - The instructions that will configure the system clock (f_{CPU}) must be executed from the internal RAM. Do not execute any of those configurations by executing the concerned instructions from the internal flash memory:
 - As the consequence, do jump to the internal RAM memory and execute the concerned instructions from this memory location.
 - Disable the generation of any maskable or non-maskable interrupt. This is achieved with the following configuration of the processor's Program Status Word PSW:
 PSW.ID = 1 // Disables maskable interrupts
 PSW.NP = 1 // Disables non-maskable interrupts
 - Do configure the desired clock source as system clock (f_{CPU}) by configuring the Processor clock control register PCC (PCC.CKS0 and PCC.CKS1).

No. 14 Flash Memory: Flash Access Timing Violation after System Clock (f_{CPU}) Supply Switch

(cont.)

- Do apply a dummy read access to the flash-cluster (For the derivative μ PD70F3426, do apply a dummy read access to each of both flash-clusters). As a consequence to that the flash-cluster is enabling high-speed operation mode.
- Do wait for at least 28.5 μ s before applying any new access to the internal flash memory. This wait time can be realized by execution of an appropriate software loop.
- With regards to the application needs, do enable the generation of maskable and non-maskable interrupts. This can be achieved with the following configuration of the processor's Program Status Word PSW:

```
PSW.ID = 0      // Enables maskable interrupts
PSW.NP = 0     // Enables non-maskable interrupts
```

- Do jump back to the internal flash-memory and continue execution of the application software.

Workaround

In case the application requires that the CPU enters the STOP stand-by mode, do never enter the STOP stand-by mode in case the clock of the Sub-oscillator is used as the system clock ($f_{CPU} = 32$ kHz).

No. 15 CPU: HALT instruction (1) (μ PD70F3426 only)
(Specification change notice)

Details

Data read from upper 1 MB code flash (internal VSB flash memory located from 00100000H to 001FFFFFFH) becomes invalid when a HALT instruction is executed immediately afterwards.

Workaround

To avoid the critical situation both following conditions must be applied:

- The last 4 instructions before the halt execution may not perform a data access to the upper 1 MB code flash (internal VSB flash memory located from 00100000H to 001FFFFFFH).
- HALT instructions may be only executed from lower 1 MB code flash (internal VFB flash memory located from 00000000H to 000FFFFFFH).

No. 16 CPU: HALT instruction (2)
(Specification change notice)

Details

When the cpu executes a HALT instruction the successive output of the flash memory may become undefined. The undefined data passes through the data latches, that are transparent and finally will be fetched by the cpu as sequential instruction code.

Workaround

Avoid sequential code execution after HALT instruction. This can be achieved by one of the following measures:

(1) Non-sequential code execution due to ISR execution after HALT instruction

The HALT mode may be only released with enabled interrupts (EI) by a non masked maskable interrupt request or a non-maskable interrupt request (NMI).

In this case the cpu does not execute the instructions located after the HALT instruction, but does an initial access to the interrupt handler address.

Note: Take care that no interrupt request is generated that is masked (when the corresponding xxMK bit is set to 1 in the xxIC registers), since the CPU would not branch to the interrupt handler address in that case.

(2) Branch after HALT instruction

Place a branch immediately after the HALT instruction, that is fetched before the cluster is going to stand-by and executed when stand-by is released.

Example:

```

    br    EvenAligned
    nop
    nop

.align 8
EvenAligned:

    halt
    br   UserCode
    nop
    nop
    nop

.align 8
UserCode:
    
```

Note: "align 8" means placing the code to the even flash memory addresses (0x...0 and 0x...8).

No. 17	DMA: MLE Bit Usage (Specification change notice)
<p><u>Details</u></p> <p>Do not modify the setting of the MLEn bit in the DCHCn register while the DMA channel n is activated and DMA transfers of channel n are executed in the background. Modify the MLEn bit when the corresponding channel n is one of the following periods. (The operation is not guaranteed if modified at another timing).</p> <ul style="list-style-type: none"> • Time from system reset to the generation of the first DMA transfer request of channel n • Time from DMA transfer end while MLEn=0 (after terminal count) to the generation of the next DMA transfer request • Time from the forcible termination (after the INITn bit has been set to 1) to the generation of the next DMA transfer request <p>The DMA channel transfer may stuck if the MLEn bit is modified. It may continue at the next DMA transfer request when (dummy) read accesses of the DCHCn register are performed to clear the TCn bit. In this case, DMA transfers may be lost if (dummy) read accesses are performed too late.</p> <p><u>Workaround</u></p> <p>If the application require to clear the MLEn bit while DMA transfers are executed in the background, following workaround must be applied: The workaround is independent of VSWC register setting, NPB access retries, code location or the use of other DMA channels.</p> <p>Four successive dummy read accesses to the DCHCn register should be performed directly before the MLEn bit is cleared. This sequence must not be disrupted or interrupted. To avoid a possible interrupt, the interrupt disable state should be entered by the 'di' instruction. After clearing the MLEn bit, the previous interrupt enable state may be restored. The workaround should be written in (inline-) assembler to avoid disturbing the register access sequence.</p> <pre> di // Avoid interruption of following sequence ld.b DCHCn_ADR[r0], r0 // Four dummy read accesses of DCHCn register ld.b DCHCn_ADR[r0], r0 ld.b DCHCn_ADR[r0], r0 ld.b DCHCn_ADR[r0], r0 clr1 3, DCHCn_ADR[r0] // Clear MLEn Bit ei // Restore previous interrupt enable state </pre>	

Operating Precautions for V850E/Dx3

No. 18	Linear code execution across address 0x00010000 and 0x00008000 when the boot sectors are swapped (Direction of use)
--------	--

Details

When the boot sectors of the flash memory are swapped, make sure that no linear code execution across the addresses 0x00010000 or 0x00008000 is done, because this can lead to unexpected behaviour.

Workaround

None.

(C) Valid Specification

Item	Date published	Document No.	Document Title
1	February 2004	U14559EJ3V1UM00	V850E1 32-Bit Microprocessor Core Architecture (User's Manual)
2	April 2008	U17566EE3V1UM00	V850E/Dx3 Hardware (User's Manual)
3	January 2007	EASE-SP-8007-V1.1	V850E/DL3, V850E/DJ3 Hardware (Preliminary Data Sheet)

(D) Revision History

Item	Date published	Document No.	Comment
1	October 2006	EASE-LL-0003-0.1	First release
2	February 2007	EASE-LL-0003-0.2	Operating precautions no. 11 to 16 were added.
3	May 2007	EASE-LL-0003-0.3	Compiler information on operating precautions no. 2 and 3 was updated. Operating precautions no. 17 was added.
4	November 2007	U19052EE1V0IF00	Operating precautions no. 1 to 3 of former document (EASE-LL-0003-0.3) were removed since these are already described in the valid specification. The remaining operating precautions were renumbered from 1 to 14. Operating precautions no. 15 and 16 were added.
5	May 2008	U19052EE1V1IF00	Added operating precaution no. 17
6	December 2008	U19052EE2V0IF00	Added operating precaution no. 18