

RENESAS TOOL NEWS on May 1, 2004: RSO-E7_2-040501D

A Note on Using the Tiny/SLP E7 Emulator Software --On Downloading a Firmware File to the Data Flash Area--

Please take note of the following problem in using the Tiny/SLP E7 Emulator Software:

- On downloading a firmware file to the data flash area
-

1. Versions Concerned

Tiny/SLP E7 Emulator Software V.2.3.01 and later

2. Description

Assume that a firmware file has been downloaded to the data flash area of the R5F21124 MCU belonging to the R8C/12 group or the R5F21134 to the R8C/13, and then the High-performance Embedded Workshop, an integrated development environment, has been launched. Under such conditions, clearing the Data Area Access Enable bit PM10 (bit 0 of address 05h) to 0 (that is, disabled) during executing or debugging the user program causes a timeout error to arise.

3. Workaround

If a firmware file is downloaded to the data flash area, don't clear PM10 to 0.

4. Schedule of Fixing the Problem

Sorry that this problem is unavoidable in the Tiny/SLP E7 Emulator Software.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

