

[Notes]

R20TS1091EJ0100

Rev.1.00

Dec. 20, 2024

## On-chip Debuggers

### E2 emulator and E2 emulator Lite (RA Connection)

#### Outline

When using on-chip debugger E2 emulator or E2 emulator Lite, note the following point.

1. Notes on using E2 emulator or E2 emulator Lite for RA Family.

#### 1. Notes on Using E2 emulator or E2 emulator Lite for RA Family

##### 1.1 Applicable Products

- E2 emulator, E2 emulator Lite

##### 1.2 Applicable Devices

All RA Family.

##### 1.3 Details

If you are using Ubuntu 20.04 LTS as the host OS, starting the debugger using applicable products on e<sup>2</sup> studio integrated development environment will fail. When the problem occurs, It displays on e<sup>2</sup> studio console following message.

ERROR : Could not load "ARM/E2\_v2.3.2/libRFWARM.so": "/lib/x86\_64-linux-gnu/libc.so.6: version 'GLIBC\_2.33' not found (required by ARM/E2\_v2.3.2/libRFWARM.so)"

##### 1.4 Conditions

This problem occurs when using applicable products in combination with e<sup>2</sup> studio and FSP v5.6.0 or v5.7.0 running on Ubuntu 20.04 LTS.

Please refer to the table below for the version combinations of Ubuntu OS and FSP version in which the problem occur.

| Host OS version                           | FSP version                | Occurring the problem or not |
|-------------------------------------------|----------------------------|------------------------------|
| Ubuntu 20.04 LTS Desktop (64-bit version) | v5.7.0                     | The problem occurs.          |
|                                           | v5.6.0                     | The problem occurs.          |
|                                           | v5.5.0 and before versions | Not occurs the problem.      |
| Ubuntu 22.04 LTS Desktop (64-bit version) | -                          | Not occurs the problem.      |
| Ubuntu 24.04 LTS Desktop (64-bit version) | -                          | Not occurs the problem.      |

### 1.5 Workaround

When debugging on Ubuntu OS, please use an OS version in which the problem do not occur.

### 1.6 Schedule for Fixing the Problem

This problem will be fixed in the next version of Flexible Software Package (FSP).

Revision History

| Rev. | Date      | Description |                      |
|------|-----------|-------------|----------------------|
|      |           | Page        | Summary              |
| 1.00 | Dec.20.24 | -           | First edition issued |
|      |           |             |                      |

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,  
Koto-ku, Tokyo 135-0061, Japan  
[www.renesas.com](http://www.renesas.com)

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:  
[www.renesas.com/contact/](http://www.renesas.com/contact/)