

[Notes]

R20TS0656EJ0100

Rev.1.00

Feb. 16, 2021

e² studio Code Generator Plug-in and AP4 Coding Assistance Tool for RZ

Overview

When using any of the products in the title, note the following point.

- Notes on counter clear setting for multi-function timer pulse unit 3 in complementary PWM mode

1. Notes on counter clear setting for multi-function timer pulse unit 3 in complementary PWM mode

1.1 Applicable Products

e² studio V4.0.0.26 (V2.0.0 and later versions of the Code Generator Plug-in)

V1.00.00 and later versions of the AP4 coding assistance tool for RZ

1.2 Applicable MCUs

RZ family: RZ/T1 group

1.3 Description

Counter clear control for multi-function timer pulse unit 3 in complementary PWM mode has an error. If [Counter clear on another channel performing synchronous operation] is set, a malfunction occurs after the first synchronous clearing.

1.4 Conditions

The problem arises when settings (1) and (2) are used.

- In the [General Setting] tab for multi-function timer pulse unit 3, [MTU3] or [MTU6] is set to complementary PWM mode.

MTU3	Complementary PWM mode 1
MTU4	Unused
MTU5	Unused
MTU6	Complementary PWM mode 1

- In the [MTU3] tab or [MTU6] tab for multi-function timer pulse unit 3, the following are set:

- Under [Synchronous mode setting], the [Include this channel in the synchronous operation] check box is selected.
- Under [TCNT3(or 6) counter setting], [Counter clear source] is set to [Counter clear on another channel performing synchronous operation].

The screenshot shows a configuration window with the following sections:

- Synchronous mode setting**: A checkbox labeled "Include this channel in the synchronous operation" is checked and circled in red.
- Count source setting**: A dropdown menu for "Counter clock selection" is set to "PCLK".
- Clock edge setting**: Three radio buttons are present: "Rising edge" (selected), "Falling edge", and "Both edges".
- TCNT3 counter setting**: A dropdown menu for "Counter clear source" is set to "Counter clear on another channel performing synchronous operation" and is circled in red.

1.5 Workaround

Add a code to specify synchronous clearing to the CCLR[2:0] bit of the timer control register (TCR) for MTU4^{*1} and MTU7^{*2} in the generated code (r_cg_mtu3.c), as shown below.

This modification is required every time code is generated.

*1: When MTU3 is used

*2: When MTU6 is used

- Function in the source file r_cg_mtu3.c: R_MTU3_Create(void)

Before modification

```

/*****
* Function Name: R_MTU3_Create
* Description  : This function initializes the MTU3 Unit0 module.
* Arguments    : None
* Return Value : None
*****/
void R_MTU3_Create(void)
{
    Omitted

    MTU3.TCR.BYTE = _MTU_PCLK_1 | _MTU_CKCL_SYN;
    MTU4.TCR.BYTE = _MTU_PCLK_1;

    Omitted

    MTU6.TCR.BYTE = _MTU_PCLK_1 | _MTU_CKCL_SYN;
    MTU7.TCR.BYTE = _MTU_PCLK_1;
}

```

After modification

```

/*****
* Function Name: R_MTU3_Create
* Description  : This function initializes the MTU3 Unit0 module.
* Arguments    : None
* Return Value : None
*****/
void R_MTU3_Create(void)
{
    Omitted

    MTU3.TCR.BYTE = _MTU_PCLK_1 | _MTU_CKCL_SYN;
    MTU4.TCR.BYTE = _MTU_PCLK_1 | _MTU_CKCL_SYN;
                                     Add

    Omitted

    MTU6.TCR.BYTE = _MTU_PCLK_1 | _MTU_CKCL_SYN;
    MTU7.TCR.BYTE = _MTU_PCLK_1 | _MTU_CKCL_SYN;
                                     Add

```

1.6 Permanent Measure

This problem will be fixed in the next version.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Feb.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/