

[Notes]

R20TS0895EC0100

Rev.1.00

Dec. 01, 2022

e² studio Smart Configurator for RL78 Plug-in,
Smart Configurator for RL78

Outline

When using the products in the title, note the following points.

- Notes when changing version of Board Support Program (BSP) or RL78 Software Integration System (SIS) modules

1. Notes when changing version of BSP or RL78 SIS modules

1.1 Applicable Products

- e² studio 2021-04 (Smart Configurator for RL78 Plug-in V1.0.1) or later
- Smart Configurator for RL78 V1.0.1 or later

1.2 Applicable Devices

RL78 family:

- RL78/G23
- RL78/F24
- RL78/G15

1.3 Details

After performing [Change version...], version seems to be changed successfully in the "Overview" summary. But actually some of the source code files are still the old version. (Refer to Figure 1-1). As a result, user can't be aware the version is unchanged and it may cause build errors in some cases.




Figure 1-1 BSP/RL78 SIS module [Change version...] operation

1.4 Conditions

The issue occurs when any of the following conditions are met:

1. When using Smart Configurator for RL78 V1.4.0 and preferences setting [Smart Configurator] > [Component] > [Generating code] selects “Overwrite existing component”




Figure 1-2 “Overwrite existing component” setting

2. When using Smart Configurator (V1.0.1 or later) and preferences setting [Smart Configurator] > [Component] > [Generating code] selects “Do nothing if component exists”




Figure 1-3 “Do nothing if component exists” setting

1.5 Workaround

For the above 2 occurred conditions described in [1.4 Condition](#), the workaround steps are recommended as below:

<1> Delete the specified configuration file under “r_config” folder which want to perform [Change version...].




Figure 1-4 Configuration file which want to change version

<2> Change preferences [Smart Configurator] > [Component] > [Generating code] to select “Overwrite existing component”. (Refer to [Figure1-2](#))

<3> Click [Change version...] menu.

After <1>, <2>, <3>, the BSP or RL78 SIS modules files can be generated correctly as expected version.

If user clicks [Change version...] directly without step <1> and <2> , he will get the wrong version BSP or RL78 SIS files. For this case, the user can do <1> and <2>, then click [Generate Code] button. By this operation, the files can be refreshed to the correct version, too.




Figure 1-5 [Generate Code] button

Note : After performing the above workaround, please manually restore the previous selection of the [Smart Configurator] > [Component] > [Generating code] setting for other user operation.

1.6 Schedule for Fixing the Problem

This problem will be fixed in the next version. (Scheduled to be released in Jan 2023.)

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Dec.01.22	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/