[Notes]

Renesas Flash Programmer

R20TS0330EJ0100 Rev.1.00 Jul. 16, 2018

Outline

When using the Renesas Flash Programmer, a software tool for programing flash memory, take note of the following points.

- 1. Lock bit settings for RX64M and RX71M groups
- 2. Lock bit settings for RX family excluding RX64M and RX71M groups

1. Lock Bit Settings for RX64M and RX71M Groups

1.1 Applicable Products

Renesas Flash Programmer (RFP hereafter) V3.00.00, V3.01.00, V3.02.00, V3.02.01, V3.03.00, V3.03.01, and V3.04.00

1.2 Applicable MCUs

RX64M and RX71M groups

1.3 Details

The two problems described below might occur when lock bits are set by selecting blocks in the [Lockbit] column on the [Block Setting] tab. If these problems occur, unintended processing is performed during erasing or programming of user areas by self-programming.

- Writing Lock Bits in Wrong Blocks

- Generating an Incorrect RPI File

The above two problems occur under the same conditions. Refer to the following for details of the problems and conditions.



1.3.1 Writing Lock Bits in Wrong Blocks

If all the following lock bit setting conditions are met and lock bits are written by the flash option programming command, lock bits are also written in unselected blocks in condition 3. RFP does not indicate an error.

Condition 1: Two or more consecutive blocks are selected.

Condition 2: One or more blocks whose block number is smaller than those in condition 1 are selected.

Condition 3: One or more blocks are not selected between a block selected in condition 1 and a block selected in condition 2.

Example case: When only Block0, Block2, and Block3 are selected for lock bit setting

A lock bit is also written in Block1 not selected in the Lockbit column.

Operation	Operation Settings	Block Settings	Flash Options	Connect	Settings	Unique (Code		
Region		Start	End	Size	Erase	P.V	Lockbit	^	
⊡ R	X71M Group		-						
÷	Code Flash 1	0xFFC00000	0xFFFFFFFF	4.0 M	\checkmark	\checkmark			
	Block0	0xFFFFE000	0xFFFFFFFF	8 K	\checkmark	\checkmark	\checkmark	Condition 2 is	s met.
	Block 1	0xFFFFC000	0xFFFFDFFF	8 K	\checkmark	\checkmark		Condition 3 is	s met.
	Block2	0xFFFFA000	0xFFFFBFFF	8 K	\checkmark	\checkmark	Z		
	Block3	0xFFFF8000	0xFFFF9FFF	8 K	\checkmark	\checkmark	\checkmark	Condition 1 is	s met.
	Block4	0xFFFF6000	0xFFFF7FFF	8 K	\checkmark	\checkmark			
	Block5	0xFFFF4000	0xFFFF5FFF	8 K	\checkmark	\checkmark			
	Block6	0xFFFF2000	0xFFFF3FFF	8 K	\checkmark	\checkmark			
	Block7	0xFFFF0000	0xFFFF1FFF	8 K	\checkmark	\checkmark			
	Block8	0xFFFE8000	0xFFFEFFFF	32 K	\checkmark	\checkmark			
	Block9	0xFFFE0000	0xFFFE7FFF	32 K	\checkmark	\checkmark			
	Block10	0xFFFD8000	0xFFFDFFFF	32 K	\checkmark	\checkmark			
	Plook 11	0.EEED0000	ALECENTEEE	22 K	~	~		~	

1.3.2 Generating an Incorrect RPI File

If all the conditions 1 to 3 in section 1.3.1 are met, the unselected block in condition 3 is also saved in the RPI file as a block subject to lock bit setting.

Example case: When only Block0, Block2, and Block3 are selected for lock bit setting (Note)

Block1 not selected in the Lockbit column is also output and saved in the RPI file as a block subject to lock bit setting.

Note: Because this example is the same as the one in section 1.3.1, see section 1.3.1 for the example of the RFP setting window.

2. Lock Bit Settings for RX Family Excluding RX64M and RX71M Groups

2.1 Applicable Products

Renesas Flash Programmer (RFP hereafter) V3.00.00, V3.01.00, V3.02.00, V3.02.01, V3.03.00, V3.03.01, and V3.04.00

2.2 Applicable MCUs

RX210, RX21A, RX220, RX610, RX621, RX62G, RX62N, RX62T, RX630, RX631, RX634, RX63N, and RX63T groups

2.3 Details

When lock bits are set by selecting blocks in the [Lockbit] column on the [Block Setting] tab, the three problems below might occur. If these problems occur, unintended processing is performed during erasing or programming of user areas by self-programming.

- Writing Lock Bits in Wrong Blocks
- Lock Bit Write Error
- Generating an Incorrect RPI File

Refer to the following for details of the problems and conditions.

2.3.1 Writing Lock Bits in Wrong Blocks

If all the following lock bit setting conditions are met and lock bits are written by the flash option programming command, lock bits are also written in an unselected block in condition 3. RFP does not indicate an error.

Condition 1: Two or more consecutive blocks are selected.

Condition 2: One or more blocks whose block number is smaller than those in condition 1 are selected.

- Condition 3: One or more blocks are not selected between a block selected in condition 1 and a block selected in condition 2.
- Condition 4: Only one block whose block number is larger than those in condition 1 is selected.
- Condition 5: One or more blocks are not selected between a block selected in condition 1 and a block selected in condition 4.
- ➢ Example case: When only Block0, Block2, Block3, and Block5 are selected for lock bit setting

A lock bit is also written in Block1 that is not selected in the Lockbit column.

Operation	n Operation Settings	Block Settings	Flash Options	Connect	Settings	Unique	Code		
Region		Start	End	Size	Erase	P.V	Lockbit	^	
	RX600 Series								
÷	Code Flash 1	0xFFFC0000	0xFFFFFFFF	256 K	\checkmark	\checkmark			
	Block0	0xFFFFF000	0xFFFFFFFF	4 K	\checkmark	\checkmark		Condition 2 is me	et.
	Block1	0xFFFFE000	0xFFFFEFFF	4 K	\checkmark	\checkmark		Condition 3 is me	et.
	Block2	0xFFFFD000	0xFFFFDFFF	4 K	\checkmark	\checkmark		Condition 1 is me	et
	Block3	0xFFFFC000	0xFFFFCFFF	4 K	\checkmark	\checkmark			.،
	Block4	0xFFFFB000	0xFFFFBFFF	4 K	\checkmark	\checkmark		Condition 5 is me	et.
	Block5	0xFFFFA000	0xFFFFAFFF	4 K	\checkmark	\checkmark	☑ ┥	Condition 4 is me	et.
	Block 6	0xFFFF9000	0xFFFF9FFF	4 K	\checkmark	\checkmark			
	Block 7	0xFFFF8000	0xFFFF8FFF	4 K	\checkmark	\checkmark			
	Block8	0xFFFF4000	0xFFFF7FFF	16 K	\checkmark	\checkmark			
	Block9	0xFFFF0000	0xFFFF3FFF	16 K	\checkmark	\checkmark			
	Block 10	0xFFFEC000	0xFFFEFFFF	16 K	\checkmark	\checkmark			
	Plook 11	0,0000	A.CCCEDCCC	10 K	\checkmark	1		~	

2.3.2 Lock Bit Write Error

If all the following lock bit setting conditions are met and lock bits are written by the flash option programming command, RFP displays the following error message, and then stops flash operation.

Error (E1000011): A write error occurred in the device. (Response 77:53)

Condition 1: Two or more consecutive blocks are selected.

Condition 2: One or more blocks whose block number is smaller than those in condition 1 are selected.

Condition 3: One or more blocks are not selected between a block selected in condition 1 and a block selected in condition 2.

Condition 4: A block whose block number is larger than those in condition 1 is not selected.

Example case: When only Block0, Block2, and Block3 are selected for lock bit setting

The error message indicated above is displayed, and then RFP flash operation stops.



2.3.3 Generating an Incorrect RPI File

If all the following lock bit setting conditions are met, the unselected block in condition 3 is also saved in the RPI file as a block subject to lock bit setting.

Condition 1: Two or more consecutive blocks are selected.

Condition 2: One or more blocks whose block number is smaller than those in condition 1 are selected.

Condition 3: One or more blocks are not selected between a block selected in condition 1 and a block selected in condition 2.

Example case: When only Block0, Block2, and Block3 are selected for lock bit setting

Block1 not selected in the Lockbit column is also output and saved in the RPI file as a block subject to lock bit setting.

Operation	Operation Settings	Block Settings	Flash Options	Connect	Settings	Unique	Code		
Region		Start	End	Size	Erase	P.V	Lockbit	~	
	X600 Series								
÷	Code Flash 1	0xFFFC0000	0xFFFFFFFF	256 K	\checkmark	\checkmark			
	Block0	0xFFFFF000	0xFFFFFFFF	4 K	\checkmark	\checkmark	\checkmark	◀───	—— Condition 2 is met.
	Block 1	0xFFFFE000	0xFFFFEFFF	4 K	\checkmark	\checkmark		◀────	—— Condition 3 is met.
	Block2	0xFFFFD000	0xFFFFDFFF	4 K	\checkmark	\checkmark	\checkmark		—— Condition 1 is met.
	Block3	0xFFFFC000	0xFFFFCFFF	4 K	\checkmark	\checkmark	\bigtriangledown		Condition 1 is met.
	Block4	0xFFFFB000	0xFFFFBFFF	4 K	\checkmark	\checkmark			
	Block5	0xFFFFA000	0xFFFFAFFF	4 K	\checkmark	\checkmark			
	Block 6	0xFFFF9000	0xFFFF9FFF	4 K	\checkmark	\checkmark			
	Block7	0xFFFF8000	0xFFFF8FFF	4 K	\checkmark	\checkmark			
	Block8	0xFFFF4000	0xFFFF7FFF	16 K	\checkmark	\checkmark			
	Block 9	0xFFFF0000	0xFFFF3FFF	16 K	\checkmark	\checkmark			
	Block 10	0xFFFEC000	0xFFFEFFFF	16 K	\checkmark	\checkmark			
	Plack 11	0.0000	A.CCCCDCCC	16 K	\checkmark	\checkmark		~	



3. How to Check Lock Bits Written in the MCU

The lock bit settings written in the MCU cannot be checked by Verify. To check the settings, from the [Device Information] menu, select [Read Block Operation].

4. Schedule for Fixing the Problem

This problem will be fixed in V3.05.00. This program will be available from July 20, 2018.

<Reference>

Lock bits that are written incorrectly can be corrected by running commands in V3.05.00.

Execute the following command in sequence for the blocks containing the lock bits to be corrected.

- (1) Block Erase command
- (2) Program command and Program Flash Options command

Revision History

		Description					
Rev.	Date	Page	Summary				
1.00	Jul. 16, 2018	-	First edition issued				

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan

Renesas Electronics Corporation

∎Inquiry

https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2018 Renesas Electronics Corporation. All rights reserved. TS Colophon 2.1

