

[Notes]

R20TS0026EJ0100

Rev.1.00

May 16, 2016

RX64M Group

Camera Sensor Solution

RX Driver Package Application

RX64M Group

Demonstration of Camera Function and Audio Replay with the HMI Expansion Board

RX Driver Package Application

## Outline

When using a camera sensor solution or a program for demonstrating camera functionality and audio playback functionality with the HMI expansion board provided as RX Driver Package Application for the RX64M group, take note of the problem described in this note regarding the following point.

1. Handling of flags by functions `pd_c_frame_end()` and `pd_c_error_interrupt()` in the application program

## 1. Handling of Flags by Functions `pd_c_frame_end()` and `pd_c_error_interrupt()` in the Application Program

### 1.1 Applicable Products

- RX64M group camera sensor solution RX Driver Package Application

Applicable revision: Rev1.00

The following document is relevant.

- RX64M Group Application Note  
Sensor solution which utilizes a camera  
RX Driver Package Application

Document no.: R01AN2462EJ0100

- RX64M group demonstration of camera function and audio replay with the HMI expansion board  
RX Driver Package Application

Applicable revision: Rev1.00

The following document is relevant.

- RX64M Group Application Note  
Camera function and sound play function demonstration using the HMI expansion board  
RX Driver Package Application

Document no.: R01AN2609EJ0100

## 1.2 Applicable MCUs

RX64M group

## 1.3 Condition

The execution of `R_pdc_init()` registers `pdc_frame_end()` and `pdc_error_interrupt()` as callback functions for response to generation of the corresponding interrupts.

## 1.4 Details

Since there is an error in the code for handling flags in `pdc_frame_end()` and `pdc_error_interrupt()` in the source code file `r_pdc_apl.c`, the following faults occur and processing by the application program is not executed properly.

- Faults
  - If an overrun error, underrun error, vertical number of lines setting error, or horizontal number of bytes setting error occurs at the time of frame end interrupt generation, any of the other error flags if set is cleared when the frame end flag is cleared. Thus, the required error handling does not proceed.
  - If more than one error among an overrun error, underrun error, vertical number of lines setting error, or horizontal number of bytes setting error occurs, any other error flag that is set is cleared with the first error flag. Again, the required error handling will not proceed.

## 1.5 Workaround

Correct the handling of flags by functions `pdc_frame_end()` and `pdc_error_interrupt()` in source code file `r_pdc_apl.c`.

The details of the modification are as follows. Modify the handling in blue to the handling in red for each function.

Remark: As a workaround, newly declare the argument specified for handling which executes the `R_PDC_Control` function to issue the status clearing command. Also, set the flags which are cleared by calling the `R_PDC_Control` function as “true”, and the flags which are not cleared as “false”.

- Function pdc\_frame\_end() of application program file r\_pdc\_apl.c

Before modification: Flag handling (2 parts) extracted

```
static void pdc_frame_end(void)
{
    volatile pdc_return_t ret_pdc;
    pdc_data_cfg_t p_dummy;
    pdc_stat_t p_stat_pdc;
//Omit
    if (true == p_stat_pdc.pcsr_stat.underrun)
    {
        p_stat_pdc.pcsr_stat.fifo_empty = true;
        ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &p_stat_pdc);
        if (PDC_SUCCESS != ret_pdc)
//Omit
        /* Clear FIFO empty flag. */
        p_stat_pdc.pcsr_stat.fifo_empty = true;
        ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &p_stat_pdc);
        if (PDC_SUCCESS != ret_pdc)
```

After modification:

```
static void pdc_frame_end(void)
{
    volatile pdc_return_t ret_pdc;
    pdc_data_cfg_t p_dummy;
    pdc_stat_t p_stat_pdc;
    pdc_stat_t clear_stat_pdc;
//Omit
    clear_stat_pdc.pcsr_stat.frame_busy = false;
    clear_stat_pdc.pcsr_stat.fifo_empty = false;
    clear_stat_pdc.pcsr_stat.frame_end = true;
    clear_stat_pdc.pcsr_stat.overrun = false;
    clear_stat_pdc.pcsr_stat.underrun = false;
    clear_stat_pdc.pcsr_stat.verf_error = false;
    clear_stat_pdc.pcsr_stat.herf_error = false;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy,
        &clear_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
//Omit
    /* Clear FIFO empty flag. */
    clear_stat_pdc.pcsr_stat.frame_busy = false;
    clear_stat_pdc.pcsr_stat.fifo_empty = false;
    clear_stat_pdc.pcsr_stat.frame_end = true;
    clear_stat_pdc.pcsr_stat.overrun = false;
    clear_stat_pdc.pcsr_stat.underrun = false;
    clear_stat_pdc.pcsr_stat.verf_error = false;
    clear_stat_pdc.pcsr_stat.herf_error = false;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &clear_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
```

- Function `pdc_error_interrupt()` of application program file `r_pdc_apl.c`

Before modification: Flag handling (4 parts) extracted

```
static void pdc_error_interrupt(void)
{
    volatile pdc_return_t ret_pdc;
    pdc_data_cfg_t p_dummy;
    pdc_stat_t p_stat_pdc;
//Omit
    /* Clear Overrun flag. */
    p_stat_pdc.pcsr_stat.overrun = true;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &p_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
//Omit
    /* Clear Underrun flag. */
    p_stat_pdc.pcsr_stat.underrun = true;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &p_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
//Omit
    /* Clear Vertical line setting error flag. */
    p_stat_pdc.pcsr_stat.verf_error = true;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &p_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
//Omit
    /* Clear Horizontal byte setting error flag. */
    p_stat_pdc.pcsr_stat.herf_error = true;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &p_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
```

After modification:

```
static void pdc_error_interrupt(void)
{
    volatile pdc_return_t ret_pdc;
    pdc_data_cfg_t p_dummy;
    pdc_stat_t p_stat_pdc;
    pdc_stat_t clear_stat_pdc;
//Omit
    /* Clear Overrun flag. */
    clear_stat_pdc.pcsr_stat.frame_busy = false;
    clear_stat_pdc.pcsr_stat.fifo_empty = false;
    clear_stat_pdc.pcsr_stat.frame_end = false;
    clear_stat_pdc.pcsr_stat.overrun = true;
    clear_stat_pdc.pcsr_stat.underrun = false;
    clear_stat_pdc.pcsr_stat.verf_error = false;
    clear_stat_pdc.pcsr_stat.herf_error = false;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &clear_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
//Omit
    /* Clear Underrun flag. */
    clear_stat_pdc.pcsr_stat.frame_busy = false;
    clear_stat_pdc.pcsr_stat.fifo_empty = false;
    clear_stat_pdc.pcsr_stat.frame_end = false;
    clear_stat_pdc.pcsr_stat.overrun = false;
    clear_stat_pdc.pcsr_stat.underrun = true;
    clear_stat_pdc.pcsr_stat.verf_error = false;
    clear_stat_pdc.pcsr_stat.herf_error = false;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &clear_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
//Omit
    /* Clear Vertical line setting error flag. */
    clear_stat_pdc.pcsr_stat.frame_busy = false;
    clear_stat_pdc.pcsr_stat.fifo_empty = false;
    clear_stat_pdc.pcsr_stat.frame_end = false;
    clear_stat_pdc.pcsr_stat.overrun = false;
    clear_stat_pdc.pcsr_stat.underrun = false;
    clear_stat_pdc.pcsr_stat.verf_error = true;
    clear_stat_pdc.pcsr_stat.herf_error = false;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &clear_stat_pdc);
```

```
    if (PDC_SUCCESS != ret_pdc)
//Omit
    /* Clear Horizontal byte setting error flag. */
    clear_stat_pdc.pcsr_stat.frame_busy = false;
    clear_stat_pdc.pcsr_stat.fifo_empty = false;
    clear_stat_pdc.pcsr_stat.frame_end = false;
    clear_stat_pdc.pcsr_stat.overrun = false;
    clear_stat_pdc.pcsr_stat.underrun = false;
    clear_stat_pdc.pcsr_stat.verf_error = false;
    clear_stat_pdc.pcsr_stat.herf_error = true;
    ret_pdc = R_PDC_Control(PDC_CMD_STATUS_CLR, &p_dummy, &clear_stat_pdc);
    if (PDC_SUCCESS != ret_pdc)
```

## 1.6 Schedule for Fixing the Problem

- RX64M group camera sensor solution RX Driver Package Application  
This problem will be fixed in the next version.
- RX64M group demonstration of camera function and audio replay with the HMI extension board RX Driver Package Application  
This problem will be fixed in the next version.

**Revision History**

Rev.	Date	Description	
		Page	Summary
1.00	May 16, 2016	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan  
 Renesas Electronics Corporation

■Inquiry

<http://www.renesas.com/en-hq/support/contact.html>

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.