[Notes]

CS+ Code Generator for RX, e<sup>2</sup> studio Code Generator Plug-in, R20TS0197EJ0100 Rev.1.00 Sep. 1, 2017

# AP4 Coding Assistance Tool for RX

#### **Outline**

When using the products in the title, note the following point.

1. When using the I<sup>2</sup>C bus interface in slave mode

### 1. When Using the I<sup>2</sup>C Bus Interface in Slave Mode

## 1.1 Applicable Products

- ➤ V1.03.00 and later versions of CS+ Code Generator for RX
- ➤ V3.1.0.024 and later versions of e² studio (V1.1.2 of the Code Generator plug-in)
- ➤ V1.03.00 and later versions of the AP4 coding assistance tool for RX

### 1.2 Applicable MCUs

RX family: RX110, RX111, RX113, and RX130 groups RX230, RX231, RX23T, RX24T, and RX24U groups RX64M, RX651, RX65N, and RX71M groups

#### 1.3 Details

When the  $I^2C$  bus interface is used in slave mode, communication may not be performed correctly because the SCL synchronous circuit enable bit (SCLE) of the  $I^2C$  bus function enable register (ICFER) is set to "0" in the code generated by the applicable products.

#### 1.4 Workaround

Set the SCL synchronous circuit enable bit (SCLE) of the  $I^2C$  bus function enable register (ICFER) to "1" in the following function.

- Function in the source file "r\_cg\_riic.c": "void R\_RIICn\_Create(void)" (Note 1)

This modification is required every time code is generated. However, the modified definition can be maintained when code is generated again by using the user code protection function and adding the modification in the following function. Refer to the following FAQ for the details. (Note 2)

- Function in the source file "r\_cg\_riic\_user.c": "void R\_RIICn\_Create\_UserInit(void)" (Note 1)

Note 1: *n* means the channel number.

Note 2: FAQ

 $\underline{https://www.renesas.com/en-sg/search/keyword-search.html\#q=FAQNo\%3A1011900}$ 

The following is an example of the required modification for RX230. The modification is shown in red.

Before modification:

```
/*********************
* Function Name: R_RIICO_Create
* Description : This function initializes the RIICO Bus Interface.
* Arguments
          : None
* Return Value : None
                  void R_RIICO_Create(void)
  Omitted
  /* Set ICFER */
  RIICO.ICFER.BYTE = _00_IIC_TIMEOUT_FUNCTION_DISABLE |
                  _00_IIC_MASTER_ARBITRATION_DISABLE |
                   _00_IIC_NACK_ARBITRATION_DISABLE |
                  _00_IIC_SLAVE_ARBITRATION_DISABLE |
                  _10_IIC_NACK_SUSPENSION_ENABLE |
                  _20_IIC_NOISE_FILTER_USED;
  Omitted
```

After modification:

```
/********************
* Function Name: R_RIICO_Create
* Description : This function initializes the RIICO Bus Interface.
* Arguments
           : None
* Return Value : None
********************
void R RIICO Create(void)
  Omitted
  /* Set ICFER */
  RIICO.ICFER.BYTE = _00_IIC_TIMEOUT_FUNCTION_DISABLE |
                   _00_IIC_MASTER_ARBITRATION_DISABLE |
                   _00_IIC_NACK_ARBITRATION_DISABLE |
                   _00_IIC_SLAVE_ARBITRATION_DISABLE |
                   _10_IIC_NACK_SUSPENSION_ENABLE |
                   _20_IIC_NOISE_FILTER_USED;
  RIICO.ICFER.BIT.SCLE = 1U;
  Omitted
```

### 1.5 Schedule for Fixing the Problem

This problem will be fixed in the next version. (January 2018)

#### **Revision History**

|      |              | Description |                      |
|------|--------------|-------------|----------------------|
| Rev. | Date         | Page        | Summary              |
| 1.00 | Sep. 1, 2017 | -           | First edition issued |
|      |              |             |                      |

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

■Inquiry

https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2017 Renesas Electronics Corporation. All rights reserved.

TS Colophon 2.0