Date: May 30, 2018


RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan Renesas Electronics Corporation

Product Category	MPU/MCU	Document No.	TN-SY*-A032A/E	Rev.	1.00	
Title	Revised information about the reserved SD_ERR_STS1 register in SDHI	Information Category	Technical Notification			
Applicable Product	Renesas Synergy™ S7G2, S5D9, S5D5, S3A7, and S3A3 MCU Groups	Lot No.	Reference Document	S7G2 Rev.1.30 (R01L S5D9 Rev.1.10 (R01U S5D5 Rev.1.10 (R01U S3A7 Rev.1.30 (R01U S3A3 Rev.1.10 (R01U	M0004El M0009El M0002El	J0110), J0110), J0130),


Description for the reserved bit of the SD_ERR_STS1 register in SD/MMC Host Interface (SDHI) will be updated in the next revision of the affected User's Manual.

SD/MMC Host Interface (SDHI), n.2.17 SD Error Status Register 1 (SD_ERR_STS1) [Before]



Bit	Symbol	Bit name	Description	R/W
b31 to b15	_	Reserved	These bits are read as 0.	R

[After]



Bit	Symbol	Bit name	Description	R/W
b15	_	Reserved	This bit is read as 0.	R
b31 to b16	_	Reserved	These bits are read as undefined.	R