

[Notes]

R20TS0672EJ0100

Rev.1.00

Mar. 16, 2021

C Compiler CA78K0R for RL78 Family and 78K0R,

C Compiler CC78K0R for 78K0R

Overview

When using the C compiler CA78K0R for RL78 family and for 78K0R, and C compiler CC78K0R for 78K0R, note the following point.

1. When the control expression of a switch statement is 32-bit long

1. When the control expression of a switch statement is 32-bit long

1.1 Applicable Products

CA78K0R V1.70 to V1.72 (CS+ integrated development environment)

CA78K0R V1.20 to V1.70 (CubeSuite+ integrated development environment)

CA78K0R V1.00 to V1.10 (CubeSuite integrated development environment)

CC78K0R V2.00 to V2.13 (PM+ integrated development environment)

1.2 Details

The following phenomena may occur when the control expression of a switch statement is 32-bit long:

- (a) The switch statement cannot appropriately branch to some of the case labels.
- (b) An internal error occurs during compilation.
- (c) The compiler terminates abnormally.

1.3 Conditions

These phenomena may occur if all of the conditions from (1) to (3) are met:

- (1) The control expression of a switch statement is either long type or unsigned long type.
- (2) There are two or more case labels whose constant values share the same upper 16 bits.
- (3) There are one or more case labels whose constant values have different upper 16 bits from the case labels in (2).

```
int f(long v) { /* (1) */
    switch(v) {
        case 0x00000001: /* (2) */
            return 2;
        case 0x00000010: /* (2) */
            return 3;
        case 0x80000002: /* (3) */
            return 4;
        default:
            return 5;
    }
}
```

```

}

void main(void) {
    f(1);
}

```

In this example, although function `f()` is supposed to return 2, it branches to the default label and returns 5.

1.4 Workaround

To avoid this problem, replace the switch statement with an if statement.

```

int f(long v) {
    if (v==0x1)
        return 2;
    else if (v==0x10)
        return 3;
    else if (v==0x80000002)
        return 4;
    else
        return 5;
}

void main(void) {
    f(1);
}

```

1.5 Permanent Measure

We do not plan to make modifications.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Mar.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/