

[Notes]

R20TS1170EC0100

Rev.1.00

Sep.20, 2025

e² studio Code Generator Plug-in,
 Applilet3 Coding Assistance Tool for RL78,
 AP4 Coding Assistance Tool for RL78

Outline

When using the products in the title, note the following points.

1. Notes when using LLVM compiler

1. Notes when using LLVM compiler

1.1 Applicable Products

- e² studio Code Generator Plug-in V2.24.0 (e² studio 2024-07) or later
- Applilet3 for RL78 V1.24.00 or later
- AP4 for RL78 V1.22.00 or later

1.2 Applicable Devices

RL78 family:

- RL78/L13
- RL78/G12 (30pin)

1.3 Details

When using the peripherals below, incorrect code will be generated and interrupts can't generate correctly.

- RL78/L13
 TAU01 (using INTTM01), TAU02, TAU03 (using INTTM03), TAU04, TAU05, TAU06, TAU07,
 AD, RTC, 12-bit interval timer, KEY, UART3, TMKB20, INTP6, INTP7,
 Comparator0, Comparator1, DMA2, DMA3
- RL78/G12 (30pin)
 12-bit interval timer, TAU04, TAU05, TAU06, TAU07

1.4 Conditions

This issue occurs when the user enables the interrupt.

Example: For TAU07

When the user enables "End of timer channel 7 count, generate an interrupt (INTTM07)", the interrupt function can't enter always.




Figure 1-1 Enable the interrupt

```

⊕ * Function Name: r_tau0_channel7_interrupt
⊖ void r_tau0_channel7_interrupt(void)
{
    /* Start user code. Do not edit comment generated here */
    /* End user code. Do not edit comment generated here */
}
    
```

Figure 1-2 Interrupt function

1.5 Workaround

After the driver code is generated, please modify the driver code of `r_cg_vector_table.c` shown in the red box below.

➤ RL78/L13

Before modification

```

const void *Vectors[] VECT_SECT = {
    ...
    /*
     * INT_RTIT (0x2E)
     */
    INT_RTIT,
    /*
     * INT_TM01 (0x32)
     */
    INT_TM01,
    ...
    /*
     * INT_TM07 (0x56)
     */
    INT_TM07,
    /*
     * INT_SRE3 (0x5C)
     */
    INT_SRE3,

    /*
     * INT_MD (0x5E)
     */
    INT_MD,
    /*
     * INT_FL (0x62)
     */
    INT_FL,
    ...
    /*
     * INT_DMA3 (0x66)
     */
    INT_DMA3,
    /*
     * INT_BRK_I (0x7E)
     */
    INT_BRK_I,
};
    
```

After modification

```

const void *Vectors[] VECT_SECT = {
    ...
    /*
     * INT_RTIT (0x2E)
     */
    INT_RTIT,

    /*
     * Padding for reserved interrupt source (0x30)
     */
    (void*)0xFFFF,

    /*
     * INT_TM01 (0x32)
     */
    INT_TM01,
    ...
    /*
     * INT_TM07 (0x56)
     */
    INT_TM07,

    /*
     * Padding for reserved interrupt source (0x58)
     */
    (void*)0xFFFF,

    /*
     * Padding for reserved interrupt source (0x5A)
     */
    (void*)0xFFFF,

    /*
     * INT_SRE3 (0x5C)
     */
    INT_SRE3,

    /*
     * INT_MD (0x5E)
     */
    INT_MD,

    /*
     * Padding for reserved interrupt source (0x60)
     */
    (void*)0xFFFF,

    /*
     * INT_FL (0x62)
     */
    INT_FL,
    ...
    /*
     * INT_DMA3 (0x66)
     */
    INT_DMA3,

    /*
     * Padding for reserved interrupt source (0x68)
     */
    (void*)0xFFFF,
    ...
    /*
     * Padding for reserved interrupt source (0x7C)
     */
    (void*)0xFFFF,

    /*
     * INT_BRK_I (0x7E)
     */
    INT_BRK_I,
};

```

➤ RL78/G12 (30pin)

Before modification

```
const void *Vectors[] VECT_SECT = {
    ...
    /*
     * INT_AD (0x34)
     */
    INT_AD,
    /*
     * INT_IT (0x38)
     */
    INT_IT,
    ...
};
```

After modification

```
const void *Vectors[] VECT_SECT = {
    ...
    /*
     * INT_AD (0x34)
     */
    INT_AD,
    /*
     * Padding for reserved interrupt source (0x7C)
     */
    (void*)0xFFFF,
    /*
     * INT_IT (0x38)
     */
    INT_IT,
    ...
};
```

Note: When the driver code is generated again, the generated code returns to the state before correction. Therefore, please correct the driver code each time the user generates code.

1.6 Schedule for Fixing the Problem

This problem will be fixed in the next version. (Scheduled to be released in Dec 2025.)

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Sep.20.25	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/