## Old Company Name in Catalogs and Other Documents

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <a href="http://www.renesas.com">http://www.renesas.com</a>

April 1<sup>st</sup>, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<a href="http://www.renesas.com">http://www.renesas.com</a>)

Send any inquiries to http://www.renesas.com/inquiry.



Date: Jan.09.2009

## RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan

Renesas Technology Corp.

Product Category	MPU&MCU		Document No.	TN-SH7-A697A/E	Rev.	1.00
Title	Notice about the flag bit of DMAC		Information Category	Technical Notification		
Applicable Product	SH7280 Group SH7211 Group SH7080 Group SH7243 Group	Lot No.		SH7280 Group Hardware Manual Rev.1.00 (REJ09B0393-0100) SH7211 Group Hardware Manual Rev.2.00 (REJ09B0344-0200) SH7080 Group Hardware Manual Rev.3.00 (REJ09B0181-0300)		
		ALL	Reference Document			

## [Notice]

About the NMIF bit (NMIF Flag) of DMA Operation Register (DMAOR) in DMAC,

just when a flag is set to 1, if the flag is read, the read data will be 0, but the internal state will be the same as reading 1.

In that case, if the flag is written 0, the flag will be cleared as 0, because the internal state is the same as reading 1.

## [Workaround]

In the case of using a flag of DMAC, to protect unintended bit clear to 0, please write it as following.

- 1) In the case of intended bit clear, please write 0 after reading 1 to the flag.
- 2) In the other cases, please write 1 to the flag.

If the flag is not used, it is no problem to write 0 to flag (in the case of intended bit clear, write 0 after reading 1 to the flag).

