

Outline

When using the CS+ integrated development environment, note the following point.

1. Compile error generated when using a definition in the I/O header file for a special function register (IOR) having an alias with the same address

1. Compile Error Generated When Using a Definition in the I/O Header File for a Special Function Register (IOR) Having an Alias with the Same Address

1.1 Applicable Products

- CS+ Integrated Development Environment V7.00.00 to V8.00.00
- [Evaluation Software] CS+ for CC V7.00.00 to V8.00.00

1.2 Applicable MCUs

RH850 family MCUs that support CS+

1.3 Details

Unnecessary code is generated in the I/O header file for an IOR having an alias with the same address. A compile error may occur when coding with this unnecessary code.

Example of unnecessary code:

```
AAA.BBB.REGS8.BBBL.UNIT8
```

```
AAA.BBB.REGS8.BBBH.UNIT8
```

AAA: Module name, BBB: Register name, BBBL: Low-order 8 bits, BBBH: High-order 8 bits

1.4 Conditions

BBBL is converted to CCCL and BBBH to CCCH if both conditions (1) and (2) below are met.*
A compiler error results because CCCL and CCCH are not defined in the I/O header file.

*: #define applies to the symbol having the same address in the I/O header file as follows:

```
#define BBBL CCCL
```

```
#define BBBH CCCH
```

(1) BBBL and CCCL share the same address or BBBH and CCCH share the same address.

(2) BBBL or BBBH in (1) above is referenced or set.

Code description: AAA.BBB.REGS8.BBBL.UNIT8

: AAA.BBB.REGS8.BBBH.UNIT8

- Code description example for setting BBBL to 0x0

```
AAA.BBB.REGS8. BBBL.UNIT8 = 0x0;
```

- Code description example for setting BBBH to 0x0
AAA.BBB.REGS8. BBBH.UNIT8 = 0x0;

1.5 Workaround

Describe AAA.BBB.UINT8[L]; or AAA.BBB.UINT8[H]; as shown below.

- Code description example for setting BBBL to 0x0
AAA.BBB.UINT8[L] = 0x0;
- Code description example for setting BBBH to 0x0
AAA.BBB.UINT8[H] = 0x0;

1.6 Schedule for Fixing the Problem

No unnecessary code is generated in CS+ Integrated Development Environment V8.01.00.

Note that, even if an I/O header file created in CS+ V8.01.00 is used, a compile error occurs if the file contains a code description as shown below. In such a case, describe code as shown in section 1.5, Workaround.

- Code description example for setting BBBL to 0x0
AAA.BBB.REGS8. BBBL.UNIT8 = 0x0;
- Code description example for setting BBBH to 0x0
AAA.BBB.REGS8. BBBH.UNIT8 = 0x0;

Revision History

| Rev. | Date | Description | |
|------|-----------|-------------|----------------------|
| | | Page | Summary |
| 1.00 | Apr.01.19 | - | First edition issued |
| | | | |

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/.

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.