

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

MESC TECHNICAL NEWS No.M16C-66-0012

MESC TECHNICAL NEWS 'No.M16C-64-0011' Replacement

Classification

Corrections and supplementary explanation of document

- ✓ Notes
- Knowhow
- Others

Products Effected

M16C/80 Group

MESC TECHNICAL NEWS 'No.M16C-64-0011' requires additional information.
Please replace old Technical News 'No.M16C-64-0011' with this corrected Technical News 'M16C/80 Group Precautions When Using Address Match Interrupts' (M16C-66-0012).

[Additional contents]

The contents of section 3.4 is increased.

< Additional instructions >

```
mov.w 6[SP],R0          ; Read FLG on stack
-->
mov.w 6[SP],R0          ; Read FLG on stack (In high speed interrupt, stc SVF,R0 )
```

[Attached]

Corrected Technical News 'No.M16C-66-0012'
'M16C/80 Group Precautions When Using Address Match Interrupts' 5 pages

MESC TECHNICAL NEWS

No. M16C-66-0012

M16C/80 Group Precautions When Using Address Match Interrupts

Classification

Corrections and supplementary explanation of document

✓ Notes

Knowhow
Others

Products Effected

M16C/80 Group

1. Affected devices

- M16C/80 Group

2. Precautions

When using the address match interrupt function, unwanted interrupts may occur. This can happen when the address match interrupt register is set to the first address of an interrupt process routine, or the contents of an interrupt control register is dynamically changed.

3. Detail and countermeasure

If the address match interrupt disabled, this countermeasure is not needed.

3.1 When the address match interrupt register is set to the first instruction of an interrupt process routine, and the interrupt occurs,

Example:

```
Inta:                                ; Interrupt A routine
    Pushm  R0,R1,R2,R3,A0           ; <-- Address match interrupt register set here
```

- (1) If a non-maskable interrupt (watchdog timer or NMI) occurs, the non-maskable interrupt routine is executed twice.
- (2) If another maskable interrupt (peripheral I/O interrupt) occurs, it's process routine will execute, regardless of it's priority level.
- (3) If no other interrupts occur, a software interrupt number 63 will occur.

Countermeasure :

Do not set the address of the first instruction of an interrupt process routine to the address match interrupt register

When you are setting the address match interrupt to an interrupt routine, use the second instruction or later to write to the address match interrupt register.

3.2 If an interrupt occurs immediately after it's control register is modified (interrupts are enabled), the address match interrupt register is set to the next 7 instructions (rewriting the interrupt priority level to a smaller value or clearing interrupt request bit / interrupt enable flag is "1").

Example:

```

mov.b  #0,TA0IC      ;Change TA0 interrupt priority level to 0
nop                ; 1st instruction
nop                ; 2nd instruction
nop                ; 3rd instruction
nop                ; 4th instruction
nop                ; 5th instruction
nop                ; 6th instruction
nop                ; 7th instruction

```

Occurs when address match interrupt is set to one of these

- (1) If a non-maskable interrupt occurs immediately before the execution of the instruction address set in the address match interrupt register, the non-maskable interrupt routine is executed twice. **(If 'I' flag is cleared to '0', interrupt will not occur.)**
- (2) If another maskable Interrupt request occurs immediately before the execution of the instruction address set in the address match interrupt register, it's service routine will execute, regardless of it's priority level. **(If 'I' flag is cleared to '0', interrupt will not occur.)**
- (3) If no interrupt occurs immediately before the execution of the instruction address set in the address match interrupt register, a software interrupt number 63 will occur. **(If 'I' flag is cleared to '0', interrupt will not occur.)**

Countermeasure :

Do not set the address in the address match interrupt register to any of the next 7 instructions following a rewrite to the interrupt control register (rewriting the interrupt priority level to a smaller value or clearing the interrupt request bit).

When you need to set the address match interrupt register, either use the address of the interrupt control register rewrite operation or use the 8th or later instruction following the rewrite instruction.

3.3 If an interrupt is pending, then its control register is changed, and then the I flag is set (or rewriting the IPL to a smaller value) (Note), if the address match interrupt register is set to one of the next 3 instructions:

Example:

```

fclr      I
.....
.....
bclr 3,TA0IC      ; Clear TA0 interrupt request bit
fset I           ; Set I flag (interrupt enabled)
nop          ; 1st instruction
nop          ; 2nd instruction
nop          ; 3rd instruction

```

} Occurs when address match interrupt
is set to one of these

- (1) If another non-maskable Interrupt request occurs immediately before the execution of the instruction address set in the address match interrupt register, non-maskable Interrupt routine is executed twice.
- (2) If another maskable Interrupt request occurs or is pending immediately before the execution of the instruction address set in the address match interrupt register, it's service routine will execute, regardless of it's priority level. **(If 'I' flag is cleared to '0', interrupt will not occur.)**
- (3) If no interrupt occurs immediately before the execution of the instruction address set in the address match interrupt register, a software interrupt number 63 will occur.

Countermeasure :

Do not set the address in the address match interrupt register to any of the next 3 instructions following a setting to the interrupt enable flag (I flag) or rewriting the IPL to a smaller value (Note).

Note : Instructions related to setting the I flag: FSET I, LDC FLG, POPC FLG, REIT and FREIT. Refer to section 3.4 about REIT and FREIT for detail.
Instructions related to rewriting the IPL to a smaller value: LDC FLG, LDIPL, POPC FLG, REIT and FREIT. Refer to section 3.4 about REIT and FREIT for detail.

3.4 If an interrupt B's interrupt control register is rewritten in interrupt A's interrupt routine, then returns to the address set in the address match interrupt register by a return instruction from interrupt:

Interrupt_A:

....

bclr 3,TA0IC ; Rewrite interrupt B's interrupt control register

....

reit ; When return to the address set in address match interrupt
; register by a return instruction from interrupt

- (1) If another non-maskable Interrupt request occurs immediately before the execution of the instruction address set in the address match interrupt register, non-maskable Interrupt routine will execute twice.
- (2) If another maskable Interrupt request occurs or is pending immediately before the execution of the instruction address set in the address match interrupt register, it's service routine will execute, regardless of it's priority level. **(If 'I' flag is cleared to '0', interrupt will not occur.)**
- (3) If no interrupt occurs immediately before the execution of the instruction address set in the address match interrupt register, a software interrupt number 63 will occur.

Countermeasure :

Do not rewrite the interrupt control register in the interrupt process routine.

When rewriting the interrupt control register in interrupt process routine, add the following instructions at the end of the interrupt (immediately before reit and freit instructions). When multiple interrupts are enabled in another interrupt, add the same instructions as above at the end of the interrupt routine.

Also, when rewriting the interrupt control register in nonmaskable interrupt process routine, add the following instructions at the end of all interrupts.

< Additional instructions >

```

; Add after register return instruction (popm instruction)
fclr    U           ; Select ISP (Not needed if ISP is already selected.)
pushm  R0          ; Store R0
mov.w  6[SP],R0    ; Read FLG on stack (In high speed interrupt, stc SVF,R0 )
ldc    R0,FLG      ; Set to FLG
popm   R0          ; Restore R0
nop                    ; Dummy
reit                    ; Interrupt end (Freit when high speed interrupt)

```

Example:

When the interrupt B's interrupt control register is rewritten in interrupt A routine and multiple interrupts are enabled in interrupt C routine, the countermeasure is needed at end of interrupt A and C routine.

Interrupt_A:

```

pushm R0,R1,R2,R3,A0,A1 ; Store registers
....
bclr  3,TA0IC           ; Rewrite interrupt B's interrupt control register
....
popm  R0,R1,R2,R3,A0,A1 ; Restore registers
fclr  U                 ; Select ISP (Not needed if ISP is already selected.)
pushm R0                ; Store R0
mov.w 6[SP],R0          ; Read FLG on stack
ldc   R0,FLG           ; Set to FLG
popm  R0                ; Restore R0
nop                    ; Dummy
reit                    ; Interrupt end

```

Interrupt_C:

```

pushm R0,R1,R2,R3,A0,A1 ; Store registers
fset  I                 ; Multiple interrupt enabled
....
....
popm  R0,R1,R2,R3,A0,A1 ; Restore registers
fclr  U                 ; Select ISP (Not needed if ISP is already selected.)
pushm R0                ; Store R0
mov.w 6[SP],R0          ; Read FLG on stack
ldc   R0,FLG           ; Set to FLG
popm  R0                ; Restore R0
nop                    ; Dummy
reit                    ; Interrupt end

```