Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1st, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.



HITACHI MICROCOMPUTER TECHNICAL UPDATE

| DATE | 30 August 2001 | No. | | TN-SH7-349A/E | | |
|---|---|-----|-----|---------------|----------|--|
| THEME | About initial value of bypass register. | | | | | |
| CLASSIFICATION | ☐ Spec change ☐ Limitation on Use ☐ Supplement of Documents | | | | | |
| PRODUCTNAME | HD6417750 HD6417750S HD6417751 | | | Lot | Lot#:All | |
| REFERENCE | RENCE SH7750 series Hardware Manual (Rev.1-4) | | ev. | Effectiv | | |
| DOCUMENTS | SH7751 Hardware Manual (Rev.1-2) | | | Eterni | ty | |
| When using bypass mode of SH-4 H-UDI function, pay attention to the following item: 1. Contents In IEEE Std 1149.1, there is prescription on the bypass mode as follows. When the TAP controller transfers to Capture-DR State, the bypass register is set to logic 0. | | | | | | |
| On the other hand, in SH-4, When the TAP controller transfers to Capture-DR State, the bypass register has an undefined value. | | | | | | |
| 2. Workaround Do not transfer the data expecting the fact that the bypass register is set to logic 0 when the TAP controller transfers to Capture-DR State on bypass mode. | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |