Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1st, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

DATE	7 November 2000	No.	TN-SH7-274A/E
THEME	SH7615 usage notice of multiply/multiply and accumulate instruction execution		
CLASSIFICATION	 Spec. change Supplement of Documents 		
PRODUCT NAME	HD6417615AF/ARF		
REFERENCE	SH7615 Hardware manual		Effective Date: Permanent
DOCUMENTS			Lot#: ALL

Multiplier access contention occurs by consecutive execution of multiply/multiply and accumulate instructions, and the stall cycle may be produced. If their stall cycle occur, sequence of instruction execution is reversed when S bit (saturation arithmetic bit) of SR register (status register) is changed right after the multiply and accumulate instruction. Then the instruction is executed after S bit is changed (it should be executed before the S bit is changed). Consequently, malfunction may occur on the operation.

The instructions affected by S bit change are,

Multiply and accumulate instruction : MAC.W and MAC.L instruction

<Condition & Phenomenon>

The following is an example of the condition.

1. Multiply/multiply and accumulate instructions

(1) DMULU.L R4, R10	; MUL.L, DMULS.L, DMULU.L and MAC.L come under (1).		
(2) MAC.L @R5+, @R5+	; MAC.W and MAC.L come under (2). Multiplier access contention		
	occurs, and stall cycle may be produced		
(3) LDC R0, SR	; Change the saturation arithmetic mode		

Multiplier access contention occurs between DMULU.L instruction(1) and MAC.L instruction(2), so MAC.L instruction execution(2) should be stalled. However, S bit change(3) is executed right before the MAC.L instruction execution(2) in the CPU due to the pipeline operation. Consequently, sequence of the execution(2) and (3) is reversed, and MAC.L operation result becomes inaccurate value. Instruction(1) corresponds to multiply/multiply and accumulate instructions. Instruction(2) corresponds to multiply and accumulate instructions.

<Workaround>

This problem can be avoided by any of the following workaround.

(1) Please do not execute SR register access right after multiply and accumulate instructions.

(2) Please insert NOP instruction right before LDC Rn, SR instruction.

(3) Please prevent the multiplier access contention (not to produce stall cycle).