

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPD

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
RenesasTechnology Corp.

Product Category	Development Environment		Document No.	TN-CSX-057A/EA	Rev.	1.0
Title	Update of the SuperH™ RISC engine C/C++ Compiler Package Ver. 7.1.04		Information Category	Specification Change		
Applicable Product	P0700CAS7-MWR P0700CAS7-SLR P0700CAS7-H7R	Lot No.	Reference Document	SuperH RISC engine C/C++ Compiler, Assembler, Optimizing Linkage Editor User's Manual ADE-702-372A Rev.2.0		
		Ver. 7.x				

We have updated the SuperH™ RISC engine C/C++ compiler package to be Ver. 7.1.04. For details on this update, see P0700CAS7-031113E attached to this technical update.

If you have the compiler package of the Windows® version, download the update tool from the following URL:
<http://www.renesas.com/eng/products/mpumcu/tool/index.html>

If you have the compiler package of the UNIX version, request an update to an authorized product distributor.

Attached document: P0700CAS7-031113E
SuperH™ RISC engine C/C++ Compiler Package Ver. 7.1.04 Update

SuperH™ RISC engine C/C++ Compiler Package Ver. 7.1.04 Update

We have updated the SuperH™ RISC engine C/C++ compiler to be Ver. 7.1.04.

Details on this update (problems fixed) are listed below.

Note, however, that section 1, and 3 only apply to the compiler package of the Windows® version.

1. High-performance Embedded Workshop

1.1 HEW Network Database Message Box on Windows® Me

Display of the network database error message box on Windows® Me is prevented.

1.2 Addition and Modification for Data Generated by the Project Generator

The I/O definition file (iodefine.h) of the following CPUs has been modified:

SH7020, SH7021, SH7032, SH7034, SH7040, SH7041, SH7042, SH7043, SH7044, SH7045, SH7052, SH7055F, SH7144 (F), SH7145 (F), SH7604, SH7615, SH7616, SH7705, SH7706, SH7707, SH7709, SH7709A, SH7709S, SH7727, SH7729R, SH7750, and SH7751

2. Compiler

2.1 Fixed Problems Listed in SuperH RISC engine C/C++ Compiler ver.7 Failures Found in This Release (9)

For details, refer to the technical update TN-CSX-054A.

2.2 Fixed Problems Listed in SuperH RISC engine C/C++ Compiler ver.7 Failures Found in This Release (10)

For details, refer to the technical update TN-CSX-056A.

3. SuperH™ RISC engine Simulator/Debugger

3.1 Fixed Problem Regarding the Little Endian (SH3-DSP, SH3-DSP (Core), and SH4AL-DSP)

When little endian is in use, displaying the X/Y memory contents in 8-byte units causes the byte order to be incorrect.

3.2 Fixed Problem Regarding an LDRC Instruction (SH3-DSP (Core))

If instructions LDRE @ (disp,PC) and LDRC have been executed in this order, the least significant bit of the RE register will not be 1 when EX of LDRC and WB of LDRE are executed at the same time.

3.3 Fixed Problem Regarding a Repeat (SH3-DSP (Core))

If a DSP stall occurs when the instruction at the address eight bytes ahead from the top of a repeat is fetched, a compatible repeat that has four instructions or more will not work correctly.

3.4 Fixed Problem Regarding Delayed Slot Instructions (SH-4, SH-4 with BSC, and SH-4 (SH7750R))

Stepping in instruction units will not be completed when a double-precision FMUL instruction is placed at the slot of a delayed branch instruction.