

Note on Using e2 studio Integrated Development Environment V4.0

Using the e2 studio V4.0, take note of the following problem:

- Notes for configuring KPIT GNU Toolchain projects on e2 studio V4.0
-

1. Product Concerned

e2 studio V4.0.0.26 and V4.0.1.007

2. Concerned Devices

(a) RX family RX23T group

(b) RL78 family RL78/G1D group

3. Concerned Toolchain

(a) KPIT GNURX-ELF Toolchain (Note)

(b) KPIT GNURL78-ELF Toolchain (Note)

Note: Product of KPIT Technologies Ltd.

4. Summary

e2 studio projects for "2. Concerned Devices" using

"3. Concerned Toolchain" may not apply compile options to indicate device architecture.

5. Phenomenon and workaround

(a) Case of Configuring project for RX family RX23T group with KPIT GNURX-ELF Toolchain

- Phenomenon

Compiler option "-mcpu=rx64m" may not be applied in a project configured for RX23T group with KPIT GNURX-ELF Toolchain.

The option indicates device architecture generation.

- Workaround

Please fix the compiler options of the project through the following procedure:

- (1) Open "C/C++ build" -> "Settings" of "Project Property" configuration dialog.
- (2) In "Compiler" -> "CPU", change "CPU type" as "RX600".
- (3) Uncheck "Disable generation of RX hardware FPU instructions" and enable "Generate code for RXv2 target".
- (4) Rebuild the project. Please be sure if "-mcpu=rx64m" option is seen in build console output.

(b) Case of Configuring project for RL78 family RL78/G1D group with KPIT GNURX-ELF Toolchain

- Phenomenon

Compiler option "-mcpu=g13" nor "-mg13" may not be applied in a project configured for RL78/G1D group with KPIT GNURL78-ELF Toolchain. The option indicates device architecture generation.

- Workaround

Please fix the compiler options of the project through the following procedure:

- (1) Open "C/C++ build" -> "Settings" of "Project Property" configuration dialog.
- (2) In "Compiler" -> "Other", add an "User defined options" as "-mcpu=g13" (or -mg13)
- (3) Rebuild the project.

Note: Access the following KPIT website for technical inquiries on GNU tools downloaded from the site.

<http://www.kpitgnutools.com/>

6. Fixing the Problem

This problem has been fixed in e2 studio V4.0.2.008, which will be available from August 7 as announced in RENESAS TOOL NEWS Doc No.150807/tn2.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150807tn2>

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

