

RENESAS TOOL NEWS on August 16, 2014: 140816/tn5

Note on Using Application Leading Tool for RX

When using automatic driver generator Application Leading Tool for RX, take note of the following problem:

- With setting of the multi-function timer pulse unit (MTU) and 16-bit timer pulse unit (TPU) (target: RX111 and RX64M groups)
 - Product and Version Concerned
 Application Leading Tool for RX V1.02.01
 - 2. MCUs Involved RX111 and RX64M groups of MCUs (RX family)

3. Description

In some cases, required code for setting the TGRC and TGRD registers is not output to the create function that is generated in response to setting up the multi-function timer pulse unit (MTU) or 16-bit timer pulse unit (TPU) (see NOTE below).

NOTE:

For products of the RX111 group, the 16-bit timer pulse unit (TPU) is not included among the items for setting.

4. Conditions

The problem arises if either of the following conditions is met:

- (1) "PWM mode 1" is selected for either "MTU3" or "MTU6" (see NOTE below) while "Multi-Function Timer Pulse Unit (MTU)" is selected in the tree view.
- (2) "PWM mode 1" is selected for "MTU3" while "16-Bit Timer Pulse Unit (TPU)" is selected in the tree view.

NOTE:

For products of the RX111 group, "MTU6" is not included among the items for setting of the multi-function timer pulse unit (MTU).

5. Workaround

Add code for setting the TGRC and TGRD registers to the create function.

Example:

For a product of the RX111 group, "PWM mode 1" is used for "MTU3" while "Multi-Function Timer Pulse Unit 2" is selected in the tree view and the values below are set in the fields for PWM output settings.

- Initial of compare match A value (TGRA) = 100
- Initial of compare match B value (TGRB) = 100
- Initial of compare match C value (TGRC) = 100

6. Schedule for Fixing the Problem

This problem will be fixed in the next version of Application

Leading Tool for RX.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.