RENESAS Tool News

RENESAS TOOL NEWS on November 16, 2007: 071116/tn3

A Note on Using the E8a and E8 Emulator Software Products

Please take note of the following problem in using the emulator software products for the on-chip debugging emulators E8a and E8:

• Problem arising from a treatment of the MCU's pin connected with the BUSY pin on the emulator

1. Products and Versions Concerned

- E8a Emulator Software V.1.00 Release 00 and V.1.00 Release 00A
- E8 Emulator Software V.2.09 Release 01 through V.2.10 Release 00

2. Description

If the MCU's pin connected with the BUSY pin (pin no. 9) on the connecting connector of the E8a or E8 is pulled down or floated in the user system, the emulator software may not be invoked.

3. Conditions

Case 1. When the user system designed with a member of the 740 MCU family is debugged.

The debugger cannot be invoked if the following conditions are all satisfied:

- The debugger is 740 E8a Emulator Debugger.
- The user system is designed with any member of the 38D5, 3803L, or 3804L MCU group.
- The MCU's pin connected with the BUSY pin (pin no. 9) on the connecting connector of the E8a or E8 is pulled down or floated in the user system.

The programmable I/O port of the MCU's pin connected with the BUSY pin is as follows:

- P43 in the 38D5 group
- P47 in the 3803L and 3804L groups

Case 2. When the user system designed with a member of the M16C family is debugged.

The debugger cannot be invoked if the following conditions are all satisfied:

- The debugger is either of the the following:

M16C E8a emulator debugger M32C E8a emulator debugger M16C E8 emulator debugger M32C E8 emulator debugger

- The user system is designed with any member of the M16C/60, M16C/30, M16C/Tiny, or M32C/80 MCU series.
- The pin (programmable I/O port P64) on the MCU connected with the BUSY pin (pin no. 9) on the connecting connector of the E8a or E8 is pulled down in the user system.

4. Workarounds

- (1) In Case 1, pull up the MCU's pin concerned in the user system.
- (2) In Case 2, pull up the MCU's pin concerned or keep it floated in the user system.

5. Schedule of Fixing the Problem

We plan to fix this problem in the next release of the product.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 $\ensuremath{\textcircled{\sc C}}$ 2010-2016 Renesas Electronics Corporation. All rights reserved.