

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

Notice

1. Descriptions of circuits, software and other related information in this document are provided only to illustrate the operation of semiconductor products and application examples. You are fully responsible for the incorporation of these circuits, software, and information in the design of your equipment. Renesas Electronics assumes no responsibility for any losses incurred by you or third parties arising from the use of these circuits, software, or information.
2. Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.
3. Renesas Electronics does not assume any liability for infringement of patents, copyrights, or other intellectual property rights of third parties by or arising from the use of Renesas Electronics products or technical information described in this document. No license, express, implied or otherwise, is granted hereby under any patents, copyrights or other intellectual property rights of Renesas Electronics or others.
4. You should not alter, modify, copy, or otherwise misappropriate any Renesas Electronics product, whether in whole or in part. Renesas Electronics assumes no responsibility for any losses incurred by you or third parties arising from such alteration, modification, copy or otherwise misappropriation of Renesas Electronics product.
5. Renesas Electronics products are classified according to the following two quality grades: "Standard" and "High Quality". The recommended applications for each Renesas Electronics product depends on the product's quality grade, as indicated below.
"Standard": Computers; office equipment; communications equipment; test and measurement equipment; audio and visual equipment; home electronic appliances; machine tools; personal electronic equipment; and industrial robots etc.
"High Quality": Transportation equipment (automobiles, trains, ships, etc.); traffic control systems; anti-disaster systems; anti-crime systems; and safety equipment etc.

Renesas Electronics products are neither intended nor authorized for use in products or systems that may pose a direct threat to human life or bodily injury (artificial life support devices or systems, surgical implantations etc.), or may cause serious property damages (nuclear reactor control systems, military equipment etc.). You must check the quality grade of each Renesas Electronics product before using it in a particular application. You may not use any Renesas Electronics product for any application for which it is not intended. Renesas Electronics shall not be in any way liable for any damages or losses incurred by you or third parties arising from the use of any Renesas Electronics product for which the product is not intended by Renesas Electronics.
6. You should use the Renesas Electronics products described in this document within the range specified by Renesas Electronics, especially with respect to the maximum rating, operating supply voltage range, movement power voltage range, heat radiation characteristics, installation and other product characteristics. Renesas Electronics shall have no liability for malfunctions or damages arising out of the use of Renesas Electronics products beyond such specified ranges.
7. Although Renesas Electronics endeavors to improve the quality and reliability of its products, semiconductor products have specific characteristics such as the occurrence of failure at a certain rate and malfunctions under certain use conditions. Further, Renesas Electronics products are not subject to radiation resistance design. Please be sure to implement safety measures to guard them against the possibility of physical injury, and injury or damage caused by fire in the event of the failure of a Renesas Electronics product, such as safety design for hardware and software including but not limited to redundancy, fire control and malfunction prevention, appropriate treatment for aging degradation or any other appropriate measures. Because the evaluation of microcomputer software alone is very difficult, please evaluate the safety of the final products or systems manufactured by you.
8. Please contact a Renesas Electronics sales office for details as to environmental matters such as the environmental compatibility of each Renesas Electronics product. Please use Renesas Electronics products in compliance with all applicable laws and regulations that regulate the inclusion or use of controlled substances, including without limitation, the EU RoHS Directive. Renesas Electronics assumes no liability for damages or losses occurring as a result of your noncompliance with applicable laws and regulations.
9. Renesas Electronics products and technology may not be used for or incorporated into any products or systems whose manufacture, use, or sale is prohibited under any applicable domestic or foreign laws or regulations. You should not use Renesas Electronics products or technology described in this document for any purpose relating to military applications or use by the military, including but not limited to the development of weapons of mass destruction. When exporting the Renesas Electronics products or technology described in this document, you should comply with the applicable export control laws and regulations and follow the procedures required by such laws and regulations.
10. It is the responsibility of the buyer or distributor of Renesas Electronics products, who distributes, disposes of, or otherwise places the product with a third party, to notify such third party in advance of the contents and conditions set forth in this document, Renesas Electronics assumes no responsibility for any losses incurred by you or third parties as a result of unauthorized use of Renesas Electronics products.
11. This document may not be reproduced or duplicated in any form, in whole or in part, without prior written consent of Renesas Electronics.
12. Please contact a Renesas Electronics sales office if you have any questions regarding the information contained in this document or Renesas Electronics products, or if you have any other inquiries.

(Note 1) "Renesas Electronics" as used in this document means Renesas Electronics Corporation and also includes its majority-owned subsidiaries.

(Note 2) "Renesas Electronics product(s)" means any product developed or manufactured by or for Renesas Electronics.

CUSTOMER NOTIFICATION

ZUD-CD-10-0015 (1/9)
January 22, 2010
Yoshinari Ando, Team Manager Development Tool Solution Group Multipurpose Microcomputer Systems Division Microcomputer Operations Unit NEC Electronics Corporation

QB-78K0RIX3
(Control Code: A, B, C, D, E)

Operating Precautions

Be sure to read this document before using the product.

Remark The previous name of the QB-78K0RIX3 is the QB-78K0RKX3L.

CONTENTS

1. Product Version.....2
2. Cautions3
3. Restrictions4
 3.1 List of restrictions.....4
 3.2 Details of restrictions4
4. Revision History9

Operating Precautions for QB-78K0RIX3

This document describes the following items. Refer to the user's manual for cautions on using an in-circuit emulator.

- Restrictions not applicable to the target device but applicable to an in-circuit emulator
- Restrictions applicable to both the target device and an in-circuit emulator but the correction is planned only for the in-circuit emulator

Also refer to the following documents for the restrictions in the target device.

- User's manual of target device
- Restrictions notification document for target device

1. Product Version

The product versions of NEC Electronics in-circuit emulators are indicated by a control code. The control code is the second digit from the left in the 10-digit serial number. If the product has been upgraded, the control code can be checked by selecting [About] from the [Help] menu while the ID78K0R-QB is running. In Figure 2, "X" in version information "IECUBE **** X F/W: V*.**" is the control code.

Figure 1. Checking Control Code (Label on QB-78K0RIX3)





Figure 2. Checking Control Code (ID78K0R-QB)



2. Cautions

No. 1 Support an open break function

[Description]

The open break function is not supported in ID78K0R-QB Ver. 3.40.

Download the installation file *OpenBreak_78K0R.zip* from the Development Tools Download page on the NEC Electronics website. For details, refer to the document included in *OpenBreak_78K0R.zip*.

URL: <http://www.necel.com/micro/en/ods/index.html> → Click “Version-up Service”.

Category:	Each Development Tool → IECUBE_Software
Product Name/version:	<u>ID78K0R-QB V3.40</u>
Complement:	Relative
File name:	OpenBreak_78K0R.zip

[Correction]

This function is supported in ID78K0R-QB Ver. 3.50 and later.

For details on the open break function, refer to the *ID78K0R-QB User's Manual*.

No. 2 Maximum current consumption in AV_{REF} pin

[Description]

The maximum current consumption substantially differs between the AV_{REF} pins in the QB-78K0RKX3L and the target device.

In the QB-78K0R1X3, the maximum current consumption in the AV_{REF} pin is 50 mA.

[Correction]

This issue has been corrected in products with control code D and later.

After correction, the maximum current consumption in the AV_{REF} pin is 0.05 mA.

No. 3 Default setting of open break function (applicable when the target device is 78K0R/lx3)

[Description]

The open break function is enabled by default.

Disable the open break function if motors are not to be used.

No. 4 Change in product name

[Description]

The product name has been changed from the QB-78K0RKX3L to the QB-78K0R1X3.

There is no difference in performance.

No. 5 Setting in HALT mode while subsystem clock is selected as CPU clock (Only 78K0R/Kx3-L)

[Description]

Even if the Operation speed mode control register (OSMC) of bit 7 is set as 1, subsystem clock is supplied to peripheral functions in HALT mode.

3. Restrictions

3.1 List of restrictions

No.	Restrictions	Control Code				
		A	B	C	D	E
1	Self-programming	×	×	○	○	○
2	Interrupt function for key-return	×	○	○	○	○
3	P73/TXD0/TO10 pin (only applicable to 38-pin MC packages)	×	○	○	○	○
4	Comparator interrupt function	×	×	○	○	○
5	Count clock for timer array unit	×	×	×	○	○
6	Restriction on trace data when an interrupt occurs (1)	×	×	×	○	○
7	Program execution on RAM	×	×	×	○	○
8	A break during division operation	×	×	×	○	○
9	Restriction on trace data when an interrupt occurs (2)	×	×	×	×	○

–: Not relevant, ×: Applicable, ○: Corrected

3.2 Details of restrictions

No. 1 Self-programming

[Description]

Self-programming is not supported.

[Workaround]

There is no workaround.

[Correction]

This issue has been corrected in products with control code C and later.

No. 2 Interrupt function for key-return (applicable when the target device is 78K0R/Kx3-L)

[Description]

The interrupt function for key-return does not operate.

[Workaround]

There is no workaround.

[Correction]

This issue has been corrected in products with control code B and later.

No. 3 P73/TXD0/TO10 pin (only applicable to 38-pin MC packages)

[Description]

The P73/TXD0/TO10 pin can be used for read/write accesses to SFRs, but its port function and alternate function do not operate.

[Workaround]

There is no workaround.

[Correction]

This issue has been corrected in products with control code B and later.

No. 4 Comparator interrupt function

[Description]

When a comparator interrupt function is used, interrupt requests are issued continuously while an overvoltage is being detected.

In normal operation, an interrupt request is issued only once upon detection of overvoltage.

[Workaround]

There is no workaround.

[Correction]

This issue has been corrected in products with control code C and later.

No. 5 Count clock for timer array unit

[Description]

A subsystem clock whose frequency is divided by 4 cannot be used as a count clock for a timer array unit.

[Workaround]

There is no workaround.

[Correction]

This issue has been corrected in products with control code D and later.

No. 6 Restriction on trace data when an interrupt occurs (1)

[Description]

If a read access or write access is performed immediately before occurrence of an interrupt, this access may not be reflected to the trace result.

[Workaround]

There is no workaround.

[Correction]

This issue has been corrected in products with control code D and later.

An example of trace data before and after the correction of this restriction is shown below.

[Before correction]

_	A 131064	0:00:00.516 208 000 01065	AA02	M1								MOVW AX,[DE+2H]
_	A 131065	0:00:00.516 209 000			F3FFE	9700	W					
_	A 131066	0:00:00.516 209 500 0002E	4A01FF	VECT	F3FFC	1067	W					
_	A 131067	0:00:00.516 211 500 0014A	84	M1								INC E
_	A 131068	0:00:00.516 212 000 0014B	4C0F	M1								CMP A,#0FH
_	A 131069	0:00:00.516 212 500 0014D	8A02	M1								MOV A,[DE+2H]
_	A 131070	0:00:00.516 213 000			F450D	83	R					

A read access by this MOV instruction is not reflected to the trace result.



[After correction]

_	A 131063	0:00:00.258 053 000 01065	AA02	M1								MOVW AX,[DE+2H]
_	A 131064	0:00:00.258 053 500			F450C	8312	R					
_	A 131065	0:00:00.258 054 000			F3FFE	9700	W					
_	A 131066	0:00:00.258 054 500 0002E	4A01FF	VECT	F3FFC	1067	W					
_	A 131067	0:00:00.258 056 500 0014A	84	M1								INC E
_	A 131068	0:00:00.258 057 000 0014B	4C0F	M1								CMP A,#0FH
_	A 131069	0:00:00.258 057 500 0014D	8A02	M1								MOV A,[DE+2H]
_	A 131070	0:00:00.258 058 000			F450D	83	R					

This line shows the result of the read access by "MOVW AX, [DE+2H]".

A read access by this MOV instruction is reflected to the trace result.

No. 7 Program execution on RAM


[Description]

When a branch instruction is executed on RAM and if the branch destination is an odd address located in RAM, a fail-safe break due to a word misalign access occurs.

[Workaround]

Clear the check box for the [Word Miss-align Access] in the Fail-Safe Break dialog box in the ID78K0R-QB.

A break source can be checked in the status bar in the ID78K0R-QB, as shown below.



[Correction]

This issue has been corrected in products with control code D and later.

No. 8 A break during division operation

[Description]

If a break occurs in a program in the 16th clock cycle after a division operation is started (DIVST = 1), the operation result may be incorrect.

[Workaround]

Do not set breaks for the division operation.

[Correction]

This issue has been corrected in products with control code D and later.

No. 9 Restriction on trace data when an interrupt occurs (2)

[Description]

If interrupt request occurs by the specific condition, a trace result may not be correct.

Detailed condition and phenomenon are explained in the following. This is a restriction only about trace function. The instruction is executed correctly.

- Condition

When branching to interrupt vector just after executing one of following instructions, a trace result may not be correct.

1. MOVW SP, #word
2. MOVW SP, AX
3. ADDW SP, #byte
4. SUBW SP, #byte

The above instructions are relevant by the following case.

- In case of fetching ROM, 1, 2, 3 and 4 of the above instructions are relevant
- In case of fetching RAM, 3 and 4 of the above instructions are relevant

- Phenomenon

When branching to interrupt vector just after executing the above instructions (1-4), the next instruction of above instructions (1-4) is not executed, thus it is not displayed on trace window. But the following contents are displayed on trace window actually.

- The next instruction of above instructions (1-4)
- The wrong vector address

[Workaround]


There is no workaround.

[Implementation]


This issue has been corrected in products with control code E or later.

An example of trace data before and after the correction of this restriction is shown below.

[Before correction]



[After correction]



4. Revision History

Document Number	Issued on	Description
ZUD-CD-07-0190	November 26, 2007	Newly created.
ZUD-CD-07-0209	December 14, 2007	Addition of action taken for correcting restrictions (Nos. 2 and 3)
ZUD-CD-08-0007	January 25, 2008	Addition of caution (No. 3) Addition of action taken for correcting restriction (No. 1) Addition of restrictions (Nos. 4 and 5)
ZUD-CD-08-0071	April 23, 2008	Product name change Addition of caution (No. 4)
ZUD-CD-08-0140	September 12, 2008	Addition of action taken for correcting caution items (Nos. 1 and 2) Addition of restrictions (Nos. 6 to 8) Addition of action taken for correcting restriction (No. 5)
ZUD-CD-10-0015	January 22, 2010	Addition of caution (No. 5) Addition of restrictions (No. 9) Addition of action taken for correcting restriction (No. 9)