



# Tsi110™ Design Notes

80E5000\_DN001\_02

October 26, 2009

6024 Silver Creek Valley Road San Jose, California 95138

Telephone: (408) 284-8200 • FAX: (408) 284-3572

Printed in U.S.A.

©2009 Integrated Device Technology, Inc.

---

---

#### GENERAL DISCLAIMER

Integrated Device Technology, Inc. ("IDT") reserves the right to make changes to its products or specifications at any time, without notice, in order to improve design or performance. IDT does not assume responsibility for use of any circuitry described herein other than the circuitry embodied in an IDT product. Disclosure of the information herein does not convey a license or any other right, by implication or otherwise, in any patent, trademark, or other intellectual property right of IDT. IDT products may contain errata which can affect product performance to a minor or immaterial degree. Current characterized errata will be made available upon request. Items identified herein as "reserved" or "undefined" are reserved for future definition. IDT does not assume responsibility for conflicts or incompatibilities arising from the future definition of such items. IDT products have not been designed, tested, or manufactured for use in, and thus are not warranted for, applications where the failure, malfunction, or any inaccuracy in the application carries a risk of death, serious bodily injury, or damage to tangible property. Code examples provided herein by IDT are for illustrative purposes only and should not be relied upon for developing applications. Any use of such code examples shall be at the user's sole risk.

Copyright © 2009 Integrated Device Technology, Inc.  
All Rights Reserved.

The IDT logo is registered to Integrated Device Technology, Inc. IDT is a trademark of Integrated Device Technology, Inc.

---

---

## About this Document

This document describes design notes for the Tsi110.

---

## Revision History

### **80E5000\_DN001\_02, Formal, October 2009**

This document was rebranded as IDT. It does not include any technical changes.

### **80E5000\_DN001\_01, Formal, February 2009**

This is the first version of the *Tsi110 Design Notes*. There is no new Tsi110 information in this document since the design note information used to reside in the *Tsi110 Device Errata*.

## Part Numbers

Part Number	Frequency	Temperature	Package	Pin Count
Tsi110-167CL	167 MHz	Commercial	BGA	1023
Tsi110-167CLY	167 MHz	Commercial	BGA (RoHS)	1023

## Design Notes

Design Note	Applicability
	Tsi110-167CL/CLY
"[DN1] Converting PCIXCAP to PCI_PCIXCAP[1:0]"	✓
"[DN2] Recovery from internal PCI timeouts"	✓
"[DN3] Byte swapping for Ethernet Controller"	✓
"[DN4] Boot vector mapping to HLP address"	✓
"[DN5] PCI_CLK and CG_REF clock frequency restrictions"	✓

### [DN1] Converting PCIXCAP to PCI\_PCIXCAP[1:0]

The *PCI-X Addendum to PCI Local Bus Specification (Revision 1.0a)* provides a recommendation for converting the 3-level PCIXCAP signal to two binary signals. These signals are active low and are named "133 MHz" and "PCIX." If "133 MHz" and "PCIX" are mapped to PCI\_PCIXCAP[1] and PCI\_PCIXCAP[0] respectively, the sense must be inverted. That is, instead of being active low, active high logic must be used for "133 MHz" and "PCIX."

### [DN2] Recovery from internal PCI timeouts

As a target, the PCI/X Interface contains a timer for timing out Switch Fabric requests that are initiated by devices on its PCI/X bus. A timeout on a Switch Fabric access indicates a serious system problem because an access was unable to complete.

If the PCI/X Interface experiences a Switch Fabric timeout error it asserts the following bits in the PFAB\_CSR register: TEA, RESP\_TIMEOUT, and INVLD\_RESP. The PCI/X Interface, however, is unable to recover from the error and a software reset must be performed by setting MISC\_CSR[SOFT\_RESET] and PFAB\_CSR[SW\_RST].

---

## [DN3] Byte swapping for Ethernet Controller

To ensure proper operation of the Ethernet Controller, use one of the following byte swapping configurations.

### Hardware cache coherency not used

When hardware cache coherency is not used (that is, the Ethernet Controller accesses memory directly through the Switch Fabric), byte swapping and word swapping must be configured in the following way:

- For buffer descriptors – Byte and word swapping must be enabled so that the Processor Interface and Ethernet Controller have a consistent view of the buffer descriptors.
- For data – No swapping must be enabled so that data is maintained in “network” order.

### Hardware cache coherency used

When hardware cache coherency is used (that is, the Ethernet Controller accesses memory through the Processor Bus Master, or PBM), byte swapping and word swapping must be configured in the following way:

- For buffer descriptors – Word swapping must be enabled. Byte swapping must be disabled to account for the byte swapping performed by the Processor Interface.
- For data – Byte swapping must be enabled to cancel the byte swapping performed by the Processor Interface.

From the Processor Interface’s description in the *Tsi110 User Manual*, it indicates that the Ethernet Controller’s configuration for byte and word swap could be the same because the upper address bits could be used to communicate the required swapping to the PBM. However, the Ethernet Controller does not provide control of the full 64-bit internal address space; therefore, it cannot control the Processor Interface’s byte swapping.

## [DN4] Boot vector mapping to HLP address

Immediately after a device reset, Tsi110’s BARs are not enabled; however, the following are exceptions:

1. The processor’s PB\_OCN\_BAR1 has the BOOT bit set which enables this BAR with default address mapping.
2. The HLP’s base address for chip selects 0 and 1 are enabled.

With this configuration, the processor’s boot vector, 0x0\_FFF0\_0100, is mapped to access the HLP’s chip select 0 using a 24-bit address of 0x00\_0100.

The Tsi110 provides a power-up strap to change this default behavior. The PWRUP\_PB\_BVS strap can be used to change the address mapping so that the HLP’s chip select 0 presents a 24-bit address of 0xF0\_0100. In addition, in the Tsi110 power-up straps may be used to change the HLP’s configuration so that a latched 32-bit address is presented: 0x0FF0\_0100 (for more information, see the PWRUP\_HLP\_LATCH signal).

---

## [DN5] PCI\_CLK and CG\_REF clock frequency restrictions

The Tsi110 uses the CG\_REF clock input to generate an internal Switch Fabric clock called OCN clock. The OCN clock frequency,  $T_{F\_OCN}^1$ , has the same frequency as CG\_REF when the Clock Generator is bypassed (that is,  $T_{F\_OCN} = T_{F\_NOPLL}$ ), and four times the frequency of CG\_REF when the Clock Generator is enabled (that is,  $T_{F\_OCN} = 4 * T_{F\_CG}$ ).

The Tsi110 requires that the PCI\_CLK frequency,  $T_{F\_PCI}$ , always be less than or equal to  $T_{F\_OCN}$ . Under most cases, this requirement is met by default:

- If Tsi110's CG\_PCI\_CLKO outputs (or buffered versions of CG\_PCI\_CLKO) provide the PCI/X bus clock, this requirement is met under all conditions.
- If  $T_{F\_PCI}$  is 25, 33, 50, 66 or 100MHz, this requirement is met.

The requirement that  $T_{F\_PCI}$  be less than or equal to  $T_{F\_OCN}$  can only be violated if PCI\_CLK is not driven by CG\_PCI\_CLKO and  $T_{F\_PCI}$  is greater than  $T_{F\_OCN}$ . This requirement may appear to be met but is actually violated under very specific conditions. If both the OCN clock and the PCI/X bus clock are nominally 133MHz but are driven from independent clock sources, the PCI clock may be marginally faster than the OCN clock due to inaccuracies in the clock sources. Enabling spread spectrum on PCI\_CLK, in the Clock Generator, or both, increases the amount of the violation.

Care must be taken to ensure that at all times (that is, including the maximum frequency deviations due to accuracy, age, jitter, spread spectrum, and noise),  $T_{F\_OCN}$  is greater than or equal to  $T_{F\_PCI}$ . Violating this requirement may degrade PCI/X Interface performance, lead to deadlock, or both.

---

1.  $T_{F\_NOPLL}$ ,  $T_{F\_CG}$  and  $T_{F\_PCI}$  are specified in the "Electrical Characteristics" section of the *Tsi110 Hardware Manual*.  $T_{F\_OCN}$  is not specified in the Hardware Manual because it is derived from  $T_{F\_NOPLL}$  and  $T_{F\_CG}$ .



**CORPORATE HEADQUARTERS**  
6024 Silver Creek Valley Road  
San Jose, CA 95138

**for SALES:**  
800-345-7015 or 408-284-8200  
fax: 408-284-2775  
www.idt.com

**for Tech Support:**  
email: EHBhelp@idt.com  
phone: 408-360-1538  
document: 80E5000\_DN001\_02