

Integrated Device Technology, Inc. 2975 Stender Way, Santa Clara, CA - 95054

PRODUCT/PROCESS CHANGE NOTICE (PCN)		
PCN #: M0005-08 DATE: June 6	5, 2000 MEANS OF DISTINGUISHING CHANGED DEVICES:	
Product Affected: 79RC64T574/79RC64T575	☐ Product Mark	
	☐ Back Mark	
Manufacturing Location Affected: N/A	☐ Date Code	
Date Effective: June 6, 2000	■ Other N/A	
Contact: Bimla Paul		
Title: Product Assurance Manager	Attachment:: Yes No	
Phone #: 408-654-6419		
Fax #: 408-492-8362	Samples: N/A	
E-mail: bimla.paul@idt.com		
DESCRIPTION AND PURPOSE OF CHANGE:		
☐ Die Technology		
☐ Wafer Fabrication Process		
☐ Assembly Process		
□ Equipment		
☐ Material		
☐ Testing Device Errata is u	apdated to the new revision dated April 13, 2000.	
☐ Manufacturing Site See attached 79F	RC64T574/RC64T575 Device Errata.	
☐ Data Sheet The latest errata r	revision can be reviewed at	
	om/docs/RC64575_ER_55229.pdf	
RELIABILITY/QUALIFICATION SUMMARY:		
N/A		
CUSTOMER ACKNOWLEDGMENT OF RECEIPT:		
	of this change. Please use the acknowledgement below or E-Mail	
to grant approval or request additional information. If IDT does not receive acknowledgement within 30 days of this notice		
it will be assumed that this change is acceptable.		
IDT reserves the right to ship either version manufactured after the process change effective date until the inventory		
on the earlier version has been depleted.		
Customer:	☐ Approval for shipments prior to effective date.	
Name/Date:	E-Mail Address:	
TI'.1	DI	
Title:	Phone# /Fax# :	
CUSTOMER COMMENTS:		
CUSTOMER COMMENTS.		
IDT ACKNOWLEDGMENT OF RECEIPT:		
LEANING THE CHILLIAN OF RECEIPT		
RECD. BY:	DATE:	
IDT EDC 1500 01 DEV 05 02/20/00 De	11 PEEED TO OCC 1705	



79RC64574/RC64575 Document Errata

Notes

Supplemental Information

This Document Errata reflects all changes made to the October 1999 version of the *IDT79RC64574/RC64575 User Reference Manual*, Version 1.0 and the data sheet for this device.

Revision History

November 30, 1999: First version of documentation errata for this device.

March 1, 2000: Added Item #2.

March 16, 2000: Added Item #3.

April 13, 2000: Added Item #4.

Errata Items

Item #1 - Changes to Figure 12.4 on page 12-3.

Issue: Figure 12.4 on page 12-3 of the manual includes two "R" labels in the PLL Circuit which could be interpreted as a requirement to include two resistors. No resistors are required in this circuit.

Item #2 - Change to Imp field in PRId register.

Issue: The value in the Imp field of the PRId register on page 5-7 of the manual is incorrectly given as 0x23. The correct value is 0x15.

Item #3 - Change to bulleted list on page 12-8.

Issue: The bulleted list directly above Table 12.2 incorrectly states that bits 15 to 255 are reserved bits. However, bits 15 to 26 are used in initialization of the CPU. Bits 27 to 256 are reserved bits.

Item #4 - Change to Config Register (16) section on page 5-7.

Issue: The third sentence in the first paragraph should read as follows: Other configuration options are read/write (as indicated by Config register bits 2:0) and controlled by software; on Reset, this field is undefined.

Add the following descriptions for BE and IC to Table 5.7.

Field	Description
BE	Big Endian Mode 0 → Little Endian 1 → Big Endian
IC	Primary I-cache size (I-cache size = 2^{12+IC} bytes). In the RC64574/64575 processor, this is set to 32Kbytes (DE=3).