

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPD

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
RenesasTechnology Corp.

Product Category	User Development Environment		Document No.	TN-CSX-075A/EA	Rev.	1.0
Title	H8S, H8/300 Series C/C++ Compiler Ver.4.0 bug information		Information Category	Usage Limitation		
Applicable Product	PS008CAS4-MWR PS008CAS4-SLR PS008CAS4-H7R PS008CAS5-MWR	Lot No.	Reference Document	H8S, H8/300 Series C/C++ Compiler Assembler Optimizing Linkage Editor User's Manual REJ10B0058-0100H Rev.1.00		
		Ver.4.0 or later				

Attached is the description of the detected bug information in Ver.4.0 or later of the H8S, H8/300 Series C/C++ Compiler.

The bug will affect this package version.

Attached: PS008CAS4-040601E

H8S, H8/300 Series C/C++ Compiler Ver. 4.0 The details of the detected bug information

H8S, H8/300 Series C/C++ Compiler Ver.4.0

The details of the detected bug information

Problems with the H8S, H8/300 series C/C++ compiler ver.4.0 are listed below.

1) Incorrect setting or reference to a bit field

Setting of a value or reference to a bit field might not be correctly performed.

[Example]

```
typedef struct {
    char c:8;
    char c2:8;
    int i;
}ST;

main()
{
    ST a;
    a.c=10;
    if (a.c==10) {                /* Illegally referred to a.c and the result of comparison was FALSE          */
        func1();
    } else {
        func2();
    }
}
```

[Conditions]

This problem might occur when all of the conditions in a) or b) were fulfilled.

a)

- i. 300HN or 300HA was specified as a CPU type.
- ii. The optimize option was specified(default).
- iii. A structure, which was a parameter or local variable, was declared.
- iv. The structure of iii. was of the [unsigned] char type and had a bit-field member of 8 bits.
- v. The structure of iii. was allocated to a register and the bit-field member of iv. was allocated to En register.

b)

- i. 300HN, 300HA, 2000N, 2000A, 2600N, or 2600A was specified as a CPU type.
- ii. The optimize option was specified(default).
- iii. A structure, which was a parameter or local variable, was declared.
- iv. The structure of iii. was of the [unsigned] short or [unsigned] int type and had a bit-field member of 16 bits.
- v. The structure iii. had boundary alignment number 1 (the pack=1 option or #pragma pack 1 was specified).
- vi. The structure of iii. was allocated to a register and the bit-field member of iv. was allocated to the lower 8 bits of En and RnH register.

[Solution]

Take either of the following methods to prevent this problem.

a) Cancel specification of a bit field and declare it as the scalar type.

```
struct ST {                                struct ST {
    char c:8;                                char c;
    char c2:8                                char c2;
    int i;                                    int i;
};                                           };
→
```

b) Do not specify optimization for compilation.

[Applied Product Version]

Ver.4.0 or later

2) Error in reference to addresses of structure members by &struct.array[0], etc.

If the start address was referred to by &struct.array [0] (&struct->array[0]), the address might be incorrect or an internal error might be output.

[Example]

```
typedef struct ST {
    char array[12];
}ST;

ST st;
int b,c;
char *p;

void sub()
{
    p= &st.array[0] + b + c;          /* Outputs a code to add the value of st.array[0] (not an address) */
}
```

[Conditions]

This problem might occur when all of the conditions in a) or b) were fulfilled.

a)

- i. 300HN, 300HA, 2000N, 2000A, 2600N, 2600A was specified as a CPU type.
- ii. A structure member was defined as an array.
- iii. The address value at the start of ii. was used to perform addition or subtraction twice or more.
- iv. The start address was figured out by &struct.array[0] or &struct->array[0].

b)

- i. 300HN, 300HA, 2000N, 2000A, 2600N, or 2600A was specified as a CPU type.
- ii. The optimize option was specified(default).
- iii. A variable array was defined.
- iv. The address value at the start of iii. was used to perform addition or subtraction twice or more.
- v. The start address was figured out by &array[0].

[Solution]

This problem can be prevented by the following method:

Figure out the address of the array by struct.array (or struct->array) or by just an array.

[Applied Product Version]

Ver.4.0 or later

3) Access to incorrect addresses by &=0 or |=0xFFFF

If a compound logic operation was performed on an [unsigned] short/int-type variable, a code might be generated to set a value on an incorrect address (correct address + 2).

[Example]

	Incorrect		[Correct]
typedef struct {	<code>_sub:</code>		
short w1;	<code>MOV.L @_pst:32,ER0</code>		
}*PST;	<code>SUB.W R1,R1</code>		
volatile PST pst = (PST)0xC40000;	<code>MOV.W R1,@(2:16,ER0) →</code>	<code>MOV.W R1,@ER0</code>	
short * volatile p;	<code>MOV.L @_p:32,ER0</code>		
	<code>MOV.W R1,@(2:16,ER0) →</code>	<code>MOV.W R1,@ER0</code>	
void sub(void)	<code>MOV.L @_pst:32,ER0</code>		
{	<code>MOV.W #-1,R1</code>		
pst->w1 &= 0;	<code>MOV.W R1,@(2:16,ER0) →</code>	<code>MOV.W R1,@ER0</code>	
*p &= 0;	<code>MOV.L @_p:32,ER0</code>		
pst->w1 = 0xffff;	<code>MOV.W R1,@(2:16,ER0) →</code>	<code>MOV.W R1,@ER0</code>	
*p = 0xffff;	<code>RTS</code>		
}			

[Conditions]

This problem might occur when all of the following conditions were fulfilled.

- a) 300, 300HN, 300HA, 2000N, 2000A, 2600N, or 2600A was specified as a CPU type.
- b) A variable was declared as the [unsigned] short/int type.
- c) The variable was a pointer declared as volatile.
- d) Either of the following compound logic operations was described:
 - i. Variable &=0;
 - ii. Variable |= 0xffff;

[Solution]

Take either of the following methods to prevent this problem.

- a) Add volatile to the area pointed to.

```
typedef volatile struct {          /* Add volatile          */
    short w1;
}*PST;

volatile PST pst = (PST)0xC40000;
volatile short * volatile p;     /* Add volatile          */
```

- b) Change operations of &= and |= to simple assignments.

```
pst->w1 = 0;

*p = 0;
pst->w1 = 0xffff;
*p = 0xffff;
```

[Applied Product Version]

Ver.3.0 or later

4) The instruction, which assigned 0, is deleted illegally.

If an instruction of assigned 0 was in each branch, it might be deleted illegally.

[Example]

```
sub.b      R0H, R0H      ;R0H was set as 0
:
:
L55:
:
bls       L36
sub.b     R0H, R0H      ; R0H was still 0 then this instruction can be deleted by optimization
add.w    R0, R0        ; R0H is possible to be updated to other value.
:
L48:
sub.b     R0H, R0H      ; deleted Illegally
add.w    R0, R0        ; If R0H isn't 0, it might be incorrect value
```

[Conditions]

This problem might occur when all of the following conditions were fulfilled.

- a) H8/300 or H8/300L was specified as a CPU type.
- b) The optimize=1 option was specified(default).
- c) An Instruction of assigned 0 was in each branch.

[Solution]

Take the following method to prevent this problem.

The optimize=0 option should be specified.

[Applied Product Version]

Ver.4.0.04 or later