

NEC Microcomputer Technical Information

CP(K), O

IE-780078-NS-EM1 Emulation Board for μ PD780078, 780078Y Subseries Usage Restriction		Document No.	SBG-T-2421-E	1/1
		Date issued	July 6, 2001	
		Issued by	Microcomputer Engineering Dept. Solution Engineering Div. NEC Electron Devices NEC Corporation	
		Notification classification	<input checked="" type="checkbox"/>	Usage restriction
<input type="checkbox"/>	Upgrade			
<input type="checkbox"/>	Document modification			
<input type="checkbox"/>	Other notification			
Related documents	User's manual SUD-T-4628-1-E			

1. Affected product

IE-780078-NS-EM1

Control code: A, B, C

2. Details of restriction

This notification concerns the following restriction. For details, see the attachment.

- No.3 The key return interrupt request flag (KRIF) may be set illegally.

3. Workaround

The following workaround is available for this restriction. For details, see the attachment.

- No.3 There is no workaround.

4. Modification schedule

Modified products are scheduled for release as follows.

Newly shipped products: From the shipment of July (control code: D)
 Upgrade for already shipped products: Available from mid-July

* Note that this schedule is subject to change without notice. For the detailed release schedule of modified products, contact an NEC sales representative.

5. Restriction history

Notes on using the IE-780078-NS-EM1, including the restriction history and detailed information, will be described on the following pages.

The "control code" is the second digit from the left in the 10-digit serial number in the warranty supplied with the in-circuit emulator you purchased (if it has not been upgraded). If the in-circuit emulator has been upgraded, a label indicating the new version is attached to the in-circuit emulator and the x in V-UP LEVEL x on this label indicates the control code.

Notes on Using IE-780078-NS-EM1

1. Product Version

Control Code	Peripheral EVA Chip
A, B	uPD78F0078CW (1.0)
C, D	uPD78F0078CW (2.0)

2. Product History

No.	Bugs and Changes/Additions to Specification	Control Code ^{Note}			
		A	B	C	D
1	A UART0 transmission interrupt may not occur during UART transmission when this device is used with the IE-78001-R-A, even if data is written to the TXS0 register.	×	√	√	√
2	Read values of P10 to P17 become illegal regardless of the input level when using under conditions other than $AV_{REF} = V_{DD0} = V_{DD1}$	×	×	√	√
3	The key return interrupt request flag (KRIF) may be set illegally.	×	×	×	√

×: Applicable, √: Not applicable

3. Details of Bugs and Additions to Specification

No. 1 A UART0 transmission interrupt may not occur during UART transmission when this device is used with the IE-78001-R-A, if data is written to the TXS0 register.

[Description]

A UART0 transmission interrupt may not occur during UART transmission when this device is used with the IE-78001-R-A, even if data is written to the TXS0 register.

This bug does not occur when using this device with the IE-78K0-NS(-A).

[Workaround]

There is no workaround.

This bug has been corrected in products with control code B and later.

No. 2 Read values of P10 to P17 become illegal regardless of the input level when using under conditions other than $AV_{REF} = V_{DD0} = V_{DD1}$.

[Description]

Read values of P10 to P17 become illegal regardless of the input level when using under conditions other than $AV_{REF} = V_{DD0} = V_{DD1}$.

[Workaround]

There is no workaround.

This bug has been corrected in products with control code C and later.

No. 3 The key return interrupt request flag (KRIF) may be set illegally.

[Description]

The key return interrupt request flag (KRIF) may be set illegally if a low-level signal is input when any of the PORT40 to PORT47 bits is in the input mode, and the memory expansion mode register is in the port 4 rising edge detection mode ($MEM = 01h$).

[Workaround]

There is no workaround.

Use products with control code D and later.

4. Other Cautions

This product has the following restrictions.

No.	Restrictions
1	The read data of address XX24 of external memory becomes invalid in external expansion mode. Workaround: Use control code L or later of the IE-78K0-NS or the control code E or later of the IE-78K0-NS-A. Set PM4 (port 4 output mode) to 0H when using a control code earlier than L of the IE-78K0-NS or a control code earlier than E of the IE-78K0-NS-A.
2	The initial value of the interrupt request flag register IF1L (FFE2h) becomes 04h. Workaround: Initialize the IF1L register to 00h after reset. (Example: MOV IF1L,#00h)