

To our customers,

---

## Old Company Name in Catalogs and Other Documents

---

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1<sup>st</sup>, 2010  
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.



(Ex.2) An exception occurs at a branch instruction whose branch condition is true

Instruction 1 (branch instruction)  
; SPC holds an address of this instruction on the occurrence of exception.  
Instruction 2 ; may be executed when this is a delay slot of Instruction 1  
; and a store instruction to SQ.  
Instruction 3 ;  
Instruction 4 ;  
Instruction 5 (target of the branch by Instruction 1)  
; may be executed when this is a store instruction to SQ.  
Instruction 6 ; may be executed when this is a store instruction to SQ.

(Ex.3) An exception occurs at a branch instruction whose branch condition is false

Instruction 1 (branch instruction)  
; SPC holds an address of this instruction on the occurrence of exception.  
Instruction 2 ; may be executed when this is a store instruction to SQ.  
Instruction 3 ; may be executed when this is a store instruction to SQ.  
Instruction 4 ; may be executed when this is a store instruction to SQ.  
Instruction 5 ; not executed even when this is a store instruction to SQ.

## 2. Workaround

Both 2.1 and 2.2 shown below should be satisfied:

2.1 When a PREF instruction which transfers SQ data to the external memory is followed by a store instruction accessing to the same SQ, both (1) and (2) below should be satisfied:

- (1) 3 NOP instructions (\*1) are required between the two instructions.
- (2) PREF instruction transferring SQ data into the external memory should not be located in the delay slot of any branch instructions.

(\*1) If there are other instructions between the two instructions, 3 instructions (including NOP's) satisfy this workaround.

2.2 PREF instruction transferring SQ data into external memory should not be executed inside the exception handling program.

If this is executed and if a store instructions into SQ is located in the address specified by SPC, SPC+2, SPC+4, or SPC+6 (\*2), the data transferred from SQ are possibly updated by the store instruction.

(\*2) If a branch instruction is located in the address specified by SPC, target two instructions by the branch instruction are included instead of the instructions located in SPC+4 and SPC+6.