

RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RA*-A0084B/E	Rev.	2.00
Title	Precaution regarding interrupt during successive bus access to peripherals sharing the same slave interfaces		Information Category	Technical Notification		
Applicable Product	RA6M1 Group, RA6M2 Group, RA6M3 Group, RA6T1 Group, RA4M1 Group, RA4W1 Group	Lot No.	Reference Document	Refer table at the end of this document		
		All				

If all the conditions described below applies to your software, one of the following workarounds could be used to resolve observed unexpected software behavior:

[Condition]

All of the following conditions must be met:

- Clock frequency setting:
ICLK > PCLKx (x=A,B) (RA4M1, RA4W1)
ICLK > PCLKx (x=A,B), ICLK > FCLK (RA6M1, RA6M2, RA6M3, RA6T1)
- A preceding access to the Slave interface or External bus (referred to as Access1) is followed by a subsequent access to the same slave interface or external bus (referred to as Access2).
- No access to other Slave interfaces and External bus between Access1 and Access2 occurs.
- An interrupt occurs on the last PCLKx/FCLK cycle of Access1.

Applicable slave interfaces and external bus:

Bus specifications (User's Manual: Hardware)

Table 15.1 for RA6M1, RA6M2, RA6M3, RA6T1, and RA4W1

Table 14.1 for RA4M1

		RA6M1/ RA6T1	RA6M2	RA6M3	RA4M1	RA4W1
Slave interface	Memory bus 1	-	-	-	-	-
	Memory bus 2	-	-	-	-	-
	Memory bus 3	-	-	-	-	-
	Memory bus 4	-	-	-	-	-
	Memory bus 5	-	-	-	-	-
	Internal peripheral bus 1	-	-	-	-	-
	Internal peripheral bus 3	✓	✓	✓	✓	✓
	Internal peripheral bus 4	✓	✓	✓	✓	✓
	Internal peripheral bus 5	✓	✓	✓	✓	✓
	Internal peripheral bus 7	✓	✓	✓	✓	✓
	Internal peripheral bus 8	-	-	✓	-	-
	Internal peripheral bus 9	✓	✓	✓	-	-
External bus	CS area	-	-	-	-	-
	SDRAM area	-	-	-	-	-
	QSPI area	✓	✓	✓	-	-

[Precaution]

Case1 : A wrong access to Access2 target register might occur when all issue conditions meet.

- 1) When Access2 is write operation, wrong data is written to Access2 target register temporary, then a correct value is written after the CPU returning from interrupt.
- 2) If Access2 target register has FIFO or flag bit clear function, it causes unintentional value write to FIFO or unnecessary read from FIFO, or unintentional flag bit clear on the register.


Case2 : A wrong access might occur in interrupt service routines when all issue conditions meet.

A register access to the same slave interface or external bus as Access2 in an interrupt service routine (referred to as Access3) causes an illegal operation


- 3) When Access3 is read operation, CPU might receive wrong data.
- 4) When Access3 is write operation, Access3 might not occurred in target register.
- 5) If Access3 target register has FIFO or flag bit clear function, these functions don't operated correctly.

*These behaviors may occur in combination.

Case1



Case2



[Workaround]

Apply one of the following workarounds.

- 1) In your system, set clock frequency as follows
 ICLK = PCLKx (x=A,B) (RA4M1, RA4W1)
 ICLK = PCLKx (x=A,B), ICLK=FCLK (RA6M1, RA6M2, RA6M3, RA6T1)
- 2) Identify in your code where successive Access1 and Access2 occurs relevant to the area where the unintended SW behavior was observed. Then insert DSB instruction between Access1 and Access2
- 3) Disable Interrupts during Access1 to Access2

Note: Either one of the workarounds above will address the issue; therefore, choosing which one to apply will depend on your system requirements and behavior.

[Reference Documents]

Product Group	Document Name	Revision
RA6M1	Renesas RA6M1 Group User's Manual: Hardware	Rev.1.20
RA6M2	Renesas RA6M2 Group User's Manual: Hardware	Rev.1.20
RA6M3	Renesas RA6M3 Group User's Manual: Hardware	Rev.1.20
RA6T1	Renesas RA6T1 Group User's Manual: Hardware	Rev.1.20
RA4M1	Renesas RA4M1 Group User's Manual: Hardware	Rev.1.00
RA4W1	Renesas RA4W1 Group User's Manual: Hardware	Rev.1.00