## **RENESAS TECHNICAL UPDATE**

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan **Renesas Electronics Corporation** 

Product Category	MPU/MCU		Document No.	TN-SY*-A0074B/E	Rev.	2.00	
Title	Precaution regarding interrupt during successive bus access to peripherals sharing the same slave interfaces		Information Category	Technical Notification			
Applicable Product	S3A7 Group, S3S6 Group, S3A3 Group, S3A1 Group, S5D9 Group, S5D5 Group, S5D3 Group	Lot No.					
		All	Reference Document	Refer table at the end of this document			

If all the conditions described below applies to your software, one of the following workarounds could be used to resolve observed unexpected software behavior:

[Condition]

All of the following conditions must be met:

- Clock frequency setting: a)
  - ICLK > PCLKx (x=A,B) (S3A1, S3A3, S3A6, S3A7) ICLK > PCLKx (x=A,B), ICLK>FCLK (S5D3, S5D5, S5D9)
- A preceding access to the Slave interface or External bus (referred to as Access1) is followed by a subsequent access to b) the same slave interface or external bus (referred to as Access2).
- No access to other Slave interfaces and External bus between Access1 and Access2 occurs. c)
- d) An interrupt occurs on the last PCLKx/FCLK cycle of Access1.

Applicable slave interfaces and external bus:

Bus specifications (User's Manual: Hardware)

Table 15.1 for S5D3, S5D5, S5D9, S3A1, S3A6, and S3A7

Table 14.1 for S3A3

		S5D3	S5D5	S5D9	S3A1	S3A3	S3A6	S3A7
Slave interface	Memory bus 1	-	-	-	-	-	-	-
	Memory bus 2	-	-	-				
	Memory bus 3	-	-	-	-	-	-	-
	Memory bus 4	-	-	-	-	-	-	-
	Memory bus 5	-	-	-	-			-
	Internal peripheral bus 1	-	-	-	-	-	-	-
	Internal peripheral bus 3	~	~	~	~	~	~	~
	Internal peripheral bus 4	~	~	~	~	~	~	~
	Internal peripheral bus 5	~	~	~	~	~	~	~
	Internal peripheral bus 7	~	~	~	~	~	~	~
	Internal peripheral bus 8			~				
	Internal peripheral bus 9	~	~	~	-	-	-	-
External	CS area	-	-	-	-	-		-
bus	SDRAM area		-	-				
	QSPI area	~	~	~	~	~		~



[Precaution] Case1 : A wrong access to Access2 target register might occur when all issue conditions meet. 1) When Access2 is write operation, wrong data is written to Access2 target register temporary, then a correct value is written after the CPU returning from interrupt. 2) If Access2 target register has FIFO or flag bit clear function, it causes unintentional value write to FIFO or unnecessary read from FIFO, or unintentional flag bit clear on the register. Case2 : A wrong access might occur in interrupt service routines when all issue conditions meet. A register access to the same slave interface or external bus as Access2 in an interrupt service routine (referred to as Access3) causes an illegal operation 3) When Access3 is read operation, CPU might receive wrong data. 4) When Access3 is write operation, Access3 might not occurred in target register. 5) If Access3 target register has FIFO or flag bit clear function, these functions don't operated correctly. \*These behaviors may occur in combination. Case1 ICLK Condition a) **PCLKx** Condition b) Successive access to same I/F without interrupt BUS X Access1 Access2 Value of Access2 target register Condition c) In the above accesses, an interrupt occurs Access after Interrupt routine Interrupt Generated by interrupt (XXX) BUS Access1 Access2 Resume after Interrupt process Context stacking is done due to interrupt Condition d Case1-1) Value of Access2 target register Data before change Wrong Data by write operation Correct Data Without FIFO and clear function <u> Case1-2)</u> Value of Access2 target register Data before change with FIFO or clear function If Access2 target register has FIFO or clear function, these don't operate correctly on Access2 read/write operation Case2  $\$ ICLK Condition a) PCLKx Condition Successive access to same I/F without interrupt BUS X Access1 Access2 Condition c) Access3 to same slave interface as Access2 In the above accesses, an interrupt occurs Access during Interrupt routine Interrupt Generated by interrupt In addition, if Access3 target Case2-3.5 register has FIFO or clear BUS XXX X Access1 Access3(Read) function, these functions Context stacking is done due to interrupt don't operated correctly Get Wrong Data on Condition d) Read operation Interrupt Ţ Generated by interrupt BUS X Access1 Access3(Write) Case2-4,5 Value of Access3 target register Access3 write operation isn't occurred.



## [Workaround]

Apply one of the following workarounds.

- 1) In your system, set clock frequency as follows ICLK = PCLKx (x=A,B) (S3A1, S3A3, S3A6, S3A7)
  - ICLK = PCLKx (x=A,B), ICLK>FCLK (S5D3, S5D5, S5D9)
- 2) Identify in your code where successive Access1 and Access2 occurs relevant to the area where the unintended SW behavior was observed. Then insert DSB instruction between Access1 and Access2
- 3) Disable Interrupts during Access1 to Access2
- Note: Either one of the workarounds above will address the issue; therefore, choosing which one to apply will depend on your system requirements and behavior.

[Reference Docu	ments]	
Product Group	Document Name	Revision
S5D3	S5D3 Microcontroller Group User's Manual	Rev.1.10
S5D5	S5D5 Microcontroller Group User's Manual	Rev.1.30
S5D9	S5D9 Microcontroller Group User's Manual	Rev.1.30
S3A1	S3A1 Microcontroller Group User's Manual	Rev.1.20
S3A3	S3A3 Microcontroller Group User's Manual	Rev.1.10
S3A6	S3A6 Microcontroller Group User's Manual	Rev.1.20
S3A7	S3A7 Microcontroller Group User's Manual	Rev.1.40

