

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL NEWS

No. M16C-95-0304

Precaution for the Use of the Three-Phase Motor Control Timer Functions

Classification

Corrections and supplementary
explanation of document

✓Notes

Knowhow

Others

Concerned Products

M32C/83 group

M16C/62P group

M32C/82 group

M32C/81 group

1. Symptoms

The microcomputer may generate unexpected waveforms when modifying TAI-1 (i=1, 2 and 4) register settings if all the following conditions are met while using the three-phase motor control timer functions.

Conditions (See Figure 1)

- The INV11 bit in the INVC1 register is set to "1" (Three-phase mode 1).
- A value is set in the TAI-1 register shortly before and after the timer Ai underflows.

2. Resolution

Set the value in the TAI-1 register, then rewrite the same value in the TAI-1 register after one cycle of the timer Ai count source has elapsed.

Notes:

1. If the TCK0 and TCK1 bits in the TAIiMR register are set to "0" (count source f1) and the CPU clock runs in the same cycle as the timer Ai count source, the value can be rewritten immediately after the TAI-1 register is initially written.

e.g. `mov.w RAM,TA41`
`mov.w RAM,TA41`




Figure 1. Example waveform when a value is set in the TA_{i-1} register shortly before and after the timer A_i underflows