# Old Company Name in Catalogs and Other Documents

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1<sup>st</sup>, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.

GRADE

# MAEC TECHNICAL NEWS No.4500-03-0206

Α

4554 Group Notes For CNTR1 Output Auto-Control Circuit

### Classification

Corrections and supplementary explanation of document

√ Notes Knowhow Others

#### **Concerned Products** M34554M8-XXXFP, M34554MC-XXXFP, M34554EDFP

**Concerned Function** CNTR1 pin output auto-control circuit

(1) CNTR1 Pin Output Auto-Control Circuit Specification

This function is valid when the bit 1 of register W6 is set (W61=1).

Each timer 3 underflows, valid/invalid of the PWM signal output to CNTR1 pin are repeated alternately.

(However, it is necessary to set the bit 3 of register W4 (W43=1) to change into a CNTR1 output valid state.)

If the bit 1 of register W6 is cleared again (W61=0) when using this function, the valid/invalid state of a PWM signal output is retained.

This function is canceled when the bit 2 of register W3 is cleared (W32=0) to stop timer 3. (A PWM signal output is in a valid state.)

# (2) Error

The registers W61 and W32 in a CNTR1 pin output auto-control circuit were exchanged.

Valid/invalid state of the PWM signal output to be retained when register W61 is cleared (0) is not retained by this, and this function is canceled and the output is set to be valid forcibly.

Moreover, when register W32 is cleared (0) in the state where the register W61 is set (1), the valid/invalid state of a PWM signal output is retained.

## (3) Measurement

This error poses a problem when PWM signal output is controlled by register W61. Please fix register W61 to "1" while the CNTR1 pin output auto-control function is used.

\* Please be careful about this error in the case of software development.

\* This product will be revised to resolve this error.

Immediately after its revising, we will inform you.

