

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

MESC TECHNICAL NEWS

No.M7200-07-9806

Correction in Documents of MITSUBISHI Microcomputer for TV (REV.A)

An error exist in the following documents. Please refer to the Table below.

■ Documents	Specifications	Each data sheet (printed No.)	Mar.1998 CD-ROM
M37207MF-XXXSP, M37207M8-XXXSP, M37207EFSP/FP	○	-	○
M37207MC-XXXSP	○	-	-
M37221MA-XXXSP	○	○ (H-LF451-A)	-
M37224M3-XXXSP	○	-	○
M37220M3-XXXSP	○	-	○
M37220M3-XXXFP	○	-	-
M37220M2-XXXSP	○	-	-
M37221M4-XXXSP	○	-	-
M37221M6-XXXSP	○	-	○
M37221M6-XXXFP	○	-	-
M37221M8-XXXSP	○	-	-
M37221EF-XXXSP, M37221EFSP	○	-	○
M37212M4-XXXSP, M37212M6-XXXSP/FP, M37212EF-XXXSP/FP, M37212EFSP/FP	○	-	○

In the wait mode, the following interrupts are invalid.

- (1) VSYNC interrupt
- (2) OSD interrupt
- (3) All timers interrupts using external clock input from pins as count source
- (4) All timers interrupts using $f(XIN)/2$ or $f(XCIN)/2$ as count source (See note 1)
- (5) All timers interrupts using $f(XIN)/4096$ or $f(XCIN)/4096$ as count source (See note1)
- (6) $f(XIN)/4096$ interrupt
- (7) Multi-master I²C-BUS interface interrupt (See note 2)

Notes 1: All timers interrupts using $f(XCIN)/2$ or $f(XCIN)/4096$ are applied to only the products below:

M37207M8-XXXSP, M37207MC-XXXSP, M37207MF-XXXSP/FP, M37207EFSP,
M37207EF-XXXSP

2: The interrupts are not applied to the products below:

M37220M2-XXXSP, M37220M3-XXXSP/FP, M37224M3-XXXSP.