# [Notes]

R20TS0249EJ0100 Rev.1.00 Jan. 16, 2018

EEPROM Emulation Library Pack03 for 78K Family 78K0R, EEPROM Emulation Library T03 for 78K Family 78K0R

## Outline

When using the EEPROM Emulation Library Pack03 for 78K Family 78K0R, EEPROM Emulation Library T03 for 78K Family 78K0R, note the following point.

1. When a reset or power outage occurred during data writing

## 1. When a Reset or Power Outage Occurred During Data Writing

#### 1.1 Applicable Products

- EEPROM Emulation Library Pack03 for 78K Family 78K0R (78K0R EEL Pack03) Package, Japan Release all versions earlier than V2.00
- EEPROM Emulation Library T03 for 78K Family 78K0R (78K0R EEL T03) Package, European Release all versions earlier than V2.00 (Note)

Note: For the installer that contains only EEL without FDL, all versions earlier than V1.10 are applicable.

## 1.2 Applicable MCUs

78K family: 78K0R/Fx3 and 78K0R/Hx3

### 1.3 Details

The following phenomena may occur:

- (a) When existing data is 0xFF, user data or the reference table (DRP) managed by EEL is destroyed.
- (b) When the last valid block does not have enough write area, write processing does not end.
- (c) The management table of the EEL data is destroyed.

### 1.4 Conditions

This problem may arise if all of the following specific conditions are met.

- (1) A reset or power outage occurs while 78K0R EEL Pack03 or 78K0R EEL T03 is writing the DRP in the processing of data writing.
- (2) Although the DRP is incompletely written, the checksum (RCS) happens to match.
- (3) After the STARTUP processing is executed, the write processing (EEL\_WRITE command or maintenance processing) is executed.

## 1.5 Rate of Occurrence (Reference)

The probability of occurrence under the following conditions of use is about 0.903ppm. (An error may occur in 0.903 of 1 million units.)

- Example of use conditions
- Data writing is performed 100 times a day
- A total of 400 reset and power outage events occur in a year.
- The device has been in operation for 20 years.

## 1.6 Workaround

There is no workaround for this problem.

## 1.7 Solution

This problem will be fixed in the next version. The next version will be available from January 22, 2018.



## **Revision History**

			Description	
	Rev.	Date	Page	Summary
ſ	1.00	Jan. 16, 2018	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

Inquiry https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2018 Renesas Electronics Corporation. All rights reserved. TS Colophon 2.1

