

[Notes]

R20TS0431EJ0100

Rev.1.00

Jun. 01, 2019

Smart Configurator for RH850

Outline

When using Smart Configurator for RH850, note the following point.

1. When using PLL0 Clock

1. When Using PLL0 Clock

1.1 Applicable Products


Smart Configurator for RH850 V1.0.0 or later

1.2 Applicable Devices

RH850 family: RH850/F1KM group

1.3 Details

When using the PLL0 clock of the applicable devices in section 1.2 (when CPLL0OUT is enabled as shown in the image below), incorrect code is generated.



➤ Location where incorrect code is generated

1. An incorrect macro value (red) is generated in the `_CGC_PLL0C_DEFAULT_VALUE` variable in the `r_cg_cg.c` header file.

Source example

```
r_cg_cg.h
#define _CGC_PLL0C_DEFAULT_VALUE      (0x6000503BUL)
```

2. The following code is generated in the `R_CGC_Create` function in the `r_cg_cg.c` file, setting an incorrect value (red) in the `CLKCTL.PLL0C` register.

Source example

```
void R_CGC_Create(void)
{
    ...
    CLKCTL.PLL0C = _CGC_PLL0C_DEFAULT_VALUE | _CGC_PLL0_xxx;
    ...
}
```

1.4 Workaround

Add the code (red) in the user code editing area defined in the `r_cg_cg.h` file to undefine and redefine the macro in `_CGC_PLL0C_DEFAULT_VALUE`.

➤ Process to redefine a macro

1. Display the user code editing area located under Global functions in the `r_cg_cg.h` file. The user code editing area is between the following comments.
 - `/* Start user code for user init. Do not edit comment generated here */`
 - `/* End user code. Do not edit comment generated here */`
2. Add code `#undef` to undefine the macro in `_CGC_PLL0C_DEFAULT_VALUE`.
 - `#undef _CGC_PLL0C_DEFAULT_VALUE`
3. Add code `#define` to redefine the macro in `_CGC_PLL0C_DEFAULT_VALUE`.
 - `#define _CGC_PLL0C_DEFAULT_VALUE (0x60004000UL)`

Modification example:

```
r_cg_cgc.h
/*****
Global functions
*****/
void R_CGC_Create(void);
void R_CGC_Create_UserInit(void);
/* Start user code for function. Do not edit comment generated here */
#undef _CGC_PLL0C_DEFAULT_VALUE
#define _CGC_PLL0C_DEFAULT_VALUE (0x60004000UL)
/* End user code. Do not edit comment generated here */
```

1.5 Schedule for Fixing the Problem

This problem will be fixed in the next version. (Scheduled to be released in January 2020.)

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jun.01.19	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

URLs in Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan
www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.