[Notes]

RX Family

R20TS0854ES0100 Rev.1.00 Jul. 01, 2022

SCI Module Firmware Integration Technology

RX Driver Package

Outline

When using the products in the title, note the following point.

- 1. More than 1 SCI channel uses DTC, abnormality in data transfer might happen.
- More than 1 SCI channel uses DTC, abnormality in data transfer might happen.

1.1 Applicable Products

1) SCI module Firmware Integration Technology (SCI FIT module)

The applicable revision numbers and document numbers are as follows:

Table 1.1 SCI FIT module applicable products

Revision number of the SCI FIT module	Document number
Rev.4.30	R01AN1815EJ0430
Rev.4.20	R01AN1815EJ0420
Rev.4.10	R01AN1815EJ0410
Rev.4.00	R01AN1815EJ0400
Rev.3.91	R01AN1815EJ0391
Rev.3.90	R01AN1815EJ0390
Rev.3.80	R01AN1815EJ0380
Rev.3.70	R01AN1815EJ0370
Rev.3.60	R01AN1815EJ0360

2) RX Driver Package

The SCI FIT module in 1) is also included in the RX Driver Package

The product names and revision numbers of the applicable RX Driver Package and the revision numbers of the SCI FIT module are as follows:

Table 1.2 SCI FIT module applicable products

	RX Driver Package		Revision number of
RX Driver Package product	revision number	Document number	the included SCI FIT
name			module
RX Family	Rev.1.34	R01AN6323xx0134	Rev.4.30
RX Driver Package Ver.1.34			
RX Family	Rev.1.33	R01AN6073xx0133	Rev.4.10
RX Driver Package Ver.1.33			
RX Family	Rev.1.32	R01AN6013xx0132	Rev.3.90
RX Driver Package Ver.1.32			
RX Family	Rev.1.31	R01AN5975xx0131	Rev.3.80
RX Driver Package Ver.1.31			
RX Family	Rev.1.30	R01AN5882xx0130	Rev.3.70
RX Driver Package Ver.1.30			
RX Family	Rev.1.29	R01AN5826xx0129	Rev.3.70
RX Driver Package Ver.1.29			

RX Family	Rev.1.27	R01AN5600xx0127	Rev.3.70
RX Driver Package Ver.1.27			

1.2 Applicable Devices

RX110, RX111, RX113, RX130, RX140, and RX13T groups
RX230, RX231, RX23E-A, RX23W, RX23T, RX24T, and RX24U groups
RX64M, RX65N, RX66N, and RX66T, RX671 groups
RX71M, RX72T, RX72M, and RX72N groups

1.3 Details

Data transfer would fail when more than 1 SCI channels uses DTC FIT module.

In SCI code, DTC transfer information structures tx_info_dtc and rx_info_dtc are shared among SCI channels. Under this condition, if the data transfer of one SCI channel (using DTC) is initiated before the data transfer of the other SCI channel (using DTC) is completed, transfer may be erroneous because the DTC transfer information structure is corrupted.

1.4 Conditions

> When more than one SCI channels use DTC, transfer may be erroneous.

Below are sample codes which illustrate the conditions under which the error would happen:

```
//main.c
...
R_SCI_SendReceive(g_my_sci_handle12, ..., ...);
R_SCI_Send(g_my_sci_handle0, ..., ...);
//CH12 transfer may be erroneous.
...
```

In the above code, R_SCI_Send(g_my_sci_handle0, ..., ...) is called immediately after R_SCI_SendReceive(g_my_sci_handle12, ..., ...), without checking if CH12 data transfer is completed. tx_info_dtc is used by both CH0 and CH12, DTC transfer information for CH12 is corrupted, and thus transfer may be erroneous.

Similarly, the code below would also yield transfer to be erroneous:

```
//main.c
...
R_SCI_Send(g_my_sci_handle12, ..., ...);
R_SCI_Send(g_my_sci_handle0, ..., ...);
//CH12 transfer will be corrupted. Error would happen
...
```

1.5 Workaround

Temporary workaround: Do not use two or more SCI channels with DTC User should upgrade to SCI FIT Rev.4.40 once it is available

1.6 Schedule for Fixing the Problem

This problem will be fixed in SCI FIT Rev.4.40

Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Jul. 01.22	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061, Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

 $\hbox{@\,}2022$ Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.3