[Upgrade to revision]

RX family

R20TS0096EJ0100 Rev.1.00 Dec. 01, 2016

PTP Get Synchronous Time Using Firmware Integration Technology Modules,
PTP Timer Synchronous Start Using Firmware Integration Technology Modules,
PTP Synchronous Pulse Output Using Firmware Integration Technology Modules,
Ethernet Simple Switch Function Using Firmware Integration Technology Modules,
Ethernet Multicast Frame Filter Function Using Firmware Integration Technology Modules

Outline

We are revising the products in the title from Rev1.10 to Rev1.11.

1. Products and Versions to Be Revised

RX family PTP Get Synchronous Time Using Firmware Integration Technology Modules

Revision: Rev1.10

The following document is relevant.

 Application note for the RX Family PTP Get Synchronous Time Using Firmware Integration Technology Modules

Document number: R01AN1983EJ0110

RX family PTP Timer Synchronous Start Using Firmware Integration Technology Modules

Revision: Rev1.10

The following document is relevant.

 Application note for the RX Family PTP Timer Synchronous Start Using Firmware Integration Technology Modules

Document number: R01AN1984EJ0110

RX family PTP Synchronous Pulse Output Using Firmware Integration Technology Modules

Revision: Rev1.10

The following document is relevant.

 Application note for the RX Family PTP Synchronous Pulse Output Using Firmware Integration Technology Modules

Document number: R01AN2846EJ0110

RX family Ethernet Simple Switch Function Using Firmware Integration Technology Modules

Revision: Rev1.10

The following document is relevant.

 Application note for the RX Family Ethernet Simple Switch Function Using Firmware Integration Technology Modules

Document number: R01AN3036EJ0110

> RX family Ethernet Multicast Frame Filter Function Using Firmware Integration Technology Modules

Revision: Rev1.10

The following document is relevant.

 Application note for the RX Family Ethernet Multicast Frame Filter Function Using Firmware Integration Technology Modules

Document number: R01AN3037EJ0110

2. Description of Revisions

The following points are to be upgraded.

2.1 Description of Modification

The problem regarding the following point, of which we informed you in RENESAS TOOL NEWS Document No. R20TS0089EJ0100, has been fixed.

1. Detection of changes in the link state by the "R_ETHER_LinkProcess" function

For details of the problem, refer to the URL below.

https://www.renesas.com/search/keyword-search.html#genre=document&documenttype=531&g=r20ts0089

3. Updating Your Product

3.1 Downloading the Package

Download the package from the following Web page.

- RX Family PTP Get Synchronous Time Using Firmware Integration Technology Modules https://www.renesas.com/search/keyword-search.html#genre=sampleprogram&q=r01an1983
- RX Family PTP Timer Synchronous Start Using Firmware Integration Technology Modules https://www.renesas.com/search/keyword-search.html#genre=sampleprogram&q=r01an1984
- RX Family PTP Synchronous Pulse Output Using Firmware Integration Technology Modules https://www.renesas.com/search/keyword-search.html#genre=sampleprogram&q=r01an2846
- RX Family Ethernet Simple Switch Function Using Firmware Integration Technology Modules https://www.renesas.com/search/keyword-search.html#genre=sampleprogram&q=r01an3036
- RX Family Ethernet Multicast Frame Filter Function Using Firmware Integration Technology Modules https://www.renesas.com/search/keyword-search.html#genre=sampleprogram&q=r01an3037

Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Dec. 01, 2016	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

■Inquiry

http://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2016. Renesas Electronics Corporation. All rights reserved.